17. SUGGESTED REPLACEMENT TRANSISTORS

LINE No.	TYPE NO. TO BE REPLACED	The Following Type Numbers Are Suggested By The Manufacturer As Their Nearest Replacement To The Type In The Left Column											
		TYPE NO.	MFR.	TYPE NO.	MFR.	TYPE NO.	MFR.	TYPE NO.	MFR.	TYPE NO.	MFR.	TYPE NO.	MFR.
1▼	2N6053	BDX62	PHIN										
2▼	2N6054	BDX62A	PHIN										
3▼	2N6055	BDX63	PHIN										
4▼	2N6056	BDX63A	PHIN										
5▼	2N6057	BDX65	PHIN										
6▼	2N6058	BDX65A	PHIN										
7▼	2N6059	BDX65B	PHIN										
8▼	2N6080	BLX67	PHIN										
9▼	2N6081	BLX88A	PHIN										
10▼	2N6082	BLX89A	PHIN										
11▼	2N6083	BLX89A	PHIN										
12▼	2N6084	BLW60	PHIN										
13▼	2N6098	BDT93	PHIN	2N6098	SODI								
14▼	2N6099	BDT93	PHIN	2N6099	SODI								
15▼	2N6100	BDT93	PHIN	TIP73B	TII	2N6100	SODI						
16▼	2N6101	BDT93	PHIN	TIP73B	TII	2N6101	SODI						
17▼	2N6104	MRF5177	MOTA										
18▼	2N6105	MRF5177A	MOTA										
19▼	2N6106	BDX78	PHIN	TIP42B	TII								
20▼	2N6107	BDX78	PHIN	TIP42B	TII								
21▼	2N6108	BD204	PHIN	TIP42B	TII								
22▼	2N6109	BD204	PHIN	TIP42B	TII								
23▼	2N6110	BD202	PHIN	TIP42B	TII								
24▼	2N6111	BD202	PHIN	TIP42B	TII								
25▼	2N6136	BLW31	PHIN										
26▼	2N6197	BLY91A	PHIN										
27▼	2N6198	BLY92A	PHIN										
28▼	2N6199	BLY93A	PHIN										
29▼	2N6200	BLY94	PHIN										
30▼	2N6201	BLY94	PHIN										
31▼	2N6202	BLX92A	PHIN										
32▼	2N6203	BLX93A	PHIN										
33▼	2N6205	BLX95	PHIN										
34▼	2N6206	BLX92A	PHIN										
35▼	2N6207	BLX93A	PHIN										
36▼	2N6226	BLX96	PHIN	TIP544	TII								
37▼	2N6282	BLX67	PHIN										
38▼	2N6284	BLX67B	PHIN										
39▼	2N6285	BLX66	PHIN										
40▼	2N6286	BLX66A	PHIN										
41▼	2N6287	BLX66B	PHIN										
42▼	2N6288	BD201	PHIN	TIP41	TII	2N6111	MEHK						
43▼	2N6289	BD201	PHIN	TIP41	TII	2N6106	MEHK						
44▼	2N6290	BD203	PHIN	TIP41A	TII	2N6109	MEHK						
45▼	2N6293	BDX77	PHIN	TIP41B	TII	2N6110	MEHK						
46▼	2N6296	RCA8350A	RCA	2N6296	MOTA								
47▼	2N6297	RCA8350B	RCA	TIP126	TII								
48▼	2N6298	RCA8350A	RCA	TIP105	TII								
49▼	2N6299	RCA8350B	RCA	TIP106	TII								
50▼	2N6307	BUX80	PHIN	SVT7530	TRWS	2N6307	TII	SVT7530	TRWS	2N6307	SODI		
51▼	2N6308	BUX80	PHIN	SVT7531	TRWS	TIP563	TII	SVT7531	TRWS	2N63085	SODI		
52▼	2N6366	MRF475	MOTA	MR231	MOTA								
53▼	2N6383	BDX65	PHIN	TIP640	TII								
54▼	2N6384	BDX65	PHIN	TIP640	TII								
55▼	2N6385	BDX65A	PHIN	TIP641	TII								
56▼	2N6406	RCP700B	RCA	TIP32B	TII	MJE171	MOTA						
57▼	2N6407	RCP700C	RCA	TIP32C	TII	MJE172	MOTA						
58▼	2N6408	RCP701B	RCA	TIP31B	TII	MJE181	MOTA	2N6408	MOTA				
59▼	2N6409	RCP701C	RCA	TIP31C	TII	MJE182	MOTA	2N6409	MOTA				
60▼	2N6412	RCP701A	RCA	TIP41A	TII	MJE180	MOTA						
61▼	2N6413	RCP701B	RCA	TIP41B	TII	MJE181	MOTA						
62▼	2N6414	RCP700A	RCA	TIP42A	TII	MJE170	MOTA						
63▼	2N6415	RCP700B	RCA	TIP42B	TII	MJE171	MOTA	RCP701C	RCA				
64▼	2N6417	RCP701D	RCA	TIP31C	TII	MJE243	MOTA						
65▼	2N6418	RCP700C	RCA	TIP32B	TII	MJE251	MOTA						
66▼	2N6419	RCP700D	RCA	TIP32C	TII	MJE253	MOTA						
67▼	2N6469	BDX92	PHIN	2N6469	TII								
68▼	2N6470	BDX91	PHIN	2N6470	TII								
69▼	2N6471	BDX93	PHIN	2N6471	TII								
70▼	2N6472	BDX95	PHIN	2N6472	TII								
71▼	2N6510	BUX80	PHIN	SVT7523	TRWS	TIP558	TII	SVT7523	TRWS				
72▼	2N6511	BUX80	PHIN	SVT7573	TRWS	TIP558	TII						
73▼	2N6512	BUX80	PHIN	SVT7573	TRWS	TIP559	TII	SVT7573	TRWS				
74▼	2N6513	BUX80	PHIN	SVT7573	TRWS	TIP560	TII	SVT7573	TRWS				
75▼	2N6514	BUX80	PHIN	SVT7533	TRWS	TIP559	TII	SVT7533	TRWS				
76▼	2N6576	BDX65	PHIN	TIP40	TII								
77▼	2N6577	BDX65B	PHIN	TIP42	TII								
78▼	2N6578	BDX65C	PHIN	TIP42	TII								
79▼	2N6581	MJ13334	MOTA	BUX81	PHIN	2N6581	TRWS						
80▼	2N6582	BUX80	PHIN	2N6582	TRWS	TIP564	TII	2N6582	TRWS				
81▼	2N6583	BUX80	PHIN	2N6583	TRWS	TIP565	TII	2N6583	TRWS				
82▼	2N6584	MJ13334	MOTA	BUX81	PHIN	2N6584	TRWS						
83▼	2N6585	BUX80	PHIN	2N6585	TRWS	2N6585	TRWS						
84▼	2N6586	BUX80	PHIN	2N6586	TRWS	2N6586	TRWS						
85▼	2N6587	BUX81	PHIN	2N6587	TRWS	2N6587	TRWS						
86▼	2N6588	BUX80	PHIN	2N6588	TRWS	2N6588	TRWS						
87▼	2N6589	BUX80	PHIN	2N6589	TRWS	2N6589	TRWS						
88▼	2N6590	BUX81	PHIN	2N6590	TRWS	2N6590	TRWS						
89▼	2N6653	MJ13332	MOTA	SVT7573	TRWS								
90▼	2N6654	MJ13332	MOTA	SVT7574	TRWS								
91▼	2N6655	MJ13333	MOTA	SVT7575	TRWS								
92▼	2N6671	2N6544	MOTA	2N6671	TRWS	IR6542	INR	2N6671	SODI				
93▼	2N6672	2N6545	MOTA	2N6672	TRWS	IR6542	INR	2N6672	SODI				
94▼	2N6673	2N6545	MOTA	2N6673	TRWS	TR6543	INR	2N6673	SODI				
95▼	2N6674	MJ13014	MOTA	IR6544	INR	2N6674	SODI						
96▼	2N6675	MJ13015	MOTA	IR6545	INR	2N6675	SODI						
97▼	2N6676	MJ13332	MOTA	IR6546	INR	2N6676	SODI						
98▼	2N6677	MJ13332	MOTA	IR6546	INR	2N6677	SODI						
99▼	2N6678	MJ13333	MOTA	IR6547	INR	2N6678	SODI						
100▼	2SA480	BC558	PHIN										
101▼	2SA493	BC560	PHIN										
102▼	2SA495	BC557	PHIN										
103▼	2SA509	BC557	PHIN										
104▼	2SA527	BC234	PHIN										
105▼	2SA530H	BC557	PHIN										
106▼	2SA539	BC327	PHIN	2SC815	MEHK								
107▼	2SA547	BC236	PHIN										
108▼	2SA550	BC159	PHIN	BC559	PHIN								
109▼	2SA561	BC327	PHIN										
110▼	2SA564	BC558B	PHIN										

Datasheet Directory