10. SUGGESTED REPLACEMENT THRISTORS

LINE No.	1 TYPE NO. TO BE REPLACED	The Following Type Numbers Are Suggested By The Manufacturer As Their Nearest Replacement To The Type In The Left Column											
		TYPE NO.	MFR.	TYPE NO.	MFR.	TYPE NO.	MFR.	TYPE NO.	MFR.	TYPE NO.	MFR.	TYPE NO.	MFR.
1	1N3301	SK3523-6407	RCA										
2	1N3301A	SK3523-6407	RCA										
3	1N5411	SK3523-6407	RCA										
4	1N5758	SK9082A-6406	RCA										
5	1N5758A	SK9082A-6406	RCA										
6	1N5761	GT32	TCE										
7	1N5761A	GT32	TCE										
8	1N5762	GT35	TCE										
9	1N5762A	GT32	TCE										
10	2N602	2N4170	MOTA	BTY79-400R	PHIN	SK3577	RCA						
11	2N603	2N4171	MOTA	BTY79-400R	PHIN	SK3578	RCA						
12	2N604	2N4172	MOTA	BTY79-400R	PHIN	SK3578	RCA						
13	2N681	SK6621-5521	RCA										
14	2N682	SK6621-5521	RCA										
15	2N682A	SK6621-5521	RCA										
16	2N683	SK6622-5522	RCA										
17	2N683A	SK6622-5522	RCA										
18	2N684	SK6624-5524	RCA										
19	2N684A	SK6624-5524	RCA										
20	2N685	SK6624-5524	RCA										
21	2N686	SK6627-5527	RCA										
22	2N686A	SK6627-5527	RCA										
23	2N687	SK6627-5527	RCA										
24	2N688	SK6627-5527	RCA										
25	2N688A	SK6627-5527	RCA										
26	2N689	SL6629-5529	RCA										
27	2N689A	SK6629-5529	RCA										
28	2N690	SK6629-5529	RCA										
29	2N692	SK6631-5531	RCA										
30	2N876	MCR202	MOTA	SK3950/5400	RCA	EC103Y	TCE						
31	2N877	MCR202	MOTA	SK3950/5400	RCA	EC103Y	TCE						
32	2N878	MCR203	MOTA	SK3638/5402	RCA	EC103A	TCE						
33	2N879	MCR204	MOTA	SK3638/5402	RCA	EC103A	TCE						
34	2N880	MCR205	MOTA	SK3627/5404	RCA	EC103B	TCE						
35	2N881	MCR206	MOTA	SK3627/5404	RCA	EC103B	TCE						
36	2N882	EC103D	TCE										
37	2N883	EC103D	TCE										
38	2N884	MCR202	MOTA	EC103Y	TCE								
39	2N885	MCR202	MOTA	EC103Y	TCE								
40	2N886	MCR203	MOTA	EC103A	TCE								
41	2N887	MCR204	MOTA	EC103A	TCE								
42	2N888	MCR205	MOTA	EC103B	TCE								
43	2N889	MCR206	MOTA	EC103B	TCE								
44	2N890	EC103D	TCE										
45	2N948	MCR202	MOTA	2N877	TAGS	EC103Y	TCE						
46	2N949	MCR203	MOTA	2N878	TAGS	EC103A	TCE						
47	2N950	MCR204	MOTA	2N879	TAGS	EC103A	TCE						
48	2N951	MCR206	MOTA	2N881	TAGS	EC103B	TCE						
49	2N1595	SK3577	RCA	BTX18	PHIN								
50	2N1595A	SK3577	RCA										
51	2N1596	SK3577	RCA	BTX18	PHIN								
52	2N1596A	SK3577	RCA										
53	2N1597	SK3577	RCA	BTX18	PHIN								
54	2N1597A	SK3577	RCA										
55	2N1598	SK3577	RCA	BTX18	PHIN								
56	2N1598A	SK3577	RCA										
57	2N1599	SK3577	RCA	BTX18	PHIN								
58	2N1599A	SK3577	RCA	BTX18	PHIN								
59	2N1600	2N4168	MOTA	SK3577	RCA								
60	2N1601	2N4169	MOTA	BTY79-400R	PHIN	SK3577	RCA						
61	2N1602	2N4170	MOTA	BTY79-400R	PHIN	SK3577	RCA						
62	2N1603	2N4171	MOTA	BTY79-400R	PHIN	SK3578	RCA						
63	2N1604	2N4172	MOTA	BTY79-400R	PHIN	SK3578	RCA						
64	2N1671	2N4851	MOTA										
65	2N1671A	2N4851	MOTA										
66	2N1671B	2N4851	MOTA										
67	2N1671C	2N4851	MOTA										
68	2N1770	2N4167	MOTA	BTY79	PHIN	S0315B	TCE						
69	2N1770A	S0315B	TCE	BTY79-400R	PHIN								
70	2N1771	2N4168	MOTA	BTY79	PHIN	S0515B	TCE						
71	2N1771A	S0515B	TCE	BTY79-400R	PHIN								
72	2N1772	2N4169	MOTA	BTY79	PHIN	SK3942/5483	RCA	S1015B	TCE				
73	2N1772A	S1015B	TCE	BTY79-400R	PHIN	SK3942/5483	RCA						
74	2N1773	2N4170	MOTA	BTY79	PHIN	SK3942/5483	RCA	S2015B	TCE				
75	2N1773A	S2015B	TCE	BTY79-400R	PHIN	SK3942/5483	RCA						
76	2N1774	2N4170	MOTA	BTY79	PHIN	SK3942/5483	RCA	S2015B	TCE				
77	2N1774A	S7015B	TCE	BTY79-400R	PHIN	SK3942/5483	RCA						
78	2N1775	2N4171	MOTA	BTY79	PHIN	SK3943/5485	RCA	S4015B	TCE				
79	2N1775A	S4015B	TCE	BTY79-400R	PHIN	SK3943/5485	RCA						
80	2N1776	2N4171	MOTA	BTY79	PHIN	SK3943/5485	RCA						
81	2N1776A	S4015B	TCE	BTY79-400R	PHIN	SK3943/5485	RCA						
82	2N1776B	2N4171	MOTA	BTY79	PHIN								
83	2N1777	2N4172	MOTA	BTY79	PHIN	SK3943/5485	RCA	S4015B	TCE				
84	2N1777A	S4015B	TCE	BTY79-400R	PHIN	SK3943/5485	RCA						
85	2N1778	2N4173	MOTA	BTY79	PHIN	S5015B	TCE						
86	2N1778A	S5015B	TCE	SK3944/5487	RCA								
87	2N1792	BTW23-600	PHIN										
88	2N1793	BTW23-600	PHIN										
89	2N1794	BTW23-600	PHIN										
90	2N1795	BTW23-600	PHIN										
91	2N1796	BTW23-600	PHIN										
92	2N1797	BTW23-600	PHIN										
93	2N1798	BTW23-600	PHIN										
94	2N1799	BTW23-600	PHIN										
95	2N1800	BTW23-600	PHIN										
96	2N1842	S0315L	TCEA	BTY79	PHIN	SK3579/5504	RCA						
97	2N1842A	S0320L	TCEA	BTW45	PHIN	SK3579/5504	RCA						
98	2N1842B	SK3579-5504	RCA										
99	2N1843	S0520L	TCEA	BTY79	PHIN	SK3579/5504	RCA						
100	2N1843A	S0520L	TCEA	BTW45	PHIN	SK3579/5504	RCA						
101	2N1843B	SK3579-5504	RCA										
102	2N1844	S1020L	TCE	BTY79	PHIN	SK3579/5504	RCAQ						
103	2N1844A	S1020L	TCE	BTW45	PHIN	SK3579/5504	RCA						
104	2N1844B	SK3579-5504	RCA										
105	2N1845	S2010L	TCE	BTY79	PHIN	SK3579/5504	RCA						
106	2N1845A	S2010L	TCE	BTW45	PHIN	SK3579/5504	RCA						
107	2N1845B	SK3579-5504	RCA										
108	2N1846	S2010L	TCE	BTY79	PHIN	SK3579/5504	RCA						
109	2N1846A	S2010L	TCE	BTW45	PHIN	SK3579/5504	RCA						
110	2N1846B	SK3579-5504	RCA										

Datasheet.Directory