

ALPHANUMERIC INDEX — CROSS-REFERENCE (Continued)

Industry Part Number	Motorola Direct Replacement	Motorola Similar Replacement	Page Number	Industry Part Number	Motorola Direct Replacement	Motorola Similar Replacement	Page Number
TIP107	TIP107		3-1091	TIP32F		MJE15031	3-972
TIP110	TIP110		3-1095	TIP33	TIP33		3-1077
TIP111	TIP111		3-1095	TIP33A	TIP33A		3-1077
TIP112	TIP112		3-1095	TIP33B	TIP33B		3-1077
TIP115	TIP115		3-1095	TIP33C	TIP33C		3-1077
TIP116	TIP116		3-1095	TIP34	TIP34		3-1077
TIP117	TIP117		3-1095	TIP34A	TIP34A		3-1077
TIP120	TIP120		3-1098	TIP34B	TIP34B		3-1077
TIP121	TIP121		3-1098	TIP34C	TIP34C		3-1077
TIP122	TIP122		3-1098	TIP35	TIP35		3-1079
TIP125	TIP125		3-1098	TIP35A	TIP35A		3-1079
TIP126	TIP126		3-1098	TIP35B	TIP35B		3-1079
TIP127	TIP127		3-1098	TIP35C	TIP35C		3-1079
TIP140	TIP140		3-1104	TIP36	TIP36		3-1079
TIP140T		TIP100	3-1091	TIP36A	TIP36A		3-1079
TIP141	TIP141		3-1104	TIP36B	TIP36B		3-1079
TIP141T		TIP101	3-1091	TIP36C	TIP36C		3-1079
TIP142	TIP142		3-1104	TIP41	TIP41		3-1083
TIP142T		TIP102	3-1091	TIP41A	TIP41A		3-1083
TIP145	TIP145		3-1104	TIP41B	TIP41B		3-1083
TIP145T		TIP105	3-1091	TIP41C	TIP41C		3-1083
TIP146	TIP146		3-1104	TIP41D		MJE15030	3-972
TIP146T		TIP106	3-1091	TIP41E		MJE15030	3-972
TIP147	TIP147		3-1104	TIP41F		MJE15030	3-972
TIP147T		TIP107	3-1091	TIP42	TIP42		3-1083
TIP150		MJE13006	3-950	TIP42A	TIP42A		3-1083
TIP151		MJE13007	3-950	TIP42B	TIP42B		3-1083
TIP152		MJE13007	3-950	TIP42C	TIP42C		3-1083
TIP160		MJE5740	3-914	TIP42D		MJE15031	3-972
TIP161		MJE5741	3-914	TIP42E		MJE15031	3-972
TIP162		MJE5742	3-914	TIP42F		MJE15031	3-972
TIP29	TIP29		3-1071	TIP47	TIP47		3-1087
TIP2955	TIP2955		3-1108	TIP48	TIP48		3-1087
TIP29A	TIP29A		3-1071	TIP49	TIP49		3-1087
TIP29B	TIP29B		3-1071	TIP50	TIP50		3-1087
TIP29C	TIP29C		3-1071	TIP510		MJ15011	3-716
TIP29D		MJE15030	3-972	TIP511		MJ15011	3-716
TIP29E		MJE15030	3-972	TIP512		MJ15011	3-716
TIP29F		MJE15030	3-972	TIP513		MJ15012	3-716
TIP30	TIP30		3-1071	TIP514		MJE15030	3-972
TIP3055	TIP3055		3-1108	TIP517		2N6339	3-188
TIP30A	TIP30A		3-1071	TIP518		2N6341	3-188
TIP30B	TIP30B		3-1071	TIP519		MJ15012	3-716
TIP30C	TIP30C		3-1071	TIP520		MJ15012	3-716
TIP30D		MJE15031	3-972	TIP521		2N6211	3-161
TIP30E		MJE15031	3-972	TIP522		2N6211	3-161
TIP30F		MJE15031	3-972	TIP523		MJ15012	3-716
TIP31	TIP31		3-1073	TIP524		2N6497	3-211
TIP31A	TIP31A		3-1073	TIP525		MJ15011	3-716
TIP31B	TIP31B		3-1073	TIP526		MJ15011	3-716
TIP31C	TIP31C		3-1073	TIP527		MJ15012	3-716
TIP31D		MJE15030	3-972	TIP528		MJ15012	3-716
TIP31E		MJE15030	3-972	TIP536		MJ16006	3-742
TIP31F		MJE15030	3-972	TIP545		MJ15016	3-9
TIP32	TIP32		3-1073	TIP546		MJ15016	3-9
TIP32A	TIP32A		3-1073	TIP550		MJ12002	3-637
TIP32B	TIP32B		3-1073	TIP551		MJ12003	3-642
TIP32C	TIP32C		3-1073	TIP552		MJ12004	3-644
TIP32D		MJE15031	3-972	TIP553		MJ12004	3-644
TIP32E		MJE15031	3-972	TIP554		MJ13080	3-682

*Consult Motorola if a direct replacement is necessary.