

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
<b>BF25-35</b> MRF137 1 MOTA MRF171 1 MOTA	<b>BF164</b> (Cont'd) BF198 1 PHIN	<b>BF198</b> 2N5201 3 MOTA BC107 3 SGSI	<b>BF245A</b> (Cont'd) 2N5458 3 INL 2N5484 3 INL	<b>BF247</b> (Cont'd) TMPF4091 3 SPR TP4091 3 SPR	<b>BF257</b> (Cont'd) 40408 3 RCA BD115 3 PHIN	
<b>BF50-35</b> MRF172 1 MOTA	<b>BF165</b> BF185 1 PHIN BF495 1 PHIN	BC547A 3 PHIN BC548A 3 PHIN BF196 3 PHIN	2N5951 3 IFC 2N5953 3 IFC DE451 3 DGE	<b>BF247A</b> 2N4091 1 INL DE466 3 DGE	BSW66 3 PHIN BSW67 3 PHIN BSW68 3 PHIN	
<b>BF100-35</b> MRF174 1 MOTA	<b>BF166</b> BF200 1 PHIN	THC4286 3 SPR THC4287 3 SPR	DE452 3 DGE DE457 3 DGE PN4304-18 3 NSC	THJ4091 3 SPR TMPF4091 3 SPR TP4091 3 SPR	D44T1 3 GESY D44T2 3 GESY DE154 3 DGE	
<b>BF108</b> D44T1 1 GESY	<b>BF169</b> BF115 1 PHIN BF494 1 PHIN	<b>BF199</b> MPSH24 1 MOTA SF245 1 MIKG	THJ4304 3 SPR THJ4416 3 SPR THJ5457 3 SPR	<b>BF247B</b> 2N4091 1 INL DE466 3 DGE	MPSA43 3 MOTA	
<b>BF109</b> D40V1 1 GESY	<b>BF174</b> 2N3440 1 RCA	BF197 3 PHIN	THJ5668 3 SPR TMPF4304 3 SPR TMPF4416 3 SPR	THJ4091 3 SPR TMPF4091 3 SPR TP4091 3 SPR	<b>BF258</b> BF337 1 PHIN D40V1 1 GESY	
<b>BF111</b> 2N3440 1 RCA	BF258 1 GESY	<b>BF206</b> 2N918 1 PHIN	THJ5668 3 SPR TMPF4416 3 SPR TMPF5457 3 SPR	2N4091 1 INL DE466 3 DGE	2N3440 3 RCA 2N6515 3 MOTA	
BD115 3 PHIN	D40V1 1 GESY	DE161 3 DGE	TPMPF5668 3 SPR TP4304 3 SPR TP4416 3 SPR	BF247C 2N4091 1 INL DE466 3 DGE	40412 3 RCA BC639 3 PHIN	
BFN18 3 SIEG	BD115 3 PHIN	PN918 3 NSC	TP5668 3 SPR	THJ4091 3 SPR TMPF4091 3 SPR TP4091 3 SPR	D44T1 3 GESY DE154 3 DGE GES4927 3 GESY	
BFN26 3 SIEG	BF337 3 PHIN	THC918 3 SPR	<b>BF245B</b> 2N4416 1 INL 2N5338 3 MOTA	2N2221 1 PHIN 2N2222 1 PHIN	THC4927 3 SPR TP4927 3 SPR	
D44T2 3 GESY	BFN18 3 SIEG	TMP1918 3 SPR	2N5459 3 INL 2N5485 3 INL 2N5952 3 IFC	2N2906A 1 PHIN 2N2907 1 SGSI	<b>BF259</b> BF338 1 PHIN D40V3 1 GESY	
DE396 3 DGE	BFN26 3 SIEG	<b>BF214</b> BF115 1 PHIN BF494 1 PHIN	2N5952 3 IFC DE451 3 DGE DE452 3 DGE	BSS81B 3 SIEG BSS81C 3 SIEG DE123A 3 DGE	2N3440 3 RCA BD115 3 PHIN MPSA42 3 MOTA	
TN3440 3 NSC	D44T2 3 GESY	BF494 1 PHIN	DE457 3 DGE PN4303-18 3 NSC	GES222A 3 GESY GES2222 3 GESY PN2221 3 NSC	BF260 BF200 1 PHIN	
<b>BF115</b> 2N2218 3 MOTA	DE396 3 DGE	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	THJ4303 3 SPR THJ4416 3 SPR THJ5458 3 SPR	PN2222 3 NSC THC2221 3 SPR THC2222 3 SPR	BF261 BF196 1 PHIN BF198 1 PHIN	
BF494 3 PHIN	D40E1 3 GESY	MPSH04 3 MOTA	THJ5669 3 SPR TMPF4303 3 SPR TMPF4416 3 SPR	TMPT2221 3 SPR TMPT2222 3 SPR TP2221 3 SPR	<b>BF268</b> BFY90 1 PHIN SD1300 3 THCS	
D40E5 3 GESY	DE128 3 DGE	<b>BF217</b> BF257 1 SGSI BF336 3 PHIN	TP5668 3 SPR	TP2222 3 SPR	<b>BF272</b> 2N2906 1 PHIN DE159 3 DGE	
DE319 3 DGE	DE319 3 DGE	D40V1 3 GESY	<b>BF218</b> 40412 1 RCA	<b>BF249</b> 2N2906A 1 PHIN 2N2907 1 SGSI	GES2906 3 GESY PN2906 3 NSC THC2906 3 SPR	
<b>BF118</b> BF338 1 PHIN	<b>BF177</b> BF257 1 SGSI	<b>BF178</b> 40412 1 RCA	BF258 1 SGSI	DE159 3 DGE BSS80C 3 SIEG	PN2906 3 NSC TMPT2906 3 SPR TP2906 3 SPR	
D40V1 1 GESY	BF336 3 PHIN	BF258 1 SGSI	BF337 3 PHIN	DE159 3 DGE GES2907 3 GESY	PN2907 3 NSC THC2906A 3 SPR THC2907 3 SPR	
2N3440 3 RCA	D40V1 3 GESY	BF337 3 PHIN	D40V1 3 GESY	PN2906A 3 SPR TMPT2907 3 SPR TP2906A 3 SPR	TMPT2906 3 SPR TP2906 3 SPR	
BF259 3 SGSI	D40V1 3 GESY	MPSH24 3 MOTA	<b>BF119</b> BF337 1 PHIN	TP2907 3 SPR TPQ2906A 3 SPR	<b>BF273</b> BF241 1 PHIN SF225 3 MIKG	
<b>BF120</b> BC394 1 SGSI	D44T2 3 GESY	<b>BF179</b> 2N3440 1 RCA	2N3440 1 RCA	<b>BF250</b> 2N2222 1 SGSI BSS81C 3 SIEG	SF245 3 MIKG	
<b>BF123</b> BF197 1 PHIN	<b>BF179A</b> 2N3440 1 RCA	BF259 1 SGSI	D40V1 1 GESY	DE159 3 DGE GES2907 3 GESY	<b>BF291</b> BC107 1 SGSI	
BF199 1 PHIN	D40V1 1 GESY	BF337 3 PHIN	BD115 3 PHIN	PN2907 3 NSC THC2906A 3 SPR	BCX70G 3 PHIN	
MPSH24 3 MOTA	BF337 3 PHIN	BFN18 3 SIEG	BFN18 3 SIEG	PN2907 3 SPR TP2907 3 SPR TPQ2906A 3 SPR	BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN	
SF245 3 MIKG	D40V1 3 GESY	BFN26 3 SIEG	D40V3 3 GESY	<b>BF251</b> BF199 1 PHIN	THBC107 3 SPR	
<b>BF125</b> BF197 1 PHIN	D44T2 3 GESY	D40V3 3 GESY	DE396 3 DGE	TMPT2907 3 SPR TP2907 3 SPR TPQ2906A 3 SPR	<b>BF292</b> BF258 1 SGSI BF337 3 PHIN	
BF199 1 PHIN	DE396 3 DGE	DE396 3 DGE	MPSH04 3 MOTA	<b>BF252</b> 2N2222 1 SGSI BSS81C 3 SIEG	D40V1 3 GESY	
MPSH24 3 MOTA	TN3440 3 NSC	TN3440 3 NSC	SF245 3 MIKG	GES2222 3 GESY PN2222 3 NSC	<b>BF292A</b> D40V1 1 GESY	
SF245 3 MIKG	<b>BF179B</b> 2N3440 1 RCA	<b>BF233</b> BF495 1 PHIN	<b>BF230</b> BF195 1 PHIN	THC2222 3 SPR TMPT2222 3 SPR TP2222 3 SPR	<b>BF292C</b> D40V1 1 GESY	
<b>BF127</b> BF197 1 PHIN	D40V1 1 GESY	MPSH04 3 MOTA	BF495 1 PHIN	<b>BF253</b> MPSH04 1 MOTA	<b>BF293</b> BC107 1 SGSI	
BF199 1 PHIN	BD115 3 PHIN	<b>BF234</b> BF494 1 PHIN	MPSH04 3 MOTA	MPSH04 1 MOTA	BCX70G 3 PHIN	
MPSH24 3 MOTA	BFN18 3 SIEG	MPSH04 3 MOTA	<b>BF235</b> BF495 1 PHIN	MPSH04 1 MOTA	BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN	
SF245 3 MIKG	D44T2 3 GESY	<b>BF237</b> BF115 1 PHIN	MPSH04 3 MOTA	<b>BF236</b> BF115 1 PHIN	THBC107 3 SPR	
<b>BF131</b> BF182 1 PHIN	TN3440 3 NSC	BF494 1 PHIN	<b>BF240</b> MPSH04 3 MOTA	BF115 1 PHIN	<b>BF294</b> BC257 1 SGSI	
<b>BF133</b> BF183 1 PHIN	<b>BF179C</b> 2N3440 1 RCA	<b>BF237</b> BF115 1 PHIN	<b>BF241</b> SF225 1 MIKG	BF494 1 PHIN	BD115 1 PHIN	
<b>BF134</b> BF200 1 PHIN	D40V1 1 GESY	BF494 1 PHIN	SF245 1 MIKG	MPSH04 3 MOTA	D40V2 1 GESY	
<b>BF137</b> BF200 1 PHIN	BD115 3 PHIN	MPSH04 3 MOTA	MPSH04 3 MOTA	<b>BF242</b> MPSH54 1 MOTA	2N3440 3 RCA	
2N3440 1 RCA	BFN18 3 SIEG	<b>BF243</b> BF115 1 PHIN	<b>BF244</b> 2N5486 1 INL	2N5486 1 INL	BC177 3 SGSI	
BF257 1 SGSI	BFN26 3 SIEG	BF494 1 PHIN	2N5247 3 IFC	2N5247 3 IFC	BC557 3 PHIN	
BD115 3 PHIN	D44T2 3 GESY	THJ5486 3 SPR	THJ5486 3 SPR	THJ5486 3 SPR	D44T1 3 GESY	
BF336 3 PHIN	DE396 3 DGE	TMPF5486 3 SPR	<b>BF244A</b> 2N5484 1 INL	THJ5484 3 SPR	THBC257 3 SPR	
BFN18 3 SIEG	TN3440 3 NSC	<b>BF244B</b> 2N5485 1 INL	THJ5484 3 SPR	THJ5484 3 SPR	<b>BF297</b> BF257 1 SGSI	
BFN26 3 SIEG	<b>BF181</b> MPSH04 3 MOTA	THJ5485 3 SPR	<b>BF244C</b> 2N5486 1 INL	THJ5484 3 SPR	BF336 1 PHIN	
D44T2 3 GESY	SF235 3 MIKG	TMPF5486 3 SPR	THJBF244C 1 SPR	<b>BF244D</b> 2N5246 3 IFC	MPSA43 1 MOTA	
DE396 3 DGE	<b>BF184</b> BF494 3 PHIN	<b>BF244E</b> 2N5245 3 IFC	TMPF5486 3 SPR	DE180 3 DGE	2N3440 3 RCA	
TN3440 3 NSC	DE161 3 DGE	THJ5486 3 SPR	<b>BF245</b> 2N5486 1 INL	THJ5484 3 SPR	BC557 3 PHIN	
<b>BF154</b> BF196 1 PHIN	<b>BF185</b> 2N2221 3 MOTA	TMPF5486 3 SPR	2N5247 3 IFC	BSV79 3 PHIN	D44T1 3 GESY	
BF198 1 PHIN	BF495 3 PHIN	<b>BF245A</b> 2N4416 1 INL	THJ5486 3 SPR	THJ5639 3 SPR	THBC257 3 SPR	
<b>BF155</b> BF180 1 PHIN	DE161 3 DGE	2N5486 1 INL	<b>BF245B</b> 2N5484 3 INL	TIS74 3 IFC	<b>BF299</b> BF259 1 SGSI	
<b>BF156</b> BF257 1 SGSI	<b>BF186</b> BF337 3 PHIN	2N5247 3 IFC	2N5484 3 INL	TMPF5639 3 SPR	BF336 1 PHIN	
D40V1 1 GESY	2N2221 3 MOTA	DE180 3 DGE	2N5246 3 IFC	<b>BF246</b> 2N5639 1 INL	MPSA43 1 MOTA	
BF336 3 PHIN	BF495 3 PHIN	THJ5484 3 SPR	THJBF246A 1 SPR	THJBF246A 1 SPR	2N3440 3 RCA	
<b>BF157</b> 2N3440 1 RCA	DE161 3 DGE	TMPF5484 3 SPR	TMPF5484 3 SPR	THJBF246B 1 SPR	BFN16 3 SIEG	
BF257 1 SGSI	<b>BF187</b> BF115 1 PHIN	<b>BF246A</b> 2N5638 1 INL	<b>BF246B</b> 2N5638 1 INL	THJBF246B 1 SPR	D40V1 3 GESY	
D40V1 1 GESY	BF494 3 PHIN	2N5638 1 INL	2N5638 1 INL	BSV78 3 PHIN	MPSA43C 3 SPR	
BD115 3 PHIN	MPSH04 3 MOTA	THJBF244B 1 SPR	THJBF246B 1 SPR	THJ5638 3 SPR	S298TS 3 ALGG	
BF336 3 PHIN	<b>BF189</b> BF115 1 PHIN	TMPF244B 1 SPR	TMPF5486 3 SPR	TIS73 3 IFC	TMPA443 3 SPR	
BFN18 3 SIEG	BF494 1 PHIN	2N5245 3 IFC	<b>BF246C</b> 2N5638 1 INL	THJBF246C 1 SPR	<b>BF298</b> 2N6515 1 MOTA	
BFN26 3 SIEG	MPSH04 3 MOTA	DE451 3 DGE	THJBF246C 1 SPR	TMPF5486 3 SPR	BF258 1 SGSI	
D44T2 3 GESY	<b>BF191</b> BF196 1 PHIN	THJ5485 3 SPR	BSV78 3 PHIN	<b>BF246D</b> 2N5638 1 INL	BF337 3 PHIN	
DE396 3 DGE	BF198 1 PHIN	TMPF5485 3 SPR	THJ5638 3 SPR	THJ5638 3 SPR	D40V1 3 GESY	
TN3440 3 NSC	<b>BF195</b> BF495 3 PHIN	<b>BF246E</b> 2N5638 1 INL	<b>BF247</b> 2N4091 1 INL	<b>BF247</b> 2N4091 1 INL	DE287 3 DGE	
<b>BF160</b> BF495 1 PHIN	<b>BF196</b> BF495 3 PHIN	THJBF244C 1 SPR	DE466 3 DGE	D40V1 1 PHIN	<b>BF299</b> BF259 1 SGSI	
MPSH04 3 MOTA	DE161 3 DGE	TMPF5486 3 SPR	2N3020 3 PHIN	2N3440 3 RCA	MPSA42 1 MOTA	
<b>BF161</b> BF183 1 PHIN	<b>BF197</b> BF199 3 PHIN	THJ5486 3 SPR	2N3440 3 RCA		BF338 1 PHIN	
<b>BF162</b> BF200 1 PHIN	<b>BF199</b> BF199 3 PHIN	<b>BF247</b> 2N4091 1 INL			BFN18 3 SIEG	
<b>BF163</b> BF196 1 PHIN	MPSH24 3 MOTA	2N5338 3 MOTA			D40V3 3 GESY	
BF198 1 PHIN						
<b>BF164</b> BF196 1 PHIN						