

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
<b>THJ4856A</b> 2N4856A 2 2N4856 3 INL TMPF4856A 3 SPR TP4856A 3 SPR	<b>THJ5021</b> (Cont'd) 2N2608 3 SIX DE460 3 DGE TMPF5021 3 SPR TP5021 3 SPR	<b>THJ5245</b> (Cont'd) 2N5245-18 3 SIX 2N5248-18 3 NSC DE129 3 DGE ITE4416 3 INL PN4416 3 SIX TMPF5245 3 SPR TP5245 3 SPR	<b>THJ5433</b> (Cont'd) MFE2012 3 MOTA <b>THJ5434</b> 2N5434 2 MFE2012 3 MOTA <b>THJ5457</b> 2N5457 3 IFC 2N5953 3 PHIN BF245A 3 PHIN DE451 3 DGE TMPF5457 3 SPR	<b>THJ5653</b> 2N5653 2 2N5638 3 INL BSV78 3 PHIN TIS74 3 IFC TMPF5653 3 SPR	<b>THJ6451</b> (Cont'd) TMPF6451 3 SPR TP6451 3 SPR U310 3 INL <b>THJ6452</b> 2N6452 2 2N4393 3 MOTA SIX TMPF6452 3 SPR TP6452 3 SPR U310 3 IFC 3 INL
<b>THJ4857</b> 2N4857 2 DE466 3 DGE TMPF4857 3 SPR TP4857 3 SPR	<b>THJ5033</b> 2N5033 2 2N2608 3 SIX 2N5460 3 INL MOTA	<b>THJ5246</b> 2N5246 2 2N5246-18 3 NSC SIX 2N5484 3 INL DE132 3 DGE J305-18 3 SIX TMPF5246 3 SPR TP5246 3 SPR	<b>THJ5458</b> 2N5458 2 2N5952 3 IFC BF245B 3 PHIN DE451 3 DGE TMPF5458 3 SPR	<b>THJ5654</b> 2N5654 2 2N5639 3 INL BSV79 3 PHIN TIS75 3 IFC TMPF5654 3 SPR	<b>THJ6453</b> 2N6453 2 2N4392 3 MOTA 2N4393 3 SIX TMPF6453 3 SPR TP6453 3 SPR U310 3 INL
<b>THJ4857A</b> 2N4857A 2 2N4857 3 INL TMPF4857A 3 SPR TP4857A 3 SPR	A5T5460 3 IFC DE326 3 DGE PN5033-18 3 NSC SIX TMPF5033 3 SPR TP5033 3 SPR	<b>THJ5247</b> 2N5247 2 2N5247-18 3 NSC SIX 2N5486 3 INL DE132 3 DGE MPF102 3 MOTA TMPF5248 3 SPR	<b>THJ5459</b> 2N5459 2 2N5951 3 IFC BF245C 3 PHIN DE451 3 DGE TMPF5459 3 SPR	<b>THJ5668</b> 2N5668 2 2N5484 3 INL 2N5953 3 IFC BF245A 3 PHIN DE457 3 DGE TMPF5668 3 SPR TP5668 3 SPR	<b>THJ6454</b> 2N6454 2 2N4392 3 MOTA 2N4393 3 SIX TMPF6454 3 SPR TP6454 3 SPR U310 3 INL
<b>THJ4858</b> 2N4858 2 DE466 3 DGE TMPF4858 3 SPR TP4858 3 SPR	<b>THJ5045</b> 2N5045 2 2N5453 3 INL BFS21A 3 PHIN MP844 3 MPS	<b>THJ5247</b> 2N5247 2 2N5247-18 3 NSC SIX 2N5486 3 INL DE132 3 DGE J304-18 3 SIX TMPF5247 3 SPR TP5247 3 SPR	<b>THJ5460</b> 2N5460 2 DE326 3 DGE MRF454 3 MOTA TMPF5460 3 SPR	<b>THJ5669</b> 2N5669 2 2N5485 3 INL 2N5952 3 IFC BF245B 3 PHIN TMPF5669 3 SPR TP5669 3 SPR	<b>THJ6455</b> 2N6455 2 2N4392 3 MOTA 2N4393 3 SIX TMPF6455 3 SPR TP6455 3 SPR U310 3 INL
<b>THJ4858A</b> 2N4858A 2 2N4858 3 INL TMPF4858A 3 SPR TP4858A 3 SPR	<b>THJ5046</b> 2N5046 2 2N5454 3 INL BFS21A 3 PHIN MP844 3 MPS	<b>THJ5248</b> 2N5248 2 2N5486 3 INL SIX DE132 3 DGE MPF102 3 MOTA TMPF5248 3 SPR	<b>THJ5461</b> 2N5461 2 DE326 3 DGE TMPF5461 3 SPR	<b>THJ5670</b> 2N5670 2 2N5486 3 INL 2N5950 3 IFC BF245C 3 PHIN TMPF5670 3 SPR TP5670 3 SPR	<b>THJ6456</b> 2N6456 2 2N4392 3 MOTA 2N4393 3 SIX TMPF6456 3 SPR TP6456 3 SPR U310 3 INL
<b>THJ4859</b> 2N4859 2 DE466 3 DGE TMPF4859 3 SPR TP4859 3 SPR	<b>THJ5078</b> 2N5078 2 2N4416 3 IFC 2N5397 3 INL DE452 3 DGE TMPF5078 3 SPR TP5078 3 SPR	<b>THJ5358</b> 2N5358 2 2N4220 3 INL 2N4340 3 SIX BFW13 3 PHIN DE459 3 DGE TMPF5358 3 SPR TP5358 3 SPR	<b>THJ5462</b> 2N5462 2 DE326 3 DGE TMPF5462 3 SPR	<b>THJ5911</b> 2N5911 2 MP5911 3 MPS	<b>THJ6457</b> 2N6457 2 2N4392 3 MOTA 2N4393 3 SIX TMPF6457 3 SPR TP6457 3 SPR U310 3 INL
<b>THJ4859A</b> 2N4859A 2 2N4859 3 INL TMPF4859A 3 SPR TP4859A 3 SPR	<b>THJ5103</b> 2N5103 2 2N4416 3 INL MOTA	<b>THJ5359</b> 2N5359 2 2N4220 3 INL 2N4340 3 SIX BFW12 3 PHIN DE459 3 DGE TMPF5359 3 SPR TP5359 3 SPR	<b>THJ5463</b> 2N5463 2 DE326 3 DGE TMPF5463 3 SPR	<b>THJ5912</b> 2N5912 2 MP5912 3 MPS	<b>THJ6458</b> 2N6458 2 2N4392 3 MOTA 2N4393 3 SIX TMPF6458 3 SPR TP6458 3 SPR U310 3 INL
<b>THJ4860</b> 2N4860 2 DE466 3 DGE TMPF4860 3 SPR TP4860 3 SPR	<b>THJ5104</b> 2N5104 2 2N4116 3 MOTA 2N4416 3 INL SIX DE459 3 DGE TMPF5104 3 SPR TP5104 3 SPR	<b>THJ5360</b> 2N5360 2 2N4221 3 INL 2N4339 3 SIX BFW12 3 PHIN DE459 3 DGE TMPF5360 3 SPR TP5360 3 SPR	<b>THJ5464</b> 2N5464 2 2N3955A 3 INL DE461 3 DGE MP844 3 MPS	<b>THJ5949</b> 2N5949 2 2N5486 3 INL 2N5638 3 MOTA 2N5949-18 3 NSC SIX PN4416 3 SIX SX3819 3 TII TIS59 3 TII TMPF5949 3 SPR TP5949 3 SPR	<b>THJ6459</b> 2N6459 2 2N4392 3 MOTA 2N4393 3 SIX TMPF6459 3 SPR TP6459 3 SPR U310 3 INL
<b>THJ4860A</b> 2N4860A 2 2N4860 3 INL TMPF4860A 3 SPR TP4860A 3 SPR	<b>THJ5105</b> 2N5105 2 2N4116 3 MOTA 2N4416 3 INL SIX DE459 3 DGE TMPF5105 3 SPR TP5105 3 SPR	<b>THJ5361</b> 2N5361 2 2N4221 3 INL 2N4339 3 SIX BFW10 3 PHIN TMPF5361 3 SPR TP5361 3 SPR	<b>THJ5465</b> 2N5465 2 2N3955 3 INL 2N5245 3 IFC DE451 3 DGE TMPF5465 3 SPR	<b>THJ5950</b> 2N5950 2 2N5486 3 INL 2N5639 3 MOTA 2N5950-18 3 NSC SIX PN4416 3 SIX TMPF5950 3 SPR TP5950 3 SPR	<b>THJ6460</b> 2N6460 2 2N4392 3 MOTA 2N4393 3 SIX TMPF6460 3 SPR TP6460 3 SPR U310 3 INL
<b>THJ4861</b> 2N4861 2 DE466 3 DGE TMPF4861 3 SPR TP4861 3 SPR	<b>THJ5114</b> 2N5114 2 2N3993 3 MOTA TMPF5114 3 SPR TP5114 3 SPR	<b>THJ5362</b> 2N5362 2 2N4222 3 INL 2N4339 3 SIX BFW11 3 PHIN DE459 3 DGE TMPF5362 3 SPR TP5362 3 SPR	<b>THJ5466</b> 2N5466 2 2N3955 3 INL DE461 3 DGE MP844 3 MPS	<b>THJ5951</b> 2N5951 2 2N5486 3 INL 2N5640 3 MOTA 2N5951-18 3 NSC SIX PN4416 3 SIX TIS59 3 TII TMPF5951 3 SPR TP5951 3 SPR	<b>THJ6461</b> 2N6461 2 2N4392 3 MOTA 2N4393 3 SIX TMPF6461 3 SPR TP6461 3 SPR U310 3 INL
<b>THJ4861A</b> 2N4861A 2 2N4861 3 INL TMPF4861A 3 SPR TP4861A 3 SPR	<b>THJ5115</b> 2N5115 2 2N3993 3 MOTA TMPF5115 3 SPR TP5115 3 SPR	<b>THJ5363</b> 2N5363 2 2N4222 3 INL 2N4222A 3 SIX BFW10 3 PHIN TMPF5363 3 SPR TP5363 3 SPR	<b>THJ5467</b> 2N5467 2 2N3955 3 INL DE461 3 DGE MP844 3 MPS	<b>THJ5952</b> 2N5952 2 2N5484 3 INL 2N5640 3 MOTA 2N5952-18 3 NSC SIX J305 3 SIX TIS58 3 TII TMPF5952 3 SPR TP5952 3 SPR	<b>THJ6462</b> 2N6462 2 2N4392 3 MOTA 2N4393 3 SIX TMPF6462 3 SPR TP6462 3 SPR U310 3 INL
<b>THJ4867</b> 2N4867 2 2N4220A 3 MOTA 2N4339 3 NSC SIX DE459 3 DGE TMPF4867 3 SPR TP4867 3 SPR	<b>THJ5116</b> 2N5116 2 2N3994 3 MOTA TMPF5116 3 SPR TP5116 3 SPR	<b>THJ5364</b> 2N5364 2 2N4222 3 INL 2N4224 3 SIX BFW10 3 PHIN TMPF5364 3 SPR TP5364 3 SPR	<b>THJ5468</b> 2N5468 2 2N3955 3 INL DE461 3 DGE MP844 3 MPS	<b>THJ5953</b> 2N5953 2 2N5484 3 INL 2N5640 3 MOTA 2N5953-18 3 NSC SIX J305 3 SIX SX3819 3 TII TIS58 3 TII TMPF5953 3 SPR TP5953 3 SPR	<b>THJ6463</b> 2N6463 2 2N4392 3 MOTA 2N4393 3 SIX TMPF6463 3 SPR TP6463 3 SPR U310 3 INL
<b>THJ4868</b> 2N4868 2 2N3459 3 NSC SIX 2N4220A 3 MOTA DE459 3 DGE TMPF4868 3 SPR TP4868 3 SPR	<b>THJ5163</b> 2N5163 2 2N3822 3 INL 2N5246 3 IFC 2N5458 3 MOTA PN5163-18 3 NSC SIX TMPF5163 3 SPR TP5163 3 SPR	<b>THJ5397</b> 2N5397 2 DE452 3 DGE TMPF5397 3 SPR TP5397 3 SPR U309 3 MOTA U310 3 SIX	<b>THJ5469</b> 2N5469 2 2N3955 3 INL DE461 3 DGE MP844 3 MPS	<b>THJ5954</b> 2N5954 2 2N5484 3 INL 2N5638 3 MOTA 2N5954-18 3 NSC SIX PN4416 3 SIX TIS59 3 TII TMPF5954 3 SPR TP5954 3 SPR	<b>THJ6464</b> 2N6464 2 2N4392 3 MOTA 2N4393 3 SIX TMPF6464 3 SPR TP6464 3 SPR U310 3 INL
<b>THJ4869</b> 2N4869 2 2N4221 3 MOTA 2N4341 3 NSC SIX DE459 3 DGE TMPF4869 3 SPR TP4869 3 SPR	<b>THJ5198</b> 2N5198 2 2N3994 3 MOTA TMPF5198 3 SPR TP5198 3 SPR	<b>THJ5398</b> 2N5398 2 DE452 3 DGE TMPF5398 3 SPR TP5398 3 SPR U309 3 MOTA U310 3 SIX	<b>THJ5470</b> 2N5470 2 2N3955 3 INL DE461 3 DGE MP844 3 MPS	<b>THJ5955</b> 2N5955 2 2N5484 3 INL 2N5638 3 MOTA 2N5955-18 3 NSC SIX PN4416 3 SIX TIS59 3 TII TMPF5955 3 SPR TP5955 3 SPR	<b>THJ6465</b> 2N6465 2 2N4392 3 MOTA 2N4393 3 SIX TMPF6465 3 SPR TP6465 3 SPR U310 3 INL
<b>THJ5018</b> 2N5018 2 2N3993 3 MOTA DE460 3 DGE TMPF5018 3 SPR TP5018 3 SPR	<b>THJ5199</b> 2N5199 2 2N3994 3 MOTA TMPF5199 3 SPR TP5199 3 SPR	<b>THJ5432</b> 2N5432 2 MFE2012 3 MOTA	<b>THJ5471</b> 2N5471 2 2N3955 3 INL DE461 3 DGE MP844 3 MPS	<b>THJ5956</b> 2N5956 2 2N5484 3 INL 2N5638 3 MOTA 2N5956-18 3 NSC SIX J305 3 SIX TIS58 3 TII TMPF5956 3 SPR TP5956 3 SPR	<b>THJ6466</b> 2N6466 2 2N4392 3 MOTA 2N4393 3 SIX TMPF6466 3 SPR TP6466 3 SPR U310 3 INL
<b>THJ5019</b> 2N5019 2 2N3993 3 IFC 2N3994 3 MOTA DE460 3 DGE TMPF5019 3 SPR TP5019 3 SPR	<b>THJ5245</b> 2N5245 2	<b>THJ5433</b> 2N5433 2	<b>THJ5472</b> 2N5472 2 2N3955 3 INL DE461 3 DGE MP844 3 MPS	<b>THJ5957</b> 2N5957 2 2N5484 3 INL 2N5638 3 MOTA 2N5957-18 3 NSC SIX J305 3 SIX SX3819 3 TII TIS58 3 TII TMPF5957 3 SPR TP5957 3 SPR	<b>THJ6467</b> 2N6467 2 2N4392 3 MOTA 2N4393 3 SIX TMPF6467 3 SPR TP6467 3 SPR U310 3 INL
<b>THJ5020</b> 2N5020 2 2N2843 3 INL 2N3329 3 SIX 2N5265 3 MOTA DE460 3 DGE TMPF5020 3 SPR TP5020 3 SPR	<b>THJ5245</b> 2N5245 2	<b>THJ5433</b> 2N5433 2	<b>THJ5473</b> 2N5473 2 2N3955 3 INL DE461 3 DGE MP844 3 MPS	<b>THJ5958</b> 2N5958 2 2N5484 3 INL 2N5638 3 MOTA 2N5958-18 3 NSC SIX J305 3 SIX TIS58 3 TII TMPF5958 3 SPR TP5958 3 SPR	<b>THJ6468</b> 2N6468 2 2N4392 3 MOTA 2N4393 3 SIX TMPF6468 3 SPR TP6468 3 SPR U310 3 INL
<b>THJ5021</b> 2N5021 2 2N2607 3 INL 2N2608 3 MOTA	<b>THJ5245</b> 2N5245 2	<b>THJ5433</b> 2N5433 2	<b>THJ5474</b> 2N5474 2 2N3955 3 INL DE461 3 DGE MP844 3 MPS	<b>THJ5959</b> 2N5959 2 2N5484 3 INL 2N5638 3 MOTA 2N5959-18 3 NSC SIX J305 3 SIX SX3819 3 TII TIS58 3 TII TMPF5959 3 SPR TP5959 3 SPR	<b>THJ6469</b> 2N6469 2 2N4392 3 MOTA 2N4393 3 SIX TMPF6469 3 SPR TP6469 3 SPR U310 3 INL