

| Part No. Replacement No. Mfr. | Part No. Replacement No. Mfr. | Part No. Replacement No. Mfr. | Part No. Replacement No. Mfr. | Part No. Replacement No. Mfr. | Part No. Replacement No. Mfr. | Part No. Replacement No. Mfr. |
|----------------------------------|----------------------------------|----------------------------------|----------------------------------|----------------------------------|----------------------------------|----------------------------------|
| 2N5258 (Cont'd) | 2N5267 (Cont'd) | 2N5284 | 2N5319 (Cont'd) | 2N5335 (Cont'd) | 2N5354 (Cont'd) | |
| 2N5484 3 INL | 2N3329 3 SIX | 2N5347 1 MOTA | SVT250-5B 3 TRWS | 2N3020 3 MOTA | THC5354 1 SPR | |
| 2N5640 3 MOTA | 2N3329-5 3 NSC | BDY90 1 PHIN | 2N5320 | 2N5154 3 TRWS | 2N5355 | |
| 2N5952-18 3 NSC | SIX 3 SIX | D44VM10 3 GESY | DE128 1 DGE | D44VM10 3 GESY | DE290A 1 DGE | |
| SIX 3 SIX | 2N3330 3 MOTA | 2N5285 | 2N1893 3 RCA | 2N5336 | THC5355 1 SPR | |
| BF245B 3 PHIN | 2N3332 3 SIX | 2N5347 1 MOTA | 2N3053 3 MOTA | 2N4309 1 TRWS | 2N5356 | |
| DE451 3 DGE | 2N3332-5 3 NSC | D44VM10 3 GESY | 2N5347 3 MOTA | D44VM10 1 GESY | DE290A 1 DGE | |
| J305 3 SIX | 2N5265 3 MOTA | 2N5286 | BC301 3 SGSI | 2N4305 3 TRWS | THC5356 1 SPR | |
| THJ5458 3 SPR | THJ2608 3 SPR | 2N6189 1 MOTA | BC637 3 PHIN | 2N4307 3 TRWS | 2N5358 | |
| THJ5952 3 SPR | THJ3329 3 SPR | 2N5287 | BD139 3 PHIN | 2N5339 3 MOTA | 2N4220 1 INL | |
| TIS58 3 TII | TPMPF2608 3 SPR | 2N6189 1 MOTA | BFX34 3 PHIN | TRWS 3 TRWS | 2N4340 1 SIX | |
| TPMPF5458 3 SPR | TPMPF3329 3 SPR | 2N5288 | BSV64 3 PHIN | D40D7 3 GESY | BFW13 1 PHIN | |
| TPMPF5952 3 SPR | TP2608 3 SPR | BDY90 1 PHIN | D40D7 3 GESY | D42C8 3 GESY | DE459 1 DGE | |
| TP5952 3 SPR | TP3329 3 SPR | 2N5293 | 2N5337 | 2N5337 | THJ5358 1 SPR | |
| 2N5259 | 2N5268 | 2N6123 1 MOTA | 2N5154 1 TRWS | 2N5154 1 TRWS | TPMPF5358 1 SPR | |
| 2N5459 1 INL | 2N2608 1 INL | BDT41B 1 APX | D44VM10 1 GESY | D44VM10 1 GESY | TP5358 1 SPR | |
| SIX 3 SIX | 2N2609 3 NSC | DE152 1 DGE | DE128 1 DGE | 2N4305 3 TRWS | 2N3459 3 IFC | |
| 2N5951 1 IFC | SIX 3 SIX | BD951 3 PHIN | 2N3725 3 SGSI | 2N4309 3 TRWS | 2N3460 3 IFC | |
| 2N5486 3 INL | 2N2609 3 NSC | BDT31B 3 APX | 2N4236 3 MOTA | 2N4311 3 TRWS | 2N3686 3 INL | |
| 2N5640 3 MOTA | SIX 3 SIX | DE196 3 DGE | 2N4307 3 TRWS | 2N5315 3 TRWS | 2N3687 3 SIX | |
| 2N5951-18 3 NSC | 2N3330 3 IFC | 2N5294 | 2N6292 3 RCA | 2N5339 3 TRWS | 2N4338 3 INL | |
| SIX 3 SIX | MOTA 3 MOTA | 2N6123 1 MOTA | BC440 3 SGSI | 2N5953 3 IFC | SIX 3 SIX | |
| BF245C 3 PHIN | THJ2608 3 SPR | BDT41B 1 APX | BSX32 3 SGSI | BF245C 3 PHIN | 2N4341 3 SIX | |
| DE451 3 DGE | THJ3330 3 SPR | DE152 1 DGE | BSX59 3 PHIN | BSW66 3 PHIN | 2N4867 3 INL | |
| PN4416 3 SIX | THJ3332 3 SPR | BD951 3 PHIN | BSX60 3 PHIN | BUY47 3 SGSI | 2N5359 3 MOTA | |
| THJ5459 3 SPR | THJ3332 3 SPR | BDT31B 3 APX | BSX61 3 PHIN | BUY68 3 SGSI | 2N5486 3 MOTA | |
| THJ5951 3 SPR | TPMPF2608 3 SPR | DE196 3 DGE | D40D1 3 GESY | D40D4 3 GESY | BFW12 3 PHIN | |
| TIS59 3 TII | TPMPF3330 3 SPR | 2N5295 | D40D4 3 GESY | D40D5 3 GESY | DE456 3 DGE | |
| TPMPF5459 3 SPR | TPMPF3332 3 SPR | 2N6121 1 MOTA | D40D7 3 GESY | D40D7 3 GESY | THJ4220 3 SPR | |
| TPMPF5951 3 SPR | TP2608 3 SPR | BDT41 1 APX | D42C1 3 GESY | D40D8 3 GESY | THJ4340 3 SPR | |
| TP5951 3 SPR | TP3330 3 SPR | DE152 1 DGE | MDS27 3 MOTA | D42C5 3 GESY | TPMPF4220 3 SPR | |
| 2N5260 | TP3332 3 SPR | BD947 3 PHIN | THC3444 3 SPR | D42C6 3 GESY | TPMPF4340 3 SPR | |
| 2N5460 1 IFC | 2N5269 | BDT31A 3 APX | TP3444 3 SPR | D42C7 3 GESY | TP4220 3 SPR | |
| DE326 3 DGE | 2N2609 1 INL | DE196 3 DGE | 2N5322 | D42C8 3 GESY | TP4340 3 SPR | |
| MRF454 3 MOTA | 2N2609 1 INL | 2N5296 | D42C8 1 GESY | DE73 3 DGE | 2N5359 | |
| THJ5460 3 SPR | 2N2609 3 NSC | 2N5298 1 RCA | DE129 1 DGE | DE195A 3 DGE | 2N4220 1 INL | |
| TPMPF5460 3 SPR | 2N2609 3 NSC | 2N6121 1 MOTA | 2N5679 3 MOTA | DE324 3 DGE | 2N4340 1 SIX | |
| 2N5262 | THJ2609 3 SPR | BDT41 1 APX | 2N6292 3 RCA | DE457 3 DGE | BFW12 1 PHIN | |
| BFX34 1 PHIN | THJ3331 3 SPR | DE152 1 DGE | BSS44 3 SGSI | PN4302-18 3 NSC | DE459 1 DGE | |
| BSV64 1 PHIN | TPMPF2609 3 SPR | 2N6122 3 MOTA | BSV16 3 SGSI | SIX 3 SIX | THJ5359 1 SPR | |
| D42C7 1 GESY | TPMPF3331 3 SPR | BD949 3 PHIN | D41D7 3 GESY | THJ4302 3 SPR | TPMPF5359 1 SPR | |
| 2N6292 3 RCA | TP2609 3 SPR | BDT31A 3 APX | D43C8 3 GESY | TIP501 3 TII | TP5359 1 SPR | |
| MDS27 3 MOTA | TP3331 3 SPR | BDT41A 3 APX | DE323 3 DGE | TPMPF4302 3 SPR | 2N3459 3 IFC | |
| 2N5264 | 2N5270 | DE196 3 DGE | MDS27 3 MOTA | TP4302 3 SPR | 2N3684 3 INL | |
| 2N6249 1 MOTA | 2N2609 1 INL | DE452 3 DGE | THC3720 3 SPR | 2N5338 | 2N3685 3 INL | |
| 2N6510 1 RCA | 2N3331 1 SIX | 2N5297 | 2N5323 | D44VM10 1 GESY | 2N3686 3 SIX | |
| 2N6306 3 MOTA | 2N2609 3 NSC | 2N6122 1 MOTA | D43C7 1 GESY | 2N5339 3 TRWS | 2N4221 3 MOTA | |
| 2N6674 3 PTC | 2N3330 3 MOTA | BDT41A 1 APX | DE129 1 DGE | 2N5458 3 INL | 2N4339 3 INL | |
| BUX41 3 SGSI | 2N3331 3 IFC | DE152 1 DGE | 2N6107 3 RCA | 2N5459 3 INL | SIX 3 SIX | |
| BUX80 3 PHIN | 2N3331 3 IFC | BD949 3 PHIN | BSS44 3 SGSI | 2N5951 3 IFC | 2N4416 3 INL | |
| D64VS3 3 GESY | 2N5265 3 MOTA | BDT31A 3 APX | D40D5 3 GESY | 2N5952 3 IFC | 2N4867 3 INL | |
| DE283 3 DGE | THJ2609 3 SPR | DE196 3 DGE | D41D4 3 GESY | BF245A 3 PHIN | BFW13 3 PHIN | |
| DE286 3 DGE | THJ3331 3 SPR | 2N5298 | D41D7 3 GESY | BF245B 3 PHIN | DE456 3 DGE | |
| SDT7605 3 SOD | TPMPF2609 3 SPR | 2N6122 1 MOTA | D43C6 3 GESY | DE457 3 DGE | THJ4220 3 SPR | |
| SDT7610 3 SOD | TPMPF3331 3 SPR | BDT41A 1 APX | MDS77 3 MOTA | PN4303-18 3 NSC | THJ4340 3 SPR | |
| SDT7611 3 SOD | TP2609 3 SPR | DE152 1 DGE | THC3719 3 SPR | SIX 3 SIX | TPMPF4220 3 SPR | |
| SDT7612 3 SOD | TP3331 3 SPR | DE452 1 DGE | 2N5324 | TP4302 3 SPR | TPMPF4340 3 SPR | |
| SVT7523 3 TRWS | 2N5277 | 2N6121 3 MOTA | DE127 1 DGE | PN4304-18 3 NSC | TP4220 3 SPR | |
| SVT7563 3 TRWS | 2N4341 1 INL | BD949 3 PHIN | MP3730A 1 LTE | SIX 3 SIX | TP4340 3 SPR | |
| 2N5265 | 2N3458 3 IFC | BDT31A 3 APX | 2N5325 | THJ4303 3 SPR | 2N5360 | |
| 2N2607 1 INL | 2N3458 3 IFC | BDT41 3 APX | DE127 1 DGE | THJ4304 3 SPR | 2N4221 1 INL | |
| 2N2608 1 SIX | DE312 3 DGE | DE196 3 DGE | MP3730B 1 LTE | TPMPF4303 3 SPR | 2N4339 1 SIX | |
| 2N2606 3 INL | THJ4341 3 SPR | 2N5301 | 2N5326 | TP4303 3 SPR | BFW12 1 PHIN | |
| 2N2608 3 IFC | TPMPF4341 3 SPR | DE181 1 DGE | 2N5347 1 MOTA | TP4304 3 SPR | DE459 1 DGE | |
| INL 3 INL | TP4341 3 SPR | STD7731 1 SOD | D44VM10 1 GESY | 2N5339 | THJ5360 1 SPR | |
| NSC 3 NSC | 2N5276 | STD7732 1 SOD | DE74 3 DGE | 2N5336 3 MOTA | TPMPF5360 1 SPR | |
| 2N2609 3 IFC | 2N4341 1 INL | STD7733 1 SOD | 2N5330 | 2N5337 3 MOTA | TP5360 1 SPR | |
| INL 3 INL | 2N5364 1 MOTA | STD7734 1 SOD | 2N6338 3 MOTA | 2N5338 3 MOTA | 2N3685 3 INL | |
| 2N2643 3 INL | 2N3458 3 IFC | STD9204 1 SOD | TIP526 3 TII | 2N6056 3 MOTA | SIX 3 SIX | |
| 2N3329 3 IFC | 2N4222 3 INL | STD9209 1 SOD | 2N5331 | BSW66 3 PHIN | 2N3821 3 MOTA | |
| NSC 3 NSC | 2N4224 3 SIX | 2N5302 | 2N6274 3 MOTA | DE282 3 DGE | 2N3822 3 INL | |
| 2N3331 3 IFC | BFW10 3 PHIN | DE181 1 DGE | DE70 3 DGE | 2N5344 | SIX 3 SIX | |
| NSC 3 NSC | BFW11 3 PHIN | DE283 3 DGE | 2N5333 | 2N6211 1 RCA | 2N4220 3 NSC | |
| 2N3438 3 SIX | DE312 3 DGE | 2N5303 | 2N6303 1 MOTA | D44T1 1 GESY | SIX 3 SIX | |
| 2N3822 3 IFC | THJ4341 3 SPR | DE181 1 DGE | BSS44 1 SGSI | DE38 3 DGE | 2N4220A 3 MOTA | |
| 2N5020 3 NSC | THJ5364 3 SPR | 2N6258 3 RCA | THC5333 1 SPR | 2N5345 | 2N4221 3 MOTA | |
| SIX 3 SIX | TPMPF4341 3 SPR | 2N5304 | TIP522 2 TII | 2N6212 1 RCA | 2N4340 3 INL | |
| 2N5267 3 INL | TPMPF5364 3 SPR | D44H4 1 GESY | 2N6211 3 MOTA | D44T3 1 GESY | 2N4416 3 INL | |
| 2N5270 3 INL | TP4341 3 SPR | 2N6290 3 RCA | DE323 3 DGE | DE38 3 DGE | 2N4540 3 SIX | |
| DE460 3 DGE | TP5364 3 SPR | BUV26 3 APX | ST522 3 STI | 2N5346 | 2N4540 3 SIX | |
| IT132 3 INL | 2N5279 | ST44H4 3 STI | THC6303 3 SPR | D44VM10 1 GESY | BFW13 3 PHIN | |
| THJ2608 3 SPR | 2N3439 1 RCA | 2N5305 | 2N5334 | 2N5347 | DE312 3 DGE | |
| THJ5020 3 SPR | 2N3742 1 MOTA | BDY29 1 RCA | 2N5337 1 MOTA | D44VM10 1 GESY | DE456 3 DGE | |
| TPMPF2608 3 SPR | D44T4 1 GESY | DE172A 1 DGE | BUY68 1 SGSI | 2N44VM10 1 GESY | THJ4221 3 SPR | |
| TPMPF5020 3 SPR | DE154 1 DGE | THC5305 1 SPR | D42C7 1 GESY | 2N5326 3 TRWS | THJ4339 3 SPR | |
| TP2608 3 SPR | DE396 3 DGE | 2N5306 | 2N2102 3 RCA | 2N6674 3 RCA | TPMPF4221 3 SPR | |
| TP5020 3 SPR | GES3742 3 GESY | DE172A 1 DGE | 2N2107 3 RCA | BDY90 3 PHIN | TP4221 3 SPR | |
| 2N5266 | THC3742 3 SPR | THC5306 1 SPR | 2N3053 3 RCA | DE74 3 DGE | TP4339 3 SPR | |
| 2N2607 1 INL | 2N5280 | 2N5307 | 2N4404 3 MOTA | DE75 3 DGE | 2N5361 | |
| 2N2608 1 SIX | 2N4036 1 RCA | DE172A 1 DGE | 2N5154 3 TRWS | SVT250-5 3 TRW | 2N4221 1 INL | |
| 2N5020 3 NSC | BCX53-6 3 SIEG | THC5307 1 SPR | 2N6292 3 RCA | SVT250-10 3 TRW | 2N4339 1 SIX | |
| THJ2608 3 SPR | BCX53-10 3 SIEG | 2N5308 | BD139 3 PHIN | SVT300-5 3 TRW | DE459 1 DGE | |
| TPMPF2608 3 SPR | D41D7 3 GESY | THC5308 1 SPR | D40D7 3 GESY | SVT300-10 3 TRW | THJ5361 1 SPR | |
| TP2608 3 SPR | DE129 3 DGE | 2N5309 | D42C4 3 GESY | SVT300-20 3 TRW | TPMPF5361 1 SPR | |
| 2N5267 | THC4036 3 SPR | DE289A 1 DGE | D42C6 3 GESY | SVT7511 3 TRW | TP5361 1 SPR | |
| 2N2608 1 INL | TN4036 3 NSC | 2N5310 | D42C8 3 GESY | SVT7512 3 TRW | 2N3684 3 INL | |
| SIX 3 SIX | 2N5281 | THC5310 1 SPR | D44VM10 3 GESY | TIP531 3 TII | 2N3822 3 MOTA | |
| THJ2608 3 SPR | 2N5415 1 RCA | 2N5315 | DE324 3 DGE | TIP532 3 TII | NSC 3 NSC | |
| TPMPF2608 3 SPR | DE397 1 DGE | 2N5337 3 MOTA | MDS27 3 MOTA | 2N5348 | SIX 3 SIX | |
| TP2608 3 SPR | BFN17 3 SIEG | DE73 3 DGE | THC3945 3 SPR | D44VM10 1 GESY | 2N4220A 3 MOTA | |
| 2N5267 | BFN25 3 SIEG | 2N5319 | 2N5335 | 2N5349 | 2N4221A 3 MOTA | |
| 2N2608 1 INL | 2N5282 | 2N5330 1 TRWS | 2N5337 1 MOTA | D44VM10 1 GESY | 2N4868A 3 INL | |
| SIX 3 SIX | 2N5416 1 RCA | TIP526 2 TII | BUY47 1 SGSI | 2N5354 | SIX 3 SIX | |
| 2N3329 3 IFC | DE397 3 DGE | MJ15011 3 MOTA | 2N1893 3 RCA | DE290A 1 DGE | 2N4869 3 INL | |