

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
<b>2N3211</b> (Cont'd) DE123AP 3 DGE PN3646 3 NSC THC3013 3 SPR THC3903 3 SPR TMPT3903 3 SPR	<b>2N3236</b> (Cont'd) 2N6254 1 RCA DE283 1 DGE 2N5878 3 MOTA DE130 3 DGE DE385 3 DGE SDT7731 3 SOD SDT7732 3 SOD SDT7733 3 SOD SDT9202 3 SOD SDT9207 3 SOD SDT9704 3 SOD SDT9801 3 SOD SDT9802 3 SOD SDT9803 3 SOD	<b>2N3250</b> (Cont'd) MPS3702 3 GESY PN200 3 NSC THC2905 3 SPR THC3702 3 SPR THC3905 3 SPR TMPT3905 3 SPR TN2905 3 NSC TP2905 3 SPR	<b>2N3278</b> (Cont'd) THJ2608 3 SPR TMPF2608 3 SPR TP2608 3 SPR	<b>2N3297</b> D44C4 3 GESY 2N6290 3 RCA BD239 3 RCA BU407 3 APX ST44C4 3 STI	<b>2N3309A</b> 2N3553 1 MOTA BUY68 3 SGI D40D4 3 GESY
<b>2N3212</b> DE176 1 DGE	<b>2N3237</b> SDT9704 3 SOD SDT9801 3 SOD SDT9802 3 SOD SDT9803 3 SOD	<b>2N3250A</b> 1 GESY	<b>2N3280</b> DE160 1 DGE	<b>2N3298</b> 2N2369 1 MOTA D40D2 1 GESY 2N3903 3 GESY BCW60A 3 SIEG PN2369 3 NSC	<b>2N3310</b> 2N3903 1 GESY 2N2222 3 SGI BC548A 3 PHIN DE123AP 3 DGE THC3903 3 SPR TMPT3903 3 SPR
<b>2N3213</b> DE176 1 DGE	<b>2N3238</b> 2N5302 1 MOTA DE283 1 DGE DE181 3 DGE	<b>2N3251</b> 2N2905 1 PHIN 2N3906 1 NSC DE159 1 DGE GES3251 1 GESY THC3251 1 SPR TP3251 1 SPR 2N2907 3 SGI 2N2907A 3 PHIN 2N4351 3 INL BC557 3 PHIN BCX71G 3 SIEG BSS80C 3 SIEG BSX29 3 SGI DE106 3 DGE DE129 3 DGE DE234 3 DGE MPS3703 3 GESY PN200 3 NSC PN4917-18 3 NSC THC2905 3 SPR THC3703 3 SPR THC3906 3 SPR THC4917 3 SPR TMPT3906 3 SPR TN2905 3 NSC TP2905 3 SPR	<b>2N3281</b> DE160 1 DGE 2N4339 3 INL	<b>2N3299</b> 2N2218 1 PHIN D40D1 1 GESY DE128 1 DGE THC3299 1 SPR TP3299 1 SPR 2N697 3 RCA GES2218 3 GESY THC2218 3 SPR TN2218 3 NSC TP2218 3 SPR	<b>2N3311</b> DE105 1 DGE
<b>2N3214</b> DE176 1 DGE	<b>2N3239</b> 2N5882 1 MOTA DE283 1 DGE BDW51B 3 SGI DE181 3 DGE	<b>2N3251A</b> 1 PHIN 2N3906 1 NSC DE159 1 DGE GES3251 1 GESY THC3251 1 SPR TP3251 1 SPR 2N2907 3 SGI 2N2907A 3 PHIN 2N4351 3 INL BC557 3 PHIN BCX71G 3 SIEG BSS80C 3 SIEG BSX29 3 SGI DE106 3 DGE DE129 3 DGE DE234 3 DGE MPS3703 3 GESY PN200 3 NSC PN4917-18 3 NSC THC2905 3 SPR THC3703 3 SPR THC3906 3 SPR THC4917 3 SPR TMPT3906 3 SPR TN2905 3 NSC TP2905 3 SPR	<b>2N3282</b> DE160 1 DGE	<b>2N3300</b> 2N2219 1 SGI 2N4401 1 NSC BSX60 1 PHIN D40D1 1 GESY DE128 1 DGE THC3300 1 SPR TP3300 1 SPR 2N3725 3 SGI 2N5321 3 RCA BC337 3 PHIN BSS79C 3 SIEG DE123AP 3 DGE GES2219 3 GESY PN100 3 NSC THC2219 3 SPR THC4401 3 SPR TMPT4401 3 SPR TN2219 3 NSC TP2219 3 SPR	<b>2N3312</b> DE105 1 DGE
<b>2N3215</b> DE176 1 DGE	<b>2N3240</b> 2N5882 1 MOTA DE283 1 DGE BDW51B 3 SGI DE181 3 DGE	<b>2N3252</b> 2N3725 1 SGI D40D7 1 GESY THC3252 1 SPR TP3252 1 SPR BSX59 3 PHIN D40E7 3 GESY THC3725 3 SPR TN3725 3 NSC	<b>2N3283</b> DE160 1 DGE	<b>2N3301</b> 2N2222 1 PHIN 2N4400 1 NSC DE123A 1 DGE GES2221 1 GESY THC3301 1 SPR TP3301 1 SPR BC337 3 PHIN BSS79B 3 SIEG DE123AP 3 DGE GES2222 3 GESY PN2222 3 NSC THC2222 3 SPR THC4400 3 SPR TMPT2222 3 SPR	<b>2N3313</b> DE105 1 DGE
<b>2N3216</b> DE102A 1 DGE	<b>2N3241</b> BFY52 1 PHIN DE123A 1 DGE 2N3053 3 RCA D40D5 3 GESY	<b>2N3253</b> BSX32 1 SGI BSX59 1 PHIN D40D4 1 GESY THC3253 1 SPR TP3253 1 SPR 2N2218A 3 PHIN 2N5321 3 RCA D40D4C 3 SPR	<b>2N3284</b> DE160 1 DGE	<b>2N3302</b> 2N2222 1 PHIN 2N4400 1 NSC DE123A 1 DGE GES2222 1 GESY THC3302 1 SPR TP3302 1 SPR BC337 3 PHIN BSS79C 3 SIEG DE123AP 3 DGE PN100 3 NSC PN2222 3 NSC THC2222 3 SPR THC4401 3 SPR TMPT2222 3 SPR	<b>2N3314</b> DE105 1 DGE
<b>2N3217</b> DE129 1 DGE	<b>2N3242</b> DE123A 1 DGE	<b>2N3254</b> 2N2221A 1 PHIN BSX20 1 SGI DE123A 1 DGE BSS79B 3 SIEG GES2221A 3 GESY THC2221A 3 SPR TMPT2221A 3 SPR TP2221A 3 SPR	<b>2N3285</b> DE160 1 DGE	<b>2N3303</b> 2N2222 1 PHIN 2N4401 1 NSC DE123A 1 DGE GES2222 1 GESY THC3303 1 SPR TP3303 1 SPR BC337 3 PHIN BSS79C 3 SIEG DE123AP 3 DGE PN100 3 NSC PN2222 3 NSC THC2222 3 SPR THC4401 3 SPR TMPT2222 3 SPR	<b>2N3315</b> DE105 1 DGE
<b>2N3218</b> DE129 1 DGE	<b>2N3243</b> 2N3964 1 MOTA DE123A 1 DGE 2N5087 3 NSC BCY71 3 PHIN THC3964 3 SPR	<b>2N3255</b> SDT8106 1 SOD SDT8113 1 SOD	<b>2N3286</b> DE160 1 DGE	<b>2N3304</b> 2N4209 1 MOTA DE106 1 DGE PN3639 1 NSC DE159 3 DGE PN3640 3 NSC	<b>2N3316</b> DE105 1 DGE
<b>2N3220</b> 2N5477 1 GSE 2N5347 3 MOTA	<b>2N3244</b> 2N3905 1 GESY 2N2907 3 SGI 2N2907A 3 PHIN BCX71G 3 SIEG BSS80C 3 SIEG DE159 3 DGE THC2905 3 SPR THC3905 3 SPR TMPT3905 3 SPR TN2905 3 NSC TP2905 3 SPR	<b>2N3256</b> SDT8003 1 SOD SDT8013 1 SOD SDT8016 1 SOD SDT8302 1 SOD SDT8304 1 SOD	<b>2N3287</b> BC547 1 PHIN DE181 1 DGE SD1310 1 THCS BCX70G 3 PHIN SD1310 1 THCS BCX70G 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC547 3 SPR	<b>2N3305</b> 2N2609 3 INL 2N3331 3 IFC NSC SIX	<b>2N3317</b> DE105 1 DGE
<b>2N3221</b> 2N5477 1 GSE 2N5347 3 MOTA	<b>2N3245</b> 2N2905 1 PHIN 2N3546 1 MOTA 2N3905 1 GESY 2N2906 3 SGI 2N2907A 3 PHIN DE129 3 DGE DE159 3 DGE THC2905 3 SPR THC3905 3 SPR TMPT3905 3 SPR TN2905 3 NSC TP2905 3 SPR	<b>2N3257</b> SDT8015 1 SOD SDT8112 1 SOD	<b>2N3288</b> BC547 1 PHIN DE181 1 DGE SD1310 1 THCS BCX70G 3 PHIN SD1310 1 THCS BCX70G 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC547 3 SPR	<b>2N3306</b> 2N2218 1 PHIN 2N4401 1 NSC DE123A 1 DGE GES2221 1 GESY THC3301 1 SPR TP3301 1 SPR BC337 3 PHIN BSS79B 3 SIEG DE123AP 3 DGE GES2222 3 GESY PN2222 3 NSC THC2222 3 SPR THC4401 3 SPR TMPT2222 3 SPR	<b>2N3318</b> DE105 1 DGE
<b>2N3222</b> 2N5477 1 GSE 2N5347 3 MOTA	<b>2N3246</b> 2N3964 1 MOTA DE123A 1 DGE 2N5087 3 NSC BCY71 3 PHIN THC3964 3 SPR	<b>2N3258</b> DE71 1 DGE SDT8003 1 SOD SDT8013 1 SOD SDT8016 1 SOD SDT8302 1 SOD SDT8304 1 SOD	<b>2N3289</b> BC547 1 PHIN DE181 1 DGE SD1310 1 THCS BCX70G 3 PHIN SD1310 1 THCS BCX70G 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC547 3 SPR	<b>2N3307</b> 2N2609 3 INL 2N3331 3 IFC NSC SIX	<b>2N3319</b> DE105 1 DGE
<b>2N3223</b> 2N5479 1 GSE 2N5349 3 MOTA	<b>2N3247</b> 2N3964 1 MOTA DE123A 1 DGE 2N5087 3 NSC BCY71 3 PHIN THC3964 3 SPR	<b>2N3259</b> SDT8002 1 SOD SDT8012 1 SOD SDT8015 1 SOD SDT8301 1 SOD SDT8303 1 SOD	<b>2N3290</b> BC547 1 PHIN DE181 1 DGE SD1310 1 THCS BCX70G 3 PHIN SD1310 1 THCS BCX70G 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC547 3 SPR	<b>2N3308</b> 2N2218 1 PHIN 2N4401 1 NSC DE123A 1 DGE GES2221 1 GESY THC3301 1 SPR TP3301 1 SPR BC337 3 PHIN BSS79B 3 SIEG DE123AP 3 DGE PN100 3 NSC PN2222 3 NSC THC2222 3 SPR THC4401 3 SPR TMPT2222 3 SPR	<b>2N3320</b> DE126A 1 DGE
<b>2N3224</b> 2N5415 1 RCA DE397 1 DGE BFN17 3 SIEG BFN25 3 SIEG	<b>2N3248</b> 2N2905 1 PHIN 2N3546 1 MOTA 2N3905 1 GESY 2N2906 3 SGI 2N2907A 3 PHIN DE129 3 DGE DE159 3 DGE THC2905 3 SPR THC3905 3 SPR TMPT3905 3 SPR TN2905 3 NSC TP2905 3 SPR	<b>2N3260</b> DE71 1 DGE SDT8003 1 SOD SDT8013 1 SOD SDT8016 1 SOD SDT8302 1 SOD SDT8304 1 SOD	<b>2N3291</b> BC547 1 PHIN DE181 1 DGE SD1310 1 THCS BCX70G 3 PHIN SD1310 1 THCS BCX70G 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC547 3 SPR	<b>2N3309</b> 2N2218 1 PHIN 2N4401 1 NSC DE123A 1 DGE GES2221 1 GESY THC3301 1 SPR TP3301 1 SPR BC337 3 PHIN BSS79B 3 SIEG DE123AP 3 DGE PN100 3 NSC PN2222 3 NSC THC2222 3 SPR THC4401 3 SPR TMPT2222 3 SPR	<b>2N3321</b> DE126A 1 DGE
<b>2N3225</b> 2N5415 1 RCA DE397 1 DGE BFN17 3 SIEG BFN25 3 SIEG	<b>2N3249</b> 2N3906 1 GESY 2N2907 3 SGI 2N2907A 3 PHIN BCX71G 3 SIEG BSS80C 3 SIEG DE159 3 DGE PN200 3 NSC THC3906 3 SPR TMPT3906 3 SPR	<b>2N3261</b> DE71 1 DGE SDT8003 1 SOD SDT8013 1 SOD SDT8016 1 SOD SDT8302 1 SOD SDT8304 1 SOD	<b>2N3292</b> 2N687 1 RCA BC547 1 PHIN DE181 1 DGE SD1310 1 THCS 2N1613 3 SGI 2N1711 3 PHIN 2N4400 3 NSC BCX70G 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN D40D7 3 GESY DE126 3 DGE THBC547 3 SPR THC697 3 SPR	<b>2N3310</b> 2N2222 1 PHIN 2N4400 1 NSC DE123A 1 DGE GES2221 1 GESY THC3301 1 SPR TP3301 1 SPR BC337 3 PHIN BSS79B 3 SIEG DE123AP 3 DGE PN100 3 NSC PN2222 3 NSC THC2222 3 SPR THC4401 3 SPR TMPT2222 3 SPR	<b>2N3322</b> DE126A 1 DGE
<b>2N3226</b> 2N6253 1 RCA D44C5 1 GESY 2N3055 3 WESY 2N5877 3 MOTA 2N6290 3 RCA BD239 3 RCA BU407 3 APX DE130 3 DGE SDT9210 3 SOD ST44C5 3 STI	<b>2N3250</b> 2N2905 1 PHIN 2N3905 1 GESY 2N2906 3 SGI 2N2907A 3 PHIN DE129 3 DGE DE159 3 DGE THC2905 3 SPR THC3905 3 SPR TMPT3905 3 SPR TN2905 3 NSC TP2905 3 SPR	<b>2N3262</b> DE71 1 DGE SDT8002 1 SOD SDT8012 1 SOD SDT8015 1 SOD SDT8301 1 SOD SDT8303 1 SOD	<b>2N3293</b> BC547 1 PHIN DE181 1 DGE SD1310 1 THCS BCX70G 3 PHIN SD1310 1 THCS BCX70G 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC547 3 SPR	<b>2N3311</b> 2N2222 1 PHIN 2N4400 1 NSC DE123A 1 DGE GES2221 1 GESY THC3301 1 SPR TP3301 1 SPR BC337 3 PHIN BSS79B 3 SIEG DE123AP 3 DGE PN100 3 NSC PN2222 3 NSC THC2222 3 SPR THC4401 3 SPR TMPT2222 3 SPR	<b>2N3323</b> DE126A 1 DGE
<b>2N3227</b> 2N3904 1 GESY DE123A 1 DGE 2N2221 3 SGI 2N2222A 3 PHIN BCX70G 3 SIEG BSS79C 3 SIEG DE123AP 3 DGE PN100 3 NSC THC3904 3 SPR TMPT3904 3 SPR	<b>2N3251</b> 2N2905 1 PHIN 2N3905 1 GESY 2N2906 3 SGI 2N2907A 3 PHIN DE129 3 DGE DE159 3 DGE THC2905 3 SPR THC3905 3 SPR TMPT3905 3 SPR TN2905 3 NSC TP2905 3 SPR	<b>2N3263</b> DE71 1 DGE SDT8002 1 SOD SDT8012 1 SOD SDT8015 1 SOD SDT8301 1 SOD SDT8303 1 SOD	<b>2N3294</b> BC547 1 PHIN DE181 1 DGE SD1310 1 THCS BCX70G 3 PHIN SD1310 1 THCS BCX70G 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC547 3 SPR	<b>2N3312</b> 2N2222 1 PHIN 2N4400 1 NSC DE123A 1 DGE GES2221 1 GESY THC3301 1 SPR TP3301 1 SPR BC337 3 PHIN BSS79B 3 SIEG DE123AP 3 DGE PN100 3 NSC PN2222 3 NSC THC2222 3 SPR THC4401 3 SPR TMPT2222 3 SPR	<b>2N3324</b> DE126A 1 DGE
<b>2N3228</b> 2N6253 1 RCA D44C5 1 GESY 2N3055 3 WESY 2N5877 3 MOTA 2N6290 3 RCA BD239 3 RCA BU407 3 APX DE130 3 DGE SDT9210 3 SOD ST44C5 3 STI	<b>2N3252</b> 2N2905 1 PHIN 2N3905 1 GESY 2N2906 3 SGI 2N2907A 3 PHIN DE129 3 DGE DE159 3 DGE THC2905 3 SPR THC3905 3 SPR TMPT3905 3 SPR TN2905 3 NSC TP2905 3 SPR	<b>2N3264</b> DE71 1 DGE SDT8002 1 SOD SDT8012 1 SOD SDT8015 1 SOD SDT8301 1 SOD SDT8303 1 SOD	<b>2N3295</b> BC547 1 PHIN DE181 1 DGE SD1310 1 THCS BCX70G 3 PHIN SD1310 1 THCS BCX70G 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC547 3 SPR	<b>2N3313</b> 2N2222 1 PHIN 2N4400 1 NSC DE123A 1 DGE GES2221 1 GESY THC3301 1 SPR TP3301 1 SPR BC337 3 PHIN BSS79B 3 SIEG DE123AP 3 DGE PN100 3 NSC PN2222 3 NSC THC2222 3 SPR THC4401 3 SPR TMPT2222 3 SPR	<b>2N3325</b> DE126A 1 DGE
<b>2N3229</b> D42C7 1 GESY 2N6292 3 RCA MDS27 3 MOTA	<b>2N3253</b> 2N2905 1 PHIN 2N3905 1 GESY 2N2906 3 SGI 2N2907A 3 PHIN DE129 3 DGE DE159 3 DGE THC2905 3 SPR THC3905 3 SPR TMPT3905 3 SPR TN2905 3 NSC TP2905 3 SPR	<b>2N3265</b> DE71 1 DGE SDT8002 1 SOD SDT8012 1 SOD SDT8015 1 SOD SDT8301 1 SOD SDT8303 1 SOD	<b>2N3296</b> BC547 1 PHIN DE181 1 DGE SD1310 1 THCS BCX70G 3 PHIN SD1310 1 THCS BCX70G 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC547 3 SPR	<b>2N3314</b> 2N2222 1 PHIN 2N4400 1 NSC DE123A 1 DGE GES2221 1 GESY THC3301 1 SPR TP3301 1 SPR BC337 3 PHIN BSS79B 3 SIEG DE123AP 3 DGE PN100 3 NSC PN2222 3 NSC THC2222 3 SPR THC4401 3 SPR TMPT2222 3 SPR	<b>2N3326</b> DE126A 1 DGE
<b>2N3230</b> 2N5477 1 GSE 2N5347 3 MOTA	<b>2N3254</b> 2N2905 1 PHIN 2N3905 1 GESY 2N2906 3 SGI 2N2907A 3 PHIN DE129 3 DGE DE159 3 DGE THC2905 3 SPR THC3905 3 SPR TMPT3905 3 SPR TN2905 3 NSC TP2905 3 SPR	<b>2N3266</b> DE71 1 DGE SDT8002 1 SOD SDT8012 1 SOD SDT8015 1 SOD SDT8301 1 SOD SDT8303 1 SOD	<b>2N3297</b> BC547 1 PHIN DE181 1 DGE SD1310 1 THCS BCX70G 3 PHIN SD1310 1 THCS BCX70G 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC547 3 SPR	<b>2N3315</b> 2N2222 1 PHIN 2N4400 1 NSC DE123A 1 DGE GES2221 1 GESY THC3301 1 SPR TP3301 1 SPR BC337 3 PHIN BSS79B 3 SIEG DE123AP 3 DGE PN100 3 NSC PN2222 3 NSC THC2222 3 SPR THC4401 3 SPR TMPT2222 3 SPR	<b>2N3327</b> DE126A 1 DGE
<b>2N3231</b> 2N5477 1 GSE 2N5347 3 MOTA	<b>2N3255</b> 2N2905 1 PHIN 2N3905 1 GESY 2N2906 3 SGI 2N2907A 3 PHIN DE129 3 DGE DE159 3 DGE THC2905 3 SPR THC3905 3 SPR TMPT3905 3 SPR TN2905 3 NSC TP2905 3 SPR	<b>2N3267</b> DE71 1 DGE SDT8002 1 SOD SDT8012 1 SOD SDT8015 1 SOD SDT8301 1 SOD SDT8303 1 SOD	<b>2N3298</b> BC547 1 PHIN DE181 1 DGE SD1310 1 THCS BCX70G 3 PHIN SD1310 1 THCS BCX70G 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC547 3 SPR	<b>2N3316</b> 2N2222 1 PHIN 2N4400 1 NSC DE123A 1 DGE GES2221 1 GESY THC3301 1 SPR TP3301 1 SPR BC337 3 PHIN BSS79B 3 SIEG DE123AP 3 DGE PN100 3 NSC PN2222 3 NSC THC2222 3 SPR THC4401 3 SPR TMPT2222 3 SPR	<b>2N3328</b> DE126A 1 DGE
<b>2N3232</b> 2N5479 1 GSE 2N5349 3 MOTA	<b>2N3256</b> 2N2905 1 PHIN 2N3905 1 GESY 2N2906 3 SGI 2N2907A 3 PHIN DE129 3 DGE DE159 3 DGE THC2905 3 SPR THC3905 3 SPR TMPT3905 3 SPR TN2905 3 NSC TP2905 3 SPR	<b>2N3268</b> DE71 1 DGE SDT8002 1 SOD SDT8012 1 SOD SDT8015 1 SOD SDT8301 1 SOD SDT8303 1 SOD	<b>2N3299</b> BC547 1 PHIN DE181 1 DGE SD1310 1 THCS BCX70G 3 PHIN SD1310 1 THCS BCX70G 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC547 3 SPR	<b>2N3317</b> 2N2222 1 PHIN 2N4400 1 NSC DE123A 1 DGE GES2221 1 GESY THC3301 1 SPR TP3301 1 SPR BC337 3 PHIN BSS79B 3 SIEG DE123AP 3 DGE PN100 3 NSC PN2222 3 NSC THC2222 3 SPR THC4401 3 SPR TMPT2222 3 SPR	<b>2N3329</b> DE126A 1 DGE
<b>2N3233</b> 2N5415 1 RCA DE397 1 DGE BFN17 3 SIEG BFN25 3 SIEG	<b>2N3257</b> 2N2905 1 PHIN 2N3905 1 GESY 2N2906 3 SGI 2N2907A 3 PHIN DE129 3 DGE DE159 3 DGE THC2905 3 SPR THC3905 3 SPR TMPT3905 3 SPR TN2905 3 NSC TP2905 3 SPR	<b>2N3269</b> DE71 1 DGE SDT8002 1 SOD SDT8012 1 SOD SDT8015 1 SOD SDT8301 1 SOD SDT8303 1 SOD	<b>2N3300</b> BC547 1 PHIN DE181 1 DGE SD1310 1 THCS BCX70G 3 PHIN SD1310 1 THCS BCX70G 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC547 3 SPR	<b>2N3318</b> 2N2222 1 PHIN 2N4400 1 NSC DE123A 1 DGE GES2221 1 GESY THC3301 1 SPR TP3301 1 SPR BC337 3 PHIN BSS79B 3 SIEG DE123AP 3 DGE PN100 3 NSC PN2222 3 NSC THC2222 3 SPR THC4401 3 SPR TMPT2222 3 SPR	<b>2N3330</b> DE126A 1 DGE
<b>2N3234</b> 2N5477 1 GSE 2N5347 3 MOTA	<b>2N3258</b> 2N2905 1 PHIN 2N3905 1 GESY 2N2906 3 SGI 2N2907A 3 PHIN DE129 3 DGE DE159 3 DGE THC2905 3 SPR THC3905 3 SPR TMPT3905 3 SPR TN2905 3 NSC TP2905 3 SPR	<b>2N3270</b> DE71 1 DGE SDT8002 1 SOD SDT8012 1 SOD SDT8015 1 SOD SDT8301 1 SOD SDT8303 1 SOD	<b>2N3301</b> BC547 1 PHIN DE181 1 DGE SD1310 1 THCS BCX70G 3 PHIN SD1310 1 THCS BCX70G 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC547 3 SPR	<b>2N3319</b> 2N2222 1 PHIN 2N4400 1 NSC DE123A 1 DGE GES2221 1 GESY THC3301 1 SPR TP3301 1 SPR BC337 3	