

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

SEE DN49 NOTICE LETTER FOR APPLICABLE TERMS, CONDITIONS AND CODE DEFINITIONS FOR THESE DISCONTINUED PRODUCTS.

REFER TO PHILIPS WEB-SITE "<http://www.semiconductors.philips.com/eol>" FOR ADDED INFORMATION.

TYPE CODE:

SOURCE CODE:

AVAILABILITY CODE:

T = Type number fully withdrawn

C = Customer specific product

1 = Non-availability. No last time buy possible

N = Part type packing option only withdrawn

M = Multiple source product

2 = Limited availability (check with your usual sales contact)

S = Sole source product

3 = Standard availability

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments
1	1N4448/AT	High-speed diode	934008420113	T	C	3	31-mrt-04	30-jun-04	Philips: 1N4448	Standard Discontinuation. See Replacement
2	1N4448/AT	High-speed diode	934008420133	T	C	3	31-mrt-04	30-jun-04	Philips: 1N4448	Standard Discontinuation. See Replacement
3	1N5059	Controlled avalanche rectifier	933076440113	N	M	3	31-dec-03	30-jun-04	See Comments for Replacement Part 12nc	Same basic part available with 12nc 933076440116
4	1N5059	Controlled avalanche rectifier	933076440133	N	M	3	31-dec-03	30-jun-04	See Comments for Replacement Part 12nc	Same basic part available with 12nc 933076440163
5	1N5061	Controlled avalanche rectifier	933206080113	N	M	3	31-dec-03	30-jun-04	See Comments for Replacement Part 12nc	Same basic part available with 12nc 933206080133
6	1N5817	Schottky barrier diode	934001190113	T	M	2	30-dec-03	30-mrt-04	various competitors for 1N5817	Limited Availability.
7	1N5817	Schottky barrier diode	934001190133	T	M	2	30-dec-03	30-mrt-04	various competitors for 1N5817	Limited Availability.
8	1N5818	Schottky barrier diode	934001200113	T	M	2	30-dec-03	30-mrt-04	various competitors for 1N5817	Limited Availability.
9	1N5818	Schottky barrier diode	934001200133	T	M	2	30-dec-03	30-mrt-04	various competitors for 1N5817	Limited Availability.
10	1N5819	Schottky barrier diode	934001210113	T	M	2	30-dec-03	30-mrt-04	various competitors for 1N5817	Limited Availability.
11	1N5819	Schottky barrier diode	934001210133	T	M	2	30-dec-03	30-mrt-04	various competitors for 1N5817	Limited Availability.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments
12	1N914									
		High-speed diode	933059950113	T	M	3	31-dec-03	30-jun-04	Philips: 1N914B	Standard discontinuation. See Replacemen
13	1N914									
		High-speed diode	933059950133	T	M	3	31-dec-03	30-jun-04	Philips: 1N914B	Standard discontinuation. See Replacemen
14	1N914									
		High-speed diode	933059950143	T	M	3	31-dec-03	30-jun-04	Philips: 1N914B	Standard discontinuation. See Replacemen
15	1N914A									
		SWITCHING DIODES	933076740113	T	M	3	31-dec-03	30-jun-04	Philips: 1N914B	Standard discontinuation. See Replacemen
16	1N914A									
		SWITCHING DIODES	933076740133	T	M	3	31-dec-03	30-jun-04	Philips: 1N914B	Standard discontinuation. See Replacemen
17	1N914A									
		SWITCHING DIODES	933076740143	T	M	3	31-dec-03	30-jun-04	Philips: 1N914B	Standard discontinuation. See Replacemen
18	74HC9323D	74HC9323 D								
		HC/HCT	935236160112	T	S	2	30-sep-03	31-dec-03	None	Limited Availability. Consult Marketing
19	74HC9323D	74HC9323 D								
		HC/HCT	935236160118	T	S	2	30-sep-03	31-dec-03	None	Limited Availability. Consult Marketing
20	74HCT1284D	74HCT1284 D								
		LVC	935178770112	T	M	2	30-sep-03	31-dec-03	PDI1284P11DL	Limited Availability. See Replacement
21	74HCT1284D	74HCT1284 D								
		LVC	935178770118	T	M	2	30-sep-03	31-dec-03	PDI1284P11DL	Limited Availability. See Replacement
22	74HCT1284DB	74HCT1284 DB								
		LVC	935178790112	T	M	2	30-sep-03	31-dec-03	PDI1284P11DL	Limited Availability. See Replacement
23	74HCT1284DB	74HCT1284 DB								
		LVC	935178790118	T	M	2	30-sep-03	31-dec-03	PDI1284P11DL	Limited Availability. See Replacement
24	74HCT1284PW	7HCT1284PW DH								
		LVC	935202360112	T	M	2	30-sep-03	31-dec-03	PDI1284P11DGG	Limited Availability. See Replacement
25	74HCT1284PW	7HCT1284PW DH								
		LVC	935202360118	T	M	2	30-sep-03	31-dec-03	PDI1284P11DGG	Limited Availability. See Replacement
26	74HCT9323D	74HCT9323 D								
		HC/HCT	935236170112	T	S	2	30-sep-03	31-dec-03	None	Limited Availability. Consult Marketing
27	74HCT9323D	74HCT9323 D								
		HC/HCT	935236170118	T	S	2	30-sep-03	31-dec-03	None	Limited Availability. Consult Marketing
28	74LV888DL	74LV888 DL								
		LV/HC-MOS	935181550112	T	S	2	30-sep-03	31-dec-03	None	Limited Availability. Consult Marketing
29	74LV888DL	74LV888 DL								
		LV/HC-MOS	935181550118	T	S	2	30-sep-03	31-dec-03	None	Limited Availability. Consult Marketing
30	AU5783D	AU5783 D								
		J1850/VPW TRANSCEIVER + SCF	935263974112	T	M	3	31-dec-03	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
31	AU5783D	AU5783 D								
		J1850/VPW TRANSCEIVER + SCF	935263974118	T	M	3	31-dec-03	30-jun-04	None noted	Standard Discontinuation. Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments
32	BAQ800	AM PIN diode	934050600113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
33	BAQ800	AM PIN diode	934050600133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
34	BAS21/AT	General purpose diode	933930150215	T	C	3	31-mrt-04	30-jun-04	Philips: BAS21	Standard Discontinuation. See Replacement
35	BAS21/AT	General purpose diode	933930150235	T	C	3	31-mrt-04	30-jun-04	Philips: BAS21	Standard Discontinuation. See Replacement
36	BAS35/AT	Gen.purp.contr.avalanche double d.	933876260215	T	C	3	31-mrt-04	30-jun-04	Philips: BAS35	Standard Discontinuation. See Replacement
37	BAS35/AT	Gen.purp.contr.avalanche double d.	933876260235	T	C	3	31-mrt-04	30-jun-04	Philips: BAS35	Standard Discontinuation. See Replacement
38	BAT54A/AT	Schottky barrier (double) diode	934020500215	T	C	3	31-mrt-04	30-jun-04	Philips: BAT54A	Standard Discontinuation. See Replacement
39	BAT54C/AT	Schottky barrier (double) diode	934020510215	T	C	3	31-mrt-04	30-jun-04	Philips: BAT54C	Standard Discontinuation. See Replacement
40	BAT54S/AT	Schottky barrier (double) diode	934020520215	T	C	3	31-mrt-04	30-jun-04	Philips: BAT54S	Standard Discontinuation. See Replacement
41	BAV23/FD	General purpose double diode	934023280215	T	C	3	31-mrt-04	30-jun-04	Philips: BAV23	Standard Discontinuation. See Replacement
42	BAV23/FD	General purpose double diode	934023280235	T	C	3	31-mrt-04	30-jun-04	Philips: BAV23	Standard Discontinuation. See Replacement
43	BB182B	VHF VARICAP	934055721115	T	M	3	31-dec-03	30-jun-04	BB182	Standard Discontinuation. See Replacement
44	BB182B	VHF VARICAP	934055721335	T	M	3	31-dec-03	30-jun-04	BB182	Standard Discontinuation. See Replacement
45	BB190	VCO VARICAP	934056324115	T	M	3	31-dec-03	30-jun-04	BB149A	Standard Discontinuation. See Replacement
46	BFG410W/CA	NPN 22 GHz wideband transistor	934056612115	T	M	3	31-dec-03	30-jun-04	BFG410W	Standard Discontinuation. See Replacement
47	BFG590W	NPN 5 GHz wideband transistor	934032460115	T	M	3	31-dec-03	30-jun-04	BFG590W/X	Standard Discontinuation. See Replacement
48	BFG67/XR	NPN 8 GHz wideband transistor	934009610215	T	M	3	31-dec-03	30-jun-04	BFG67	Standard Discontinuation. See Replacement
49	BLS3135-10I	RF POWER TRANSISTORS	934057108112	T	C	3	31-mrt-04	30-jun-04	BLS3135-10	Standard Discontinuation. See Replacement
50	BSH203	P-channel enhancem. mode MOS trans.	934054719235	N	M	3	31-dec-03	30-jun-04	See Comments for Replacement Part 12nc	Same part available with 12nc 934054719215
51	BUK582-100A	PowerMOS transistor Logic level FET	934023940135	T	M	3	31-dec-03	30-jun-04	None	Standard Discontinuation. Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments
52	BUK7277-55	TrenchMOS transistor	934054957118	T	M	1	30-jun-03	30-jun-03	BUK7277-55A	Non-manufacturable. See Replacement
53	BUK7620-55	TrenchMOS transistor	934050440118	T	M	1	30-jun-03	30-jun-03	BUK7620-55A	Non-manufacturable. See Replacement
54	BUK92150-55	TrenchMOS transistor	934054960118	T	M	3	31-dec-03	30-jun-04	BUK92150-55A	Standard Discontinuation. See Replacement
55	BYD123	Controlled avalanche rectifier	934055290163	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
56	BYD13G/EB	Controlled avalanche rectifier	934038810113	T	C	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
57	BYD13J	Controlled avalanche rectifier	933737750113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
58	BYD13J	Controlled avalanche rectifier	933737750133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
59	BYD13K	Controlled avalanche rectifier	933737760113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
60	BYD13K	Controlled avalanche rectifier	933737760133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
61	BYD13M	Controlled avalanche rectifier	933737770113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
62	BYD13M	Controlled avalanche rectifier	933737770133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
63	BYD13M/EB	Controlled avalanche rectifier	934038820113	T	C	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
64	BYD143	Controlled avalanche rectifier	934055291163	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
65	BYD163	Controlled avalanche rectifier	934055292163	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
66	BYD33D	Fast soft rec.contr.avalanche rect.	933723400113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
67	BYD33D	Fast soft rec.contr.avalanche rect.	933723400133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
68	BYD33G	Fast soft rec.contr.avalanche rect.	933723410113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
69	BYD33G	Fast soft rec.contr.avalanche rect.	933723410133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
70	BYD33G	Fast soft rec.contr.avalanche rect.	933723410163	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
71	BYD33J	Fast soft rec.contr.avalanche rect.	933723420113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments
72	BYD33J	Fast soft rec.contr.avalanche rect.	933723420133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
73	BYD33J	Fast soft rec.contr.avalanche rect.	933723420163	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
74	BYD33J/EB	Fast soft rec.contr.avalanche rect.	934038840113	T	C	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
75	BYD33M	Fast soft rec.contr.avalanche rect.	933741030113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
76	BYD33M	Fast soft rec.contr.avalanche rect.	933741030133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
77	BYD33M	Fast soft rec.contr.avalanche rect.	933741030163	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
78	BYD33M/26	Fast soft rec.contr.avalanche rect.	934054933112	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
79	BYD33M/EB	Fast soft rec.contr.avalanche rect.	934038850113	T	C	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
80	BYD33M/EB	Fast soft rec.contr.avalanche rect.	934038850133	T	C	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
81	BYD33V	Fast soft rec.contr.avalanche rect.	934031700113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
82	BYD33V	Fast soft rec.contr.avalanche rect.	934031700133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
83	BYD33V	Fast soft rec.contr.avalanche rect.	934031700163	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
84	BYD33V/EB	Fast soft rec.contr.avalanche rect.	934038860113	T	C	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
85	BYD33V/EB	Fast soft rec.contr.avalanche rect.	934038860133	T	C	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
86	BYD43-20	Fast soft recovery rectifier	934015540113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
87	BYD43-20	Fast soft recovery rectifier	934015540133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
88	BYD43V	Fast soft recovery rectifier	934031720113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
89	BYD43V	Fast soft recovery rectifier	934031720133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
90	BYD53G	Fast soft rec.contr.avalanche rect.	934054837113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
91	BYD53G	Fast soft rec.contr.avalanche rect.	934054837163	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments
92	BYD53J	Fast soft rec.contr.avalanche rect.	934054836113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
93	BYD53J	Fast soft rec.contr.avalanche rect.	934054836163	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
94	BYD53K	Fast soft rec.contr.avalanche rect.	934054835113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
95	BYD53K	Fast soft rec.contr.avalanche rect.	934054835163	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
96	BYD53M	Fast soft rec.contr.avalanche rect.	934054834113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
97	BYD53M	Fast soft rec.contr.avalanche rect.	934054834163	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
98	BYD53V	Fast soft rec.contr.avalanche rect.	934031740113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
99	BYD53V	Fast soft rec.contr.avalanche rect.	934031740133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
100	BYD63	Ripple blocking diode	934041340113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
101	BYD63	Ripple blocking diode	934041340163	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
102	BYD73A	Ultra fast low-loss contr.aval.rect	933753740113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
103	BYD73A	Ultra fast low-loss contr.aval.rect	933753740133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
104	BYD73B	Ultra fast low-loss contr.aval.rect	933753750113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
105	BYD73B	Ultra fast low-loss contr.aval.rect	933753750133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
106	BYD73C	Ultra fast low-loss contr.aval.rect	933753760113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
107	BYD73C	Ultra fast low-loss contr.aval.rect	933753760133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
108	BYD73C/AT	Ultra fast low-loss contr.aval.rect	934014410113	T	C	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
109	BYD73D	Ultra fast low-loss contr.aval.rect	933753770113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
110	BYD73D	Ultra fast low-loss contr.aval.rect	933753770133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
111	BYD73G	Ultra fast low-loss contr.aval.rect	933753800113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments
112	BYD73G	Ultra fast low-loss contr.aval.rect	933753800133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
113	BYD73G	Ultra fast low-loss contr.aval.rect	933753800163	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
114	BYV10-20	Schottky barrier diode	933743250113	T	M	2	30-dec-03	30-mrt-04	Various competitors: for 1N5817	Limited Availability, See Replacement
115	BYV10-20	Schottky barrier diode	933743250133	T	M	2	30-dec-03	30-mrt-04	Various competitors: for 1N5817	Limited Availability, See Replacement
116	BYV10-30	Schottky barrier diode	933743260113	T	M	2	30-dec-03	30-mrt-04	Various competitors: for 1N5818	Limited Availability, See Replacement
117	BYV10-30	Schottky barrier diode	933743260133	T	M	2	30-dec-03	30-mrt-04	Various competitors; for 1N5818	Limited Availability, See Replacement
118	BYV10-40	Schottky barrier diode	933743270113	T	M	2	30-dec-03	30-mrt-04	Various competitors: for 1N5819	Limited Availability, See Replacement
119	BYV10-40	Schottky barrier diode	933743270133	T	M	2	30-dec-03	30-mrt-04	Various competitors: for 1N5819	Limited Availability, See Replacement
120	BYV1100	EPI/LLUF 100V RECTIFIERS	934055440113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
121	BYV27-50	Ultra fast low-loss contr.aval.rect	933543490113	N	M	3	31-dec-03	30-jun-04	See Comments for Replacment Part 12nc	Same part with 12nc 933543490133 available
122	BYV28-400	Ultra fast low-loss contr.aval.rect	934036720113	N	M	3	31-dec-03	30-jun-04	See Comments for Replacment Part 12nc	Same part available with 12nc 934036720133
123	BYV28-50	Ultra fast low-loss contr.aval.rect	933553580113	N	M	3	31-dec-03	30-jun-04	See Comments for Replacment Part 12nc	Same part available with 12nc 933553580133
124	BYX133GL	HIGH VOLTAGE RECTIFIERS	934054743113	T	M	3	31-dec-03	30-jun-04	BYX134GL	Standard Discontinuation. See Replacement
125	BZA109	9-Fold ESD transient suppressor	934042830118	T	S	2	31-mrt-04	30-jun-04	None noted	Limited Availability. Consult Marketing
126	BZA109TE	ENHANCED PERFORMANCE ZENER ARRAY	934056987118	T	M	2	31-dec-03	30-mrt-04	ST: ESDA6V1FU6	Limited Availability, See Replacement
127	BZA109TS	9-Fold ESD transient suppressor	934054707118	T	M	2	31-dec-03	30-mrt-04	ST: ESDA6V1FU6	Limited Availability, See Replacement
128	BZD23-C12	Voltage regulator diode	933753410133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
129	BZD23-C15	Voltage regulator diode	933753430133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
130	BZD23-C150	Voltage regulator diode	933753670133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
131	BZD23-C180	Voltage regulator diode	933753690133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments
132	BZD23-C200	Voltage regulator diode	933753700133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
133	BZD23-C22	Voltage regulator diode	933753470133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
134	BZD23-C220	Voltage regulator diode	933753710133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
135	BZD23-C24	Voltage regulator diode	933753480133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
136	BZD23-C240	Voltage regulator diode	933753720133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
137	BZD23-C270	Voltage regulator diode	933753730133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
138	BZD23-C36	Voltage regulator diode	933753520113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
139	BZD23-C47	Voltage regulator diode	933753550133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
140	BZD23-C62	Voltage regulator diode	933753580133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
141	BZD23-C68	Voltage regulator diode	933753590133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
142	BZD23-C91	Voltage regulator diode	933753620113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
143	BZX284-C10/FD	Voltage regulator diode	934051180115	T	C	3	31-mrt-04	30-jun-04	Philips: BZX284-C10	Standard Discontinuation. See Replacement
144	BZX284-C18/FD	Voltage regulator diode	934054879115	T	C	3	31-mrt-04	30-jun-04	Philips: BZX284-C18	Standard Discontinuation. See Replacement
145	BZX284-C27/FD	Voltage regulator diode	934054880115	T	C	3	31-mrt-04	30-jun-04	Philips: BZX284-C27	Standard Discontinuation. See Replacement
146	BZX284-C2V4/FD	Voltage regulator diode	934054876115	T	C	3	31-mrt-04	30-jun-04	Philips: BZX284-C2V4	Standard Discontinuation. See Replacement
147	BZX284-C47/FD	Voltage regulator diode	934055329115	T	C	3	31-mrt-04	30-jun-04	Philips: BZX284-C47	Standard Discontinuation. See Replacement
148	BZX284-C5V1/FD	Voltage regulator diode	934054877115	T	C	3	31-mrt-04	30-jun-04	Philips: BZX284-C5V1	Standard Discontinuation. See Replacement
149	BZX284-C6V8/FD	Voltage regulator diode	934055370115	T	C	3	31-mrt-04	30-jun-04	Philips: BZX284-C6V8	Standard Discontinuation. See Replacement
150	BZX284-C7V5/FD	Voltage regulator diode	934055328115	T	C	3	31-mrt-04	30-jun-04	Philips: BZX284-C7V5	Standard Discontinuation. See Replacement
151	BZX284-C9V1/FD	Voltage regulator diode	934054878115	T	C	3	31-mrt-04	30-jun-04	Philips: BZX284-C9V1	Standard Discontinuation. See Replacement

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
152	BZX84-B10/AT	Voltage regulator diode	934021290215	T	C	3	31-mrt-04	30-jun-04	Philips: BZX84-B10	Standard Discontinuation. See Replacement	
153	BZX84-B5V1/AT	Voltage regulator diode	934039480235	T	C	3	31-mrt-04	30-jun-04	Philips: BZX84-B5V1	Standard Discontinuation. See Replacement	
154	BZX84-B8V2/AT	Voltage regulator diode	933890350215	T	C	3	31-mrt-04	30-jun-04	Philips: BZX84-B8V2	Standard Discontinuation. See Replacement	
155	BZX84-C13/AT	Voltage regulator diode	934022140215	T	C	3	31-mrt-04	30-jun-04	Philips: BZX84-C13	Standard Discontinuation. See Replacement	
156	BZX84-C3V3/AT	Voltage regulator diode	934021620185	T	C	3	31-mrt-04	30-jun-04	Philips: BZX84-C3V3	Standard Discontinuation. See Replacement	
157	BZX84-C3V3/AT	Voltage regulator diode	934021620215	T	C	3	31-mrt-04	30-jun-04	Philips: BZX84-C3V3	Standard Discontinuation. See Replacement	
158	BZX84-C5V1/AT	Voltage regulator diode	933920480235	T	C	3	31-mrt-04	30-jun-04	Philips: BZX84-C5V1	Standard Discontinuation. See Replacement	
159	BZX84-C6V8/AT	Voltage regulator diode	933939370215	T	C	3	31-mrt-04	30-jun-04	Philips: BZX84-C6V8	Standard Discontinuation. See Replacement	
160	BZX84-C8V2/AT	Voltage regulator diode	934022680215	T	C	3	31-mrt-04	30-jun-04	Philips: BZX84-C8V2	Standard Discontinuation. See Replacement	
161	BZX84-C8V2/FD	Voltage regulator diode	934018410215	T	C	3	31-mrt-04	30-jun-04	Philips: BZX-C8V2	Standard Discontinuation. See Replacement	
162	BZX84-C8V2/FD	Voltage regulator diode	934018410235	T	C	3	31-mrt-04	30-jun-04	Philips: BZX84-C8V2	Standard Discontinuation. See Replacement	
163	CE1676D	CE1676 D	AUTO CUSTOM ASIC	935247480112	T	M	3	31-dec-03	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
164	CE1676D	CE1676 D	AUTO CUSTOM ASIC	935247480118	T	M	3	31-dec-03	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
165	CE1771BA	CE1771 BA	AUTO CUSTOM ASIC	935260948557	T	C	2	30-mrt-04	30-jun-04	None noted	Limited Availability. ATB input needs to be placed before Feb. 2004
166	CE1824D	CE1824 D	SAE/J1850/VPW TRANSCEIVER	935269563118	T	C	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. Consult Marketing
167	CGY2105TS/C1		PHILIPS MICROWAVE LIMEIL	935260957112	T	S	1	30-jun-03	30-jun-03	None	Non-manufacturable, Consult Marketing
168	CGY2105TS/C1		PHILIPS MICROWAVE LIMEIL	935260957118	T	S	1	30-jun-03	30-jun-03	None	Non-manufacturable, Consult Marketing
169	CGY2105TS/C1	CGY2105TS DB	PHILIPS MICROWAVE LIMEIL	935260957518	T	S	1	30-jun-03	30-jun-03	None	Non-manufacturable, Consult Marketing
170	CV5791BA	CV5791 BA	MCM	935264165557	T	S	2	31-mrt-04	30-jun-04	None noted	Limited Availability. Consult Marketing
171	DE1ICC0501U/Y4D		CLHW	935269795025	T	C	1	30-jun-03	30-jun-03	None	Non-Manufacturable. Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments
172	EGP10A	BASIC-TYPENR NOT USED	934056425113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
173	EGP10A	BASIC-TYPENR NOT USED	934056425133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
174	EGP10B	BASIC-TYPENR NOT USED	934056426113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
175	EGP10B	BASIC-TYPENR NOT USED	934056426133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
176	EGP10C	BASIC-TYPENR NOT USED	934056497113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
177	EGP10C	BASIC-TYPENR NOT USED	934056497133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
178	EGP10D	BASIC-TYPENR NOT USED	934056424113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
179	EGP10D	BASIC-TYPENR NOT USED	934056424133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
180	EGP10F	400V 1A ULTRAFAST RECOVERY RECT.	934056428113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
181	EGP10F	400V 1A ULTRAFAST RECOVERY RECT.	934056428133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
182	EGP10G	400V 1A ULTRAFAST RECOVERY RECT.	934056427113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
183	EGP10G	400V 1A ULTRAFAST RECOVERY RECT.	934056427133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
184	EGP10J	800V 1A ULTRAFAST RECOVERY RECT.	934056430113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
185	EGP10J	800V 1A ULTRAFAST RECOVERY RECT.	934056430133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
186	EGP10K	800V 1A ULTRAFAST RECOVERY RECT.	934056429113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
187	EGP10K	800V 1A ULTRAFAST RECOVERY RECT.	934056429133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
188	ES1A	UF	934056142115	T	M	3	31-dec-03	30-jun-04	None	Standard Discontinuation. No Replacement Available
189	FR101G	400V 1A FAST RECOVERY RECTIFIER	934056414113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
190	FR101G	400V 1A FAST RECOVERY RECTIFIER	934056414133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
191	FR102G	400V 1A FAST RECOVERY RECTIFIER	934056413113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments
192	FR102G	400V 1A FAST RECOVERY RECTIFIER	934056413133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
193	FR103G	400V 1A FAST RECOVERY RECTIFIER	934056412113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
194	FR103G	400V 1A FAST RECOVERY RECTIFIER	934056412133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
195	FR104G	400V 1A FAST RECOVERY RECTIFIER	934056411113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
196	FR104G	400V 1A FAST RECOVERY RECTIFIER	934056411133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
197	FR105G	600V 1A FAST RECOVERY RECTIFIER	934056415113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
198	FR105G	600V 1A FAST RECOVERY RECTIFIER	934056415133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
199	FR106G	1000V 1A FAST RECOVERY RECTIFIER	934056417113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
200	FR106G	1000V 1A FAST RECOVERY RECTIFIER	934056417133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
201	FR107G	1000V 1A FAST RECOVERY RECTIFIER	934056416113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
202	FR107G	1000V 1A FAST RECOVERY RECTIFIER	934056416133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no possible last time buy. Consult Marketing
203	GTL16612DGG	GTL16612 DGG 18BIT UNIVERSAL GTL/ALVT XLTOR	935264009112	T	M	3	31-dec-03	30-jun-04	Texas Instruments: SN74GTLPH16612	Standard Discontinuation. Consult Marketing
204	GTL16612DGG	GTL16612 DGG 18BIT UNIVERSAL GTL/ALVT XLTOR	935264009118	T	M	3	31-dec-03	30-jun-04	Texas Instruments: GTLPH16612	Standard Discontinuation. Consult Marketing
205	GTL16612DL	GTL16612 DL 18BIT UNIVERSAL GTL	935264022112	T	M	3	31-dec-03	30-jun-04	Texas Instruments: SN74GTL16612DL	Standard Discontinuation. Consult Marketing
206	GTL16612DL	GTL16612 DL 18BIT UNIVERSAL GTL	935264022118	T	M	3	31-dec-03	30-jun-04	Texas Instruments: SN74GTL16612DLR	Standard Discontinuation. Consult Marketing
207	GTL2004PW	GTL2004PW DH QUAD LATCHED GTL TO TTL XLATOR	935263812112	T	S	3	31-mrt-04	30-jun-04	None	Standard Discontinuation. Consult Marketing
208	GTL2004PW	GTL2004PW DH QUAD LATCHED GTL TO TTL XLATOR	935263812118	T	S	3	31-mrt-04	30-jun-04	None	Standard Discontinuation. Consult Marketing
209	GTL2021DGG	GTL2021 DGG 32BIT GTL BUS SWITCH	935266675112	T	M	3	31-dec-03	30-jun-04	Pericom: PI5C32201A56	Standard Discontinuation. Consult Marketing
210	GTL2021DGG	GTL2021 DGG 32BIT GTL BUS SWITCH	935266675118	T	M	3	31-dec-03	30-jun-04	Pericom: PI5C32201A56	Standard Discontinuation. Consult Marketing
211	GTL2022DGG	GTL2022 DGG 32BIT GTL BUS SWITCH	935267154112	T	M	3	31-dec-03	30-jun-04	Pericom: PI5C32202A56	Standard Discontinuation. Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
212	GTL2022DGG	GTL2022 DGG	32BIT GTL BUS SWITCH	935267154118	T	M	3	31-dec-03	30-jun-04	Pericom: PI5C32202A56	Standard Discontinuation. Consult Marketing
213	GTL2023DGG	GTL2023 DGG	32BIT GTL BUS SWITCH	935266801112	T	M	3	31-dec-03	30-jun-04	Pericom: PI5C32203A56	Standard Discontinuation. Consult Marketing
214	GTL2023DGG	GTL2023 DGG	32BIT GTL BUS SWITCH	935266801118	T	M	3	31-dec-03	30-jun-04	Pericom: PI5C32203A56	Standard Discontinuation. Consult Marketing
215	GTLPH16612DGG	GTLPH16612DGG	GTLPH16612DGG	935270496112	T	M	3	31-dec-03	30-jun-04	Texas Instruments: SN74GTLPH16612DGG	Standard Discontinuation. Consult Marketing
216	GTLPH16612DGG	GTLPH16612DGG	GTLPH16612DGG	935270496118	T	M	3	31-dec-03	30-jun-04	Texas Instruments: SN74GTLPH16612DGG	Standard Discontinuation. Consult Marketing
217	GTLPH16612DL	GTLPH16612DL	GTLPH16612DL	935270497112	T	M	3	31-dec-03	30-jun-04	Texas Instruments: SN74GTLPH16612DL	Standard Discontinuation. Consult Marketing
218	GTLPH16612DL	GTLPH16612DL	GTLPH16612DL	935270497118	T	M	3	31-dec-03	30-jun-04	Texas Instruments: SN74GTLPH16612DL	Standard Discontinuation. Consult Marketing
219	HER101G	HER101G	300V 1A ULTRAFAST RECOVERY RECT.	934056432113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
220	HER101G	HER101G	300V 1A ULTRAFAST RECOVERY RECT.	934056432133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
221	HER102G	HER102G	300V 1A ULTRAFAST RECOVERY RECT.	934056433113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
222	HER102G	HER102G	300V 1A ULTRAFAST RECOVERY RECT.	934056433133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
223	HER103G	HER103G	300V 1A ULTRAFAST RECOVERY RECT.	934056434113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
224	HER103G	HER103G	300V 1A ULTRAFAST RECOVERY RECT.	934056434133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
225	HER104G	HER104G	300V 1A ULTRAFAST RECOVERY RECT.	934056431113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
226	HER104G	HER104G	300V 1A ULTRAFAST RECOVERY RECT.	934056431133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
227	HER105G	HER105G	400V 1A ULTRAFAST RECOVERY RECT.	934056435113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
228	HER105G	HER105G	400V 1A ULTRAFAST RECOVERY RECT.	934056435133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
229	HER106G	HER106G	1000V 1A ULTRAFAST RECOVERY RECT.	934056437113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
230	HER106G	HER106G	1000V 1A ULTRAFAST RECOVERY RECT.	934056437133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
231	HER107G	HER107G	1000V 1A ULTRAFAST RECOVERY RECT.	934056438113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
232	HER107G	1000V 1A ULTRAFAST RECOVERY RECT.	934056438133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing	
233	HER108G	1000V 1A ULTRAFAST RECOVERY RECT.	934056436113	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing	
234	HER108G	1000V 1A ULTRAFAST RECOVERY RECT.	934056436133	T	M	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing	
235	MF11CS5005U/V5D	CLHW	935267506025	N	M	1	30-jun-03	30-jun-03	MF11CS5005U/V5D	See replacement part 12nc 9352767506006	
236	MFCM200/FAA	MFCM200FAA MR	CL READER SYSTEMS	935237400122	T	S	3	31-mrt-04	30-jun-04	MFRC50001T/0FE	Standard Discontinuation. See Replacement 12nc 935268039111.
237	MFCM500/FDA	MFCM500FDA MR	CL READER SYSTEMS	935234190122	T	S	3	31-mrt-04	30-jun-04	MFRC50001T/0FE	Standard Discontinuation. See Replacement 12nc 935268039111.
238	MFCM500/FDA/K		CL READER SYSTEMS	935248970122	T	S	3	31-mrt-04	30-jun-04	MFRC50001T/0FE	Standard Discontinuation. See Replacement 12nc 935268039112.
239	MFRC15002A/02F	MRC152A02F M	CL READER SYSTEMS	935270255112	T	S	3	31-mrt-04	30-jun-04	MFRC50001T/0FE	Standard End of Life. See Replacement 12nc 935268039112.
240	MFRD260/AKA	MFRD260AKA MR	CL READER SYSTEMS	935234290122	T	S	3	31-mrt-04	30-jun-04	MFRC50001T/0FE	Standard Discontinuation. See Replacement 12nc 935268039111.
241	MFRD560/ADA	MFRD560ADA M	CL READER SYSTEMS	935234200122	T	S	3	31-mrt-04	30-jun-04	MFRC50001T/0FE	Standard Discontinuation. See Replacement 12nc 935268039111.
242	MFRD560/BDA	MFRD560BDA M	CL READER SYSTEMS	935234210122	T	S	3	31-mrt-04	30-jun-04	MFRC50001T/0FE	Standard Discontinuation. See Replacement 12nc 935268039111.
243	MFRM560/ADA	MFRM560ADA MR	CL READER SYSTEMS	935234240122	T	S	3	31-mrt-04	30-jun-04	MFRC50001T/0FE	Standard Discontinuation. See Replacement 12nc 935268039111.
244	MPSH10		NPN 1 GHz gen. purp. switching tr.	934011870126	T	M	3	31-dec-03	30-jun-04	None	Standard Discontinuation. Consult Marketing
245	MX1011B700Y		NPN sil.planar epit.microw.power tr	934016870114	T	M	2	31-mrt-04	30-jun-04	None noted	Limited Availability. Consult Marketing
246	OF4450		LV SCHOTTKY RECTIFIERS	934053460127	T	C	3	31-mrt-04	30-jun-04	BYV116B-25	Standard Discontinuation. PRIME TYPE IS AVAILABLE. Consult Marketing.
247	OF4454		9667	934055330127	T	C	1	30-jun-03	30-jun-03	None	No last time buy possible. Consult Marketing
248	OF4462		POWER SCHOTTKY DIODE	934055825127	T	C	1	30-jun-03	30-jun-03	PBYR2545CTE	PRIME TYPE IS AVAILABLE. Consult Marketing.
249	OF815		FAST RECTIFIERS	933797500113	T	C	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible
250	OF815		FAST RECTIFIERS	933797500133	T	C	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible
251	OM4053U/10/F2		CLOCKS AND WATCHES	935261042005	T	C	1	30-jun-03	30-jun-03	None	Non-manufacturable, Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments
252	OM4059U/5/F2	WAFER SERVICE	935267581015	T	C	1	30-jun-03	30-jun-03	None	Non-Manufacturable. Consult Marketing
253	OM4094U/10/F2	CLOCKS AND WATCHES	935261692005	T	S	2	30-mrt-04	30-jun-04	None noted	Limited Availability. Consult Marketing
254	OM4098U/10/F2	CLOCKS AND WATCHES	935261647005	T	S	2	30-mrt-04	30-jun-04	None noted	Limited Availability. Consult Marketing
255	OM4361BA/00	BLM - FLASH MCU	935271572512	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
256	OM5170AG/C2	OM5170AG BE BIPOLAR MOBILE TELECOM (CAEN)	935254660518	T	C	1	30-jun-03	30-jun-03	None	Non-manufacturable, Consult Marketing
257	OM5170AG/C2	BIPOLAR MOBILE TELECOM (CAEN)	935254660118	T	C	2	30-mrt-04	30-jun-04	None	Limited Availability. Consult Marketing
258	OM5178HL/C3/M1	BIPOLAR MOBILE TELECOM (CAEN)	935271700118	T	C	2	30-mrt-04	30-jun-04	OM5178HN	Limited Supply. See Replacement.
259	OM5178HN/C3/M1	OM5178HN	935271699118	T	C	1	30-jun-03	30-jun-03	OM5178HN/C3	Non-Manufacturable. See Replacement
260	OM6150HL/C1	OM6150HL BE PHILIPS MICROWAVE LIMEIL	935260958551	T	S	1	30-jun-03	30-jun-03	None	Non-manufacturable, Consult Marketing
261	OM6205U/2/F1	DISPLAY DRIVERS	935262222026	T	S	2	30-mrt-04	30-jun-04	None noted	Limited Availability. Consult Marketing
262	OM6206U/2/F1	OM6206U CK LCD GRAPHIC DRIVER	935262400026	N	S	2	30-mrt-04	30-jun-04	OM6206U/2/A/1	Limited Availability. Consult Marketing
263	OM6353E/2A3/2/M1	CELL. BASEBAND & BAI	935271706518	T	C	3	31-mrt-04	30-jun-04	OM6353E/2A3/2	Standard End of Life. See Replacement
264	OM6353EL/2A3/3	BAI	935269799518	T	C	3	31-mrt-04	30-jun-04	None	Standard Discontinuation. Consult Marketing
265	OM6353EL/2A3/3/M1	BAI	935271707518	T	C	3	31-mrt-04	30-jun-04	None	Standard Discontinuation. Consult Marketing
266	OM6354E/3C1/3	CELL. BASEBAND & BAI	935269537518	T	S	3	31-mrt-04	30-jun-04	None	Standard Discontinuation. Consult Marketing
267	OM6354E/3C3/3/M1	CELL. BASEBAND & BAI	935271708518	T	C	3	31-mrt-04	30-jun-04	OM6354E/3C3/3	Standard End of Life. See Replacement
268	OM6357EL/3C3/5/M1	GPRS BB&BAI	935271769518	T	C	3	31-mrt-04	30-jun-04	OM6357EL/3C3/5	Standard End of Life. See Replacement
269	ON4238	NPN BROADBAND TRANSISTORS CONT	933835290215	T	M	3	31-dec-03	31-mrt-04	None	Standard Discontinuation. Consult Marketing
270	ON4608	60V MOSFET	934012470127	T	C	3	31-mrt-04	30-jun-04	BUK7575-55A	Standard Discontinuation. See Replacement
271	ON4708	60V MOSFET	934017060127	T	C	1	30-jun-03	30-jun-03	None	No last time buy available. Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments
272	ON4959	SMPS TRANSISTORS	934041450127	T	C	1	30-jun-03	30-jun-03	None	Package discontinuation, no last time buy possible. Consult Marketing
273	ON5176	LOW VOLTAGE POWER MOS	934055659127	T	C	1	30-jun-03	30-jun-03	None	No last time buy possible. Consult Marketing
274	ON5177	LOW VOLTAGE POWER MOS	934055660127	T	C	1	30-jun-03	30-jun-03	None	No last time buy possible. Consult Marketing
275	ON5178	LOW VOLTAGE POWER MOS	934055661127	T	C	3	31-mrt-04	30-jun-04	None	Standard Discontinuation. No Replacement Part Available
276	ON5190	POWER MOSFET	934055711127	T	C	3	31-mrt-04	30-jun-04	None	Standard Discontinuation. No Replacement Part Available
277	ON5221	LIGHTING TRANSISTOR	934056326127	T	C	3	31-mrt-04	30-jun-04	None	Standard Discontinuation. No Replacement Available
278	ON5228	55V GEN 2 TRENCH	934056566118	T	C	3	31-mrt-04	30-jun-04	BUK7614-55A	Standard Discontinuation. See Replacement
279	ON5229	55V GEN 2 TRENCH	934056567118	T	C	3	31-mrt-04	30-jun-04	BUK7616-55A	Standard Discontinuation. See Replacement
280	ON5231	55V GEN 2 TRENCH	934056616127	T	C	3	31-mrt-04	30-jun-04	BUK7516-55A	Standard Discontinuation. See Replacement
281	ON5237	TRENCH GEN 2	934056849118	T	C	3	31-mrt-04	30-jun-04	BUK7611-55A	Standard Discontinuation. See Replacement
282	OP540	TRENCH	934056377005	T	C	1	30-jun-03	30-jun-03	OP540/A	Non-manufacturable. See Replacement
283	OP546	TRENCH	934056592005	T	C	1	30-jun-03	30-jun-03	OP546/A	Non-manufacturable, See Replacement
284	OP548	TRENCH	934056807005	T	C	1	30-jun-03	30-jun-03	OP548/A	Non-manufacturable, See Replacement
285	OP549	TRENCH	934056808005	T	C	1	30-jun-03	30-jun-03	OP549/A	Non-manufacturable, See Replacement
286	OQ0256HP/N3	ASIC	935263422557	T	C	2	29-aug-03	31-dec-03	None	Limited Availability. Consult Marketing
287	OQ0257HP/N2	ASIC	935221810557	T	C	2	29-aug-03	31-dec-03	None	Limited Availability. Consult Marketing
288	OQ0258HP/N2	ASIC	935221820557	T	C	2	29-aug-03	31-dec-03	None	Limited Availability. Consult Marketing
289	OQ0260HL/N3	ASIC	935263258557	T	C	2	29-aug-03	31-dec-03	None	Limited Availability. Consult Marketing
290	OQ2538HP/S1	OQ2538HP B TRANSMISSION AND ASICS	935163100551	T	S	2	30-sep-03	31-dec-03	TZA3054	Limited Availability, See Replacement
291	OQ2541BHP/C3	OQ2541BHP BE DCR STM16	935263641551	T	S	2	30-sep-03	31-dec-03	TZA3015	Limited Availability, See Replacement

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
292	OQ2541HP/C3	OQ2541HP B	TRANSMISSION AND ASICS	935198040551	T	S	2	30-sep-03	31-dec-03	TZA3015	Limited Availability. See Replacement
293	OQ8819TB/L4		ASIC	935076210115	T	C	2	29-aug-03	31-dec-03	None	Limited Availability. Consult Marketing
294	OQ8898U/T/C5		ASIC	935267551025	T	C	2	29-aug-03	31-dec-03	None	Limited Availability. Consult Marketing
295	OQ8899HL/C2		ASIC	935270562557	T	C	2	29-aug-03	31-dec-03	None	Limited Availability. Consult Marketing
296	OQ8900T/C1		ASIC	935270130118	T	C	2	29-aug-03	31-dec-03	None	Limited Availability. Consult Marketing
297	OQ8901HL/K1		ASIC	935268426557	T	C	2	29-aug-03	31-dec-03	None	Limited Availability. Consult Marketing
298	OQ9224HP/C2		TRANSMISSION AND ASICS	935240750118	T	C	2	30-jun-03	31-dec-03	None	Limited Availability. Consult Marketing
299	OQ9232H/C1		ASIC	935263259557	T	C	2	29-aug-03	31-dec-03	None	Limited Availability. Consult Marketing
300	P80C31X2BA		P80C31X2 PLCC44	935269612529	N	M	3	31-dec-03	30-jun-04	P87C31X2BA	Standard Discontinuation. See 12nc 935269612512 Packing option discontinuation. Device still available in large pack qty
301	P80C32X2BA		P80C32X2 PLCC44	935269607529	N	M	3	31-dec-03	30-jun-04	P87C32X2BA	Standard Discontinuation. See 12nc 935269607512. Packing option discontinuation. Device still available in large pack qty
302	P80C32X2FA		P80C32X2 PLCC44	935269608529	N	M	3	31-dec-03	30-jun-04	P87C32X2FA	Standard Discontinuation. See 12nc 935269608512. Packing option discontinuation. Device still available in large pack qty
303	P80C51RA+5B	P80C51RA+5 B	CMOS ROMLESS 80C***	935256640557	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
304	P80C51SFPN/CV517	CV5178 N	51 FAMILY CMOS ROM - 80C51	935264419112	T	M	3	31-dec-03	31-mrt-04	P87C52X2FN	OTP's P87C52X2FN 12nc 935269602512 Closest replacement programmed to customer code can replace ROM
305	P80C51SFPN/CV518	CV5180 N	51 FAMILY CMOS ROM - 80C51	935264522112	T	M	3	31-dec-03	31-mrt-04	P80C51SFPN/CV5194	Standard Discontinuation. See Replacement
306	P80C51SFPN/CV519		51 FAMILY CMOS ROM - 80C51	935272346112	T	S	3	31-mrt-04	30-jun-04	P87C58X2BBD	Standard Discontinuation. See 12nc 935271463557. OTP's P87C58BBD programmed to customer code can replace ROM
307	P80C528IBA/02		BLM - I2C	935222930512	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
308	P80C52SBAA/CV570	CV5703 A	51 FAMILY CMOS ROM - 80C52	935262557518	T	S	3	31-mrt-04	30-jun-04	P87C52X2BA	OTP's P87C52X2BA programmed to customer code can replace ROM. See Replacement 12nc 935269599512
309	P80C52SBAA/CV571	CV5718 A	51 FAMILY CMOS ROM - 80C52	935263904518	T	M	3	31-dec-03	30-jun-04	P87C52X2BA	Standard Discontinuation. See 12nc 935269599512 OTP's P87C52X2BA programmed to customer code can replace ROM
310	P80C52SBAA/CV576	CV5767 A	51 FAMILY CMOS ROM - 80C52	935268650518	T	S	3	31-mrt-04	30-jun-04	P87C52X2BA	OTP's P87C52X2BA programmed to customer code can replace ROM. See 12nc 935269599512.
311	P80C52SBBB/CV576	CV5760 B	51 FAMILY CMOS ROM - 80C52	935267757518	T	S	3	31-mrt-04	30-jun-04	P87C52X2BBD	OTP's P87C51X2BBD programmed to customer code can replace ROM. See 12nc 935271386157.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
312	P80C52SBPN/CV564	CV5648 N	51 FAMILY CMOS ROM - 80C52	935260714112	T	M	3	31-dec-03	30-jun-04	None noted	Standard Discontinuation. OTP's P87C52X2BN programmed to customer code can replace ROM
313	P80C52SFBB/CV572	CV5729 B	51 FAMILY CMOS ROM - 80C52	935264234518	T	M	3	31-dec-03	30-jun-04	P87C52X2FBD	Standard Discontinuation. See 12nc 935271391512 OTP's P87C52X2FBD programmed to customer code can replace ROM
314	P80C54SBBB/CV636	CV6362 B	51 FAMILY CMOS ROM - 80C54	935269869557	T	M	3	31-dec-03	30-jun-04	P87C54X2BBD	Standard Discontinuation. See 12nc 935271392157. OTP's P87C54X2BBD programmed to customer code can replace ROM
315	P80C562EFA/02		BLM - ADC	935202210512	T	S	3	31-mrt-04	30-jun-04	P80C552EFA/08	Standard Discontinuation. See Replacement
316	P80C58SBBB/CV841		51 FAMILY CMOS ROM - 80C58	935272094557	T	S	3	31-mrt-04	30-jun-04	P87C58X2BBD	Standard Discontinuation. See 12nc 935271463557. OTP's P87C58BBD programmed to customer code can replace ROM
317	P80C58SFBB/CV841	CV8414 B	51 FAMILY CMOS ROM - 80C58	935264222557	T	M	3	31-dec-03	30-jun-04	P87C58X2FA	Standard Discontinuation. See 12nc 935270376512 OTP's P87C58X2FA programmed to customer code can replace ROM
318	P80C58X2BBD/CV841		P80C58X2BBD	935271978157	T	S	3	31-mrt-04	30-jun-04	P87C58X2BBD	Standard Discontinuation. See 12nc 935271463557. OTP's P87C58BBD programmed to customer code can replace ROM.
319	P80C58X2BBD/CV841		P80C58X2BBD	935272292157	T	S	3	31-mrt-04	30-jun-04	P87C58X2BBD	Standard Discontinuation. See 12nc 935271463557. OTP's P87C58BBD programmed to customer code can replace ROM
320	P80C652EBB/04	P80C652EBB B	BLM I2C	935263236551	N	S	3	31-mrt-04	30-jun-04	P80C652EBB/04	Packing option discontinuation. Device still available in tubes. See Replacement 12nc 935263256557
321	P80C652EFA/04		BLM - I2C	935263240518	N	S	3	31-mrt-04	30-jun-04	P80C652EFA/04	Standard Discontinuation. See replacement 12nc 935263250557. Packing option discontinuation. Device still available in tubes.
322	P80C652EFB/04		BLM - I2C	935263237518	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
323	P80C652EFB/04		BLM - I2C	935263237557	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
324	P80C652EFP/04	P80C652EFP N	BLM - I2C	935263234112	T	S	3	31-mrt-04	30-jun-04	P80C652IFP/04	Standard Discontinuation. See replacement 12nc 935210460112
325	P80C652IBA/04		BLM - I2C	935209430512	N	S	3	31-mrt-04	30-jun-04	P80C652IBA/04	Packing option discontinuation. Device still available in Tape and Reel. 12nc 935209430518
326	P80CE558EFB/01	P80CE558EF B	RADIO/AUDIO/LCD/OTHER MICR.DER	935167530551	T	S	2	31-mrt-04	30-jun-04	None Noted	Limited Availability. Consult Marketing
327	P80CE558EFB/01	P80CE558EF B	RADIO/AUDIO/LCD/OTHER MICR.DER	935167530557	T	S	2	31-mrt-04	30-jun-04	None Noted	Limited Availability. Consult Marketing
328	P83C51RB+4A/CV93	CV9304 A	83C51RB+	935262300518	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. OTP's P87C51RB+4A programmed to customer code can replace ROM
329	P83C51RB+4A/CV93	CV9305 A	83C51RB+	935262624518	T	S	3	31-mrt-04	30-jun-04	None noted	OTP's P87C51RB+4A programmed to customer code can replace ROM
330	P83C51RB+4A/CV93	CV9315 A	83C51RB+	935267017518	T	S	3	31-mrt-04	30-jun-04	P87C51RB2BA	Standard Discontinuation. See 12nc 935271248512 OTP's P87C51RB2BA programmed to customer code can replace ROM
331	P83C51RB+4A/CV93	CV9322 A	83C51RB+	935269341518	T	M	3	31-dec-03	30-jun-04	P87C51RB2BA	Standard Discontinuation. See 12nc 935271248512 OTP's P87C51RB2BA programmed to customer code can replace ROM

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
332	P83C51RC+IA/CV92	CV9211 A	P83C51RC+IA	935270438512	T	M	3	31-dec-03	30-jun-04	P87C51RC+IA	Standard Discontinuation. See 12nc 935252090512 OTP's P87C51RC+IA programmed to customer code can replace ROM
333	P83C524EFA/262		BLM - I2C	935261337118	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
334	P83C524EFA/262		BLM - I2C	935261337518	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
335	P83C528EBA/265		BLM - I2C	935261379518	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
336	P83C528EBA/287		BLM - I2C	935263010512	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
337	P83C528EBB/301		BLM - I2C	935269127518	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
338	P83C552EBA/147		BLM - ADC	935263819512	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. P87C552EFAA OTP programmed to customer could be replacement.
339	P83C552EBA/151		BLM - ADC	935264104512	T	S	3	31-mrt-04	30-jun-04	None noted - See Comments	Standard Discontinuation. P87C552EFAA OTP programmed to customer could be replacement.
340	P83C552EBA/156		BLM - ADC	935265997518	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. Consult Marketing. P87C552EFAA OTP programmed to customer could be replacement.
341	P83C552EFA/143		BLM - ADC	935263735518	T	S	3	31-mrt-04	30-jun-04	None noted - See Comments	P87C552EFAA OTP programmed to customer could be replacement.
342	P83C554SBAA/CV95	CV9508 A	P83C554SBAA	935268879512	T	S	3	31-mrt-04	30-jun-04	None noted	P87C552EFAA OTP programmed to customer could be replacement.
343	P83C554SBAA/CV95	CV9509 A	P83C554SBAA	935268905512	N	S	3	31-mrt-04	30-jun-04	P83C554SBAA/CV9509A	Standard Discontinuation. Packing option discontinuation. Device still available in tape and reel
344	P83C557E2EFB/127		BLM - ADC	935263204557	T	S	3	31-mrt-04	30-jun-04	P89C557E4EFB/01	Standard Discontinuation. See Replacment 12nc 935263122557. OTP's P87C557E4EFB/01w/4K EPROM programmed to customer code can replace ROM
345	P83C557E4EFB/204		BLM - ADC	935268065557	T	S	3	31-mrt-04	30-jun-04	P87C557E4EFB/01	Packing option discontinuation. Device still available in 5 - tray qty. See 12nc 935263122557.
346	P83C557E4EFB/210		BLM - ADC	935271371518	T	S	3	31-mrt-04	30-jun-04	P87C557E4EFB/01	Packing option discontinuation. Device still available in 5 - tray qty. See 12nc 935263122557.
347	P83C562EBA/031		BLM - ADC	935264158512	T	S	3	31-mrt-04	30-jun-04	None noted - See Comments	Standard Discontinuation. P87C552EBA may be replacement in some applications.
348	P83C576EFAA/CV23	CV2314 A	P83C576EFAA	935266961518	T	S	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. Consult Marketing
349	P83C592FFA/011		ROM Code	935223160518	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
350	P83C652IBA/082		BLM - I2C	935263253518	T	S	3	31-mrt-04	30-jun-04	P87C654X2FA	OTP's P87C654X2FA w/16K EPROM programmed to customer code can replace ROM 12nc 935272990529 Not exact
351	P83C750EFAA/CV66		51 FAMILY CMOS ROM - 83C750	935273793118	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
352	P83CE598FFB/011		BLM - CAN PRODUCTS	935266795557	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation
353	P83LPC762BDH/CV8		83LPC762	935272537118	T	M	3	31-dec-03	30-jun-04	P87LPC762BDH	Standard Discontinuation. See 12nc 935268660112. OTP's P87LPC762BDH programmed to customer code can replace ROM
354	P87C51FA-5B	P87C51FA-5 B	51 FAMILY OTP/EPROM - 87C51FA	935253980557	T	M	3	31-dec-03	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
355	P87C51MB2BA	P87C51MB2B A	64K OTP 87C51MB2 (6CLK)	935269510512	T	S	3	31-mrt-04	30-jun-04	P87C51MB2BA	Standard Discontinuation. See 12nc 93527387652!
356	P87C51MB2BA		64K OTP 87C51MB2 (6CLK)	935269510529	T	S	3	31-mrt-04	30-jun-04	P87C51MB2BA	Standard Discontinuation. See 12nc 93527387652!
357	P87C51MC2BA/01		96K OTP 87C51MC2 (6CLK)	935271000512	T	S	3	31-mrt-04	30-jun-04	P87C51MC2BA/02	Standard Discontinuation. See Replacement
358	P87C51MC2BA/01		96K OTP 87C51MC2 (6CLK)	935271000529	T	S	3	31-mrt-04	30-jun-04	P87C51MC2BA/02	Standard Discontinuation. See Replacement 12nc 935273219529
359	P87C51RB+5B	P87C51RB+5 B	C51 FAMILY OTP/EPROM- 87C51RB+	935258300557	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
360	P87C51RC+IA	P87C51RC+I A	51 FAM.CMOS OTP EPROM 87C***	935252090512	T	S	3	31-mrt-04	30-jun-04	P87C51RC2BA	Standard Discontinuation. See Replacement 12nc 935272106512.
361	P87C51RD2BA		87C51RD2	935271965529	N	M	3	31-dec-03	30-jun-04	P87C51RD2BA	Standard Discontinuation. See 12nc 935271970112. Packing option discontinuation. Device still available in large pack qty
362	P87C51UFAA	P87C51UFA A	51 FAMILY OTP/EPROM - 87C51	935260187512	T	M	3	31-dec-03	30-jun-04	P87C51X2FA	Standard Discontinuation. See Replacement 12nc 935269605512
363	P87C51X2BA		P87C51X2 PLCC44	935269603529	N	M	3	31-dec-03	30-jun-04	P87C51X2BA	Standard Discontinuation. See 12nc 935269603512. Packing option discontinuation. Device still available in large pack qty
364	P87C51X2FA		P87C51X2 PLCC44	935269605529	N	M	3	31-dec-03	30-jun-04	P87C51X2FA	Standard Discontinuation. See 12nc 935269605512. Packing option discontinuation. Device still available in large pack qty
365	P87C54X2BA		P87C54X2B	935270161529	N	M	3	31-dec-03	30-jun-04	P87C54X2BA	Standard Discontinuation. See 12nc 935270161512. Packing option discontinuation. Device still available in large pack qty
366	P87C552SBAA		P87C552SBAA	935263111529	N	S	3	31-mrt-04	30-jun-04	P87C552SBAA	Packing option discontinuation. Device still available in tubes. See Replacement 12nc 935263111512
367	P87C552SFAA		P87C552SFAA	935263958529	N	S	3	31-mrt-04	30-jun-04	P87C552SFAA	Standard Discontinuation. 12nc 935263958512. Packing option discontinuation. Device still available in large pack qty.
368	P87C554SBAA		P87C554SBAA	935263385529	N	S	3	31-mrt-04	30-jun-04	P87C554SBAA	Packing option discontinuation. Device still available in large pack qty. 12nc 935263385512
369	P87C554SFAA		P87C554SFAA	935263922529	N	S	3	31-mrt-04	30-jun-04	P87C554SFAA	Standard Discontinuation. 12nc 935263922512 Packing option discontinuation. Device still available in large pack qty.
370	P87C557E8EFB/01	P87C557E8F B	BLM - ADC	935263160518	N	S	3	31-mrt-04	30-jun-04	P87C557E8EFB/01	Packing option discontinuation. Device still available in tubes. See Replacement 12nc 935263111557
371	P87C557E8EFB/01	P87C557E8F B	BLM - ADC	935263160551	N	S	3	31-mrt-04	30-jun-04	P87C557E8EFB/01	Packing option discontinuation. Device still available in tubes. See Replacement 12nc 935263111557

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
372	P87C58SBBB/CV841	51 FAMILY OTP/EPROM - 87C58	935272435557	T	S	3	31-mrt-04	30-jun-04	P87C58X2BBBD	Standard Discontinuation. See 12nc 935271463557. OTP's P87C58BBBD programmed to customer code can replace ROM	
373	P87C591VFA/00	BLM - CAN PRODUCTS	935268182529	N	S	3	31-mrt-04	30-jun-04	P87C591VFA/00	Packing option discontinuation. Device still available in large pack qty. See 12nc 9352681825512.	
374	P87LPC760BDH	87LPC760	935271146129	N	S	3	31-mrt-04	30-jun-04	P87LPC760BDH	Standard Discontinuation. See 12nc 935271146112 Packing option discontinuation. Device still available in large pack qty	
375	P87LPC761BDH	87LPC761	935271147129	N	S	3	31-mrt-04	30-jun-04	P87LPC761BDH	Standard Discontinuation. See 12nc 935271147112. Packing option discontinuation. Device still available in large pack qty	
376	P87LPC762BDH	P87LPC762 SSOP20	935268660129	N	S	3	31-mrt-04	30-jun-04	P87LPC762BDH	Packing option discontinuation. Device still available in large pack qty. See 12nc 935268660112	
377	P87LPC764BD	P87LPC764BD	935263358129	N	S	3	31-mrt-04	30-jun-04	P87LPC764BD	Packing option discontinuation. Device still available in large pack qty. 12nc 935263358512	
378	P87LPC764BD	P87LPC764BD	935263358529	N	S	3	31-mrt-04	30-jun-04	P87LPC764BD	Packing option discontinuation. Device still available in large pack qty. 12nc 935263358512	
379	P87LPC764BDH	P87LPC764BD	935267867129	N	S	3	31-mrt-04	30-jun-04	P87LPC764BDH	Packing option discontinuation. Device still available in large pack qty. 12nc 935267867112.	
380	P87LPC764FD	P87LPC764	935266844129	N	S	3	31-mrt-04	30-jun-04	P87LPC764FD	Standard Discontinuation. See 12nc 935266844112 Packing option discontinuation. Device still available in large pack qty	
381	P87LPC764FD	P87LPC764	935266844529	N	S	3	31-mrt-04	30-jun-04	P87LPC764FD	Standard Discontinuation. See 12nc 935266844112 Packing option discontinuation. Device still available in large pack qty	
382	P87LPC764FDH	P87LPC764BD	935267869129	N	S	3	31-mrt-04	30-jun-04	P87LPC764FDH	Packing option discontinuation. Device still available in large pack qty. See 12nc 935267869112.	
383	P87LPC767BD	P87LPC767 SO	935264007129	N	S	3	31-mrt-04	30-jun-04	P87LPC767BD	Standard Discontinuation. 12nc 935264007112. Packing option discontinuation. Device still available in large pack qty.	
384	P87LPC767BD	P87LPC767 SO	935264007529	N	S	3	31-mrt-04	30-jun-04	P87LPC767BD 935264007112	Packing option discontinuation. Device still available in large pack qty	
385	P87LPC767BD/CP32	P87LPC767 SO	935271963112	T	S	3	31-mrt-04	30-jun-04	P87LPC767BD	Standard Discontinuation. See 12nc 935264007112 Packing option discontinuation. Device still available in large pack qty	
386	P87LPC767BD/CP32	P87LPC767 SO	935271963512	T	S	3	31-mrt-04	30-jun-04	P87LPC767BD 935264007112	Packing option discontinuation. Device still available in large pack qty	
387	P87LPC767BN/CP32	P87LPC767 DIP	935271970112	N	S	3	31-mrt-04	30-jun-04	P87LPC767BN	Standard Discontinuation. See 12nc 935271970112. OTP's P87LPC767BN programmed to customer code can replace ROM	
388	P87LPC767FD	P87LPC767 SO	935267191129	N	S	3	31-mrt-04	30-jun-04	P87LPC767FD	Standard Discontinuation. See 12 nc 935267191112 Packing option discontinuation. Device still available in large pack qty	
389	P87LPC767FD	P87LPC767 SO	935267191529	N	S	3	31-mrt-04	30-jun-04	P87LPC767FD	Packing option discontinuation. Device still available in large pack qty. See Replacement 12nc 935267191112	
390	P87LPC767HD	P87LPC767 SO20	935267645112	N	S	3	31-mrt-04	30-jun-04	P87LPC767HD	Packing option discontinuation. Device still available in small pack qty. 12nc 935267645529.	
391	P87LPC767HD	P87LPC767H D	P87LPC767 SO20	935267645512	N	S	3	31-mrt-04	30-jun-04	P87LPC767HD	Packing option discontinuation. Device still available in small pack qty. See Replacement 12nc 935267645529

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
392	P89C51BBD	P89C51B BD	BLM - FLASH MCU	935269767557	T	M	3	31-dec-03	30-jun-04	P89C51X2BBD	Standard Discontinuation. See 12nc 935271449557
393	P89C51RC2HBBD/00	P89C51RC2B BD	BLM - FLASH MCU	935267811551	N	S	3	31-mrt-04	30-jun-04	P89C51RC2HBBD/00	Packing option discontinuation. Device still available in 5 - tray qty. See 12nc 935267811557.
394	P89C52BBD	P89C52B BD	BLM - FLASH MCU	935269943557	T	M	3	31-dec-03	30-jun-04	P89C52X2BBD	Standard Discontinuation. See 12nc 935271454557
395	P89C54BBD	P89C54B BD	BLM - FLASH MCU	935269908557	T	M	3	31-dec-03	30-jun-04	P89C54X2BBD	Standard Discontinuation. See 12nc 935271459557
396	P89C58BBD	P89C58B BD	BLM - FLASH MCU	935269764557	T	M	3	31-dec-03	30-jun-04	P87C58X2BBD	Standard Discontinuation. See 12nc 935271463557
397	P89C662HBA/00		BLM - FLASH MCU	935267444529	N	S	3	31-mrt-04	30-jun-04	P89C662HBA/00	Packing option discontinuation. Device still available in large pack qty. See 12nc 935267443512.
398	P89C664HBA/00		BLM - FLASH MCU	935267448518	N	S	3	31-mrt-04	30-jun-04	P89C664HBA/00	Packing option discontinuation. Available only in tubes. See 12nc 935267448512.
399	P89C664HBA/00		BLM - FLASH MCU	935267448529	N	S	3	31-mrt-04	30-jun-04	P89C664HBA/00	Packing option discontinuation. Device still available in large pack qty. See 12nc 935267448512.
400	P89C668HBA/HP01		BLM - FLASH MCU	935270686512	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
401	P89C668HFBD/00		BLM - FLASH MCU	935271436557	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
402	P8RF5016AEV/108A		MIFARE3	935271283118	T	C	2	30-mrt-04	30-jun-04	None noted	Replaced by new custom-codes. Limited supply. Consult Marketing
403	P8RF5016AEV/1100		MIFARE3	935271166118	T	C	2	30-mrt-04	30-jun-04	None noted	Limited Availability. Consult Marketing
404	P8RF5016AEV/1260		MIFARE3	935272546118	T	C	2	30-mrt-04	30-jun-04	None noted	Limited Supply. Consult Marketing
405	P8RF5016AEW/114A		MIFARE3	935272311005	T	C	2	30-mrt-04	30-jun-04	None noted	Replaced by new custom-codes. Limited supply. Consult Marketing
406	P8WE5017AEV/0070		08BIT CC	935270782118	T	C	3	31-mrt-04	30-jun-04	None	Standard Discontinuation. Consult Marketing
407	P8WE5017AEV/0131		08BIT CC	935272115118	T	C	2	30-mrt-04	30-jun-04	P8WE5017AEV/014128I	Replaced by new fabkeys. Limited Supply. See Replacement 12NC 935272229118
408	P8WE5017AEW/004		08BIT CC	935270324005	T	C	3	31-mrt-04	30-jun-04	None	Standard Discontinuation
409	P8WE5017AEW/0070		08BIT CC	935270684005	T	C	3	31-mrt-04	30-jun-04	None	Standard Discontinuation. Consult Marketing
410	P8WE5032AEU/0171	CWE5032711 CU	08BIT CC	935267495025	N	C	1	30-jun-03	30-jun-03	None noted	Contact Marketing for replacement.
411	P8WE5032AEV/0312	CWE5032288 J	08BIT CC	935268802118	T	C	3	31-mrt-04	30-jun-04	None	Standard discontinuation. Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments
412	P8WE5033AEV/0170	08BIT CC	935270778118	T	C	2	30-mrt-04	30-jun-04	P8WE5033AEV/032008	Replaced by new custom-codes. Limited supply. See Replacement part 12nc 935272427118 See replacement
413	P8WE5033AEV/0201	08BIT CC	935270779118	T	C	3	31-mrt-04	30-jun-04	None	Standard Discontinuation. Consult Marketing
414	P8WE5033AEV/0230	08BIT CC	935271114118	T	C	2	30-mrt-04	30-jun-04	P8WE5033AEV/032008	Limited Availability. See Replacement 12nc 935272427118
415	P8WE5033AEV/0280	08BIT CC	935272420118	T	C	2	30-mrt-04	30-jun-04	P8WE5033AEV/032008	Replaced by new fabkey. Limited Supply. See replacement. 12nc 935272427118
416	P8WE5033AEV/014	08BIT CC	935270231005	T	C	3	31-mrt-04	30-jun-04	None	Standard discontinuation. Consult Marketing
417	P8WE5033AEV/020	08BIT CC	935270691005	T	C	3	31-mrt-04	30-jun-04	None	Standard Discontinuation. Consult Marketing
418	P8WE6004AEV/007	08BIT SC	935270678005	T	C	2	30-mrt-04	30-jun-04	None noted	Limited Availability. Replaced by new fabkey. Limited Supply.
419	P8WE6004AEV/007	08BIT SC	935271023005	T	C	2	30-mrt-04	30-jun-04	None noted	Replaced by new fabkey. Limited Supply.
420	P8WE6004AEV/007	08BIT SC	935271022005	T	C	2	30-mrt-04	30-jun-04	None noted	Replaced by new fabkey. Limited Supply.
421	P8WE6008AEV/1040	08BIT SC	935268239118	T	C	2	30-mrt-04	30-jun-04	None	Limited Availability. Consult Marketing
422	P8WE6017AEV/1162	08BIT SC	935271113118	T	C	1	30-jun-03	30-jun-03	None	Not Manufacturable. Contact Marketing
423	P8WE6017AEV/1453	08BIT SC	935272139118	T	C	2	30-mrt-04	30-jun-04	P8WE6017AEV/146A38R	Replaced by new fabkeys. Limited Supply. See Replacement 12NC 935273256118
424	P8WE6017AEV/1453	08BIT SC	935272141118	T	C	2	30-mrt-04	30-jun-04	P8WE6017AEV/146A38R	Replaced by new fabkeys. Limited Supply. See Replacement 12NC 935273256118
425	P8WE6017AEV/1453	08BIT SC	935272001118	T	C	2	30-mrt-04	30-jun-04	P8WE6017AEV/146A38R	Replaced by new fabkeys. Limited Supply. See Replacement 12NC 935273256118
426	P8WE6017AEV/1453	08BIT SC	935272000118	T	C	2	30-mrt-04	30-jun-04	P8WE6017AEV/146A38R	Replaced by new fabkeys. Limited Supply. See Replacement 12NC 935273256118
427	P8WE6017AEV/1463	08BIT SC	935272380118	T	C	2	30-mrt-04	30-jun-04	P8WE6017AEV/146A38R	Replaced by new fabkey. Limited Supply. See replacement 12nc 935273256118
428	P8WE6017AEV/1463	08BIT SC	935272381118	T	C	2	30-mrt-04	30-jun-04	P8WE6017AEV/146A38R	Replaced by new fabkey. Limited Supply. See replacement 12nc 935273256118
429	P8WE6017AEV/1431	08BIT SC	935271845005	T	C	2	30-mrt-04	30-jun-04	None noted	Replaced by new fabkeys. Limited Supply. Consult Marketing
430	P8WE6032AEV/002	08BIT SC	935269450005	T	C	3	30-mrt-04	30-jun-04	None	Standard end of life. Consult Marketing
431	P8WE6032AEV/054	08BIT SC	935266751005	T	C	2	30-mrt-04	30-jun-04	None	Limited Availability. Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
432	P8WE6032AEW/107	08BIT SC	935271029005	T	C	2	30-mrt-04	30-jun-04	None	Replaced by new fabkey. Limited Supply.	
433	PBYL1625	Schottky-barrier rectifier diode	934054760127	T	M	3	31-dec-03	30-jun-04	PBYR1645	Standard Discontinuation. See Replacement. Consult Marketing.	
434	PBYL2025B	Schottky-barrier rectifier diode	934054766118	T	M	3	31-dec-03	30-jun-04	None	Standard Discontinuation. No replacement part available. Consult Marketing.	
435	PBYL2520CT	Schottky-barrier rect.double diode	934054771127	T	M	3	31-dec-03	30-jun-04	PBYL3025CT	Standard Discontinuation. See Replacement. Consult Marketing	
436	PBYR1045F/1	Rectifier diode Schottky barrier	934052920127	T	M	1	30-jun-03	30-jun-04	PBYR1045	Package discontinuation, no last time buy possible. Consult Marketing	
437	PBYR4040WT	MV SCHOTTKY RECTIFIER	934055371127	T	M	3	31-dec-03	30-jun-04	PBYR4045WT	Standard Discontinuation. Same part available in 45V. Consult Marketing.	
438	PCA1465U/10/F2	CLOCKS AND WATCHES	935240010005	T	S	3	31-mrt-04	30-jun-04	PCA2001U/10	Standard Discontinuation. See Replacement. Consult Marketing	
439	PCA1465U/7/F2	CLOCKS AND WATCHES	935239900027	T	S	3	31-mrt-04	30-jun-04	PCA2001	Standard Discontinuation. See Replacement. Consult Marketing	
440	PCA1465U/F2	CLOCKS AND WATCHES	935239810026	N	S	3	31-mrt-04	30-jun-04	PCA2001U/10	Standard Discontinuation. See Replacement. Consult Marketing	
441	PCA1485U/7/F2	CLOCKS AND WATCHES	935239910027	N	S	3	31-mrt-04	30-jun-04	PCA2000	Standard Discontinuation. See Replacement. Consult Marketing	
442	PCA1486U/10/F2	CLOCKS AND WATCHES	935240040005	T	S	3	31-mrt-04	30-jun-04	PCA2001U/10	Standard Discontinuation. See Replacement. Consult Marketing	
443	PCA1486U/7/F2	CLOCKS AND WATCHES	935239920027	T	S	3	31-mrt-04	30-jun-04	PCA2001	Standard Discontinuation. See Replacement. Consult Marketing	
444	PCA1606U/10/F2	CLOCKS AND WATCHES	935240080005	N	S	3	31-mrt-04	30-jun-04	PCA2002U/10	Standard Discontinuation. See Replacement. Consult Marketing	
445	PCA1606U/F2	CLOCKS AND WATCHES	935239820026	T	S	3	31-mrt-04	30-jun-04	PCA2002U	Standard Discontinuation. See Replacement. Consult Marketing	
446	PCA1607U/F2	CLOCKS AND WATCHES	935260455026	T	S	3	31-mrt-04	30-jun-04	PCA2002U	Standard Discontinuation. See Replacement. Consult Marketing	
447	PCA1611U/10/F2	CLOCKS AND WATCHES	935240090005	T	S	3	31-mrt-04	30-jun-04	PCA2002U/10	Standard Discontinuation. See Replacement. Consult Marketing	
448	PCA1625U/7/F2	CLOCKS AND WATCHES	935239970027	N	S	3	31-mrt-04	30-jun-04	PCA2002	Standard Discontinuation. See Replacement. Consult Marketing	
449	PCA1625U/F2	CLOCKS AND WATCHES	935239840026	N	S	3	31-mrt-04	30-jun-04	PCA2002U	Standard Discontinuation. See Replacement. Consult Marketing	
450	PCA1627U/7/F2	CLOCKS AND WATCHES	935239980027	T	S	3	31-mrt-04	30-jun-04	PCA2002	Standard Discontinuation. See Replacement. Consult Marketing	
451	PCA1673U/10/F2	PCA1673U10 CA	CLOCKS AND WATCHES	935261483005	T	S	3	31-mrt-04	30-jun-04	PCA2002U/10	Standard Discontinuation. See Replacement. Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
452	PCA1675U/F2		CLOCKS AND WATCHES	935239870026	T	S	3	31-mrt-04	30-jun-04	PCA2001U/10	Standard Discontinuation. See Replacement. Consult Marketing
453	PCA82C250T/N4/S9	CE4863 D	AUTOMOTIVE NIJMEGEN	935270408118	N	C	1	30-jun-03	30-jun-04	PCA82C250T/N4	Non-Manufacturable. See Replacement. Project called TARAC_B (ROP1016172CR1AU) from 09/05/2000.
454	PCA8581T/F6L	PCA8581TL D	CLIPS	935057660118	N	S	2	30-mrt-04	30-jun-04	PCA8581T/F6	Limited Availability, See Replacement. Consult Marketing
455	PCA8594F-2T/02	PCA8594F2 D	EEPROMS	935195580112	T	M	3	31-dec-03	30-jun-04	PCF8594C-2T	Standard Discontinuation. See Replacement. Consult Marketing
456	PCA8840L1/C/1		120/128 CH GATE DRIVER	935269538523	T	C	1	30-jun-03	30-jun-03	None	Non-Manufacturable. Consult Marketing
457	PCA8850L2/D/1		DISPLAY DRIVER	935268778116	T	C	1	30-jun-03	30-jun-03	None	Non-Manufacturable. Consult Marketing
458	PCA8851L13/C/1		TFT GATE DRIVER	935271078523	T	C	1	30-jun-03	30-jun-03	None	Non-Manufacturable. Consult Marketing
459	PCA8851L17/C/1		TFT GATE DRIVER WITH 256CH	935272260516	T	C	1	30-jun-03	30-jun-03	None	Non-Manufacturable. Consult Marketing
460	PCB2421T/F1	PCB2421T D	CLIPS	935196480118	T	S	1	30-jun-03	30-jun-03	None	Non-manufacturable, Consult Marketing
461	PCD6001H/D23/F2		84CXXX FAMILY	935269046557	T	C	1	30-jun-03	30-jun-03	None	Non-Manufacturable. Consult Marketing
462	PCF1175CT/S420/2		CLOCKS AND WATCHES	935260266112	N	S	3	31-mrt-04	30-jun-04	...118 (Blister)	Standard Discontinuation. See Replacement. Consult Marketing
463	PCF2100CP/F1	PCF2100CP N	DISPLAY DRIVERS	935192380112	N	S	2	30-mrt-04	30-jun-04	PCF2100CT/F1	Limited Availability, See Replacement. Consult Marketing
464	PCF2103EU/2/F2		DISPLAY DRIVERS	935261187026	T	S	2	30-mrt-04	30-jun-04	None noted	Limited Availability. Consult Marketing
465	PCF2103EU/F2		DISPLAY DRIVERS	935264244026	T	S	2	30-mrt-04	30-jun-04	None noted	Limited Availability. Consult Marketing
466	PCF2104LU/2/F1		DISPLAY DRIVERS	935216970026	T	S	2	30-mrt-04	30-jun-04	None	Limited Availability. Consult Marketing
467	PCF2105MU/2/F1		DISPLAY DRIVERS	935262211026	T	S	2	30-mrt-04	30-jun-04	None noted	Limited Availability. Consult Marketing
468	PCF2111CP/F1	PCF2111CP N	DISPLAY DRIVERS	935195710112	N	S	2	30-mrt-04	30-jun-04	PCF2111CT/F1	Limited Availability, See Replacement
469	PCF2111T	PCF2111T D	DISPLAY DRIVERS	933733720118	T	S	2	1-mrt-04	30-jun-04	None	Limited Availability, Consult Marketing
470	PCF2116AU/12/F1		DISPLAY DRIVERS	935226360005	N	S	2	30-mrt-04	30-jun-04	None noted	Limited Availability. Consult Marketing
471	PCF50601ET/N5/S30		POWER MANAGEMENT SYSTEM IC	935271690518	N	S	3	31-mrt-04	30-jun-04	PCF50601ET/N5C	Standard End of Life. See Replacement

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments
472	PCF50604HN/05/2C	POWER MANAGEMENT SYSTEM IC	935271638518	N	C	3	31-mrt-04	30-jun-04	None noted	Standard End of Life. Consult Marketing
473	PCF50872EL/271E1/	BASEBAND	935271960518	T	C	3	31-mrt-04	30-jun-04	PCF50872EL/271E1	Standard End of Life. See Replacement
474	PCF7951ATS/3391S	PKE CHIPS	935267621112	T	C	1	30-jun-03	30-jun-03	PCF7951ATS/3391S1	See replacement part. 935271814112 or 935271814118
475	PCF8548U/9/F1	LCD GRAPHIC DRIVER	935263626025	N	S	2	30-mrt-04	30-jun-04	PCF8548U/2/F1	Limited Availability. See Replacement
476	PCF8558U/12/F2	PCF8558U12 CA DISPLAY DRIVERS	935239430005	N	S	2	30-mrt-04	30-jun-04	PCF8558U/2/F2	Limited Availability. See Replacement
477	PCF8564AU/5/F1	CLIPS	935264197015	N	S	1	30-jun-03	30-jun-03	PCA8564AU/5/F4	Non-manufacturable. See Replacement
478	PCF8576CU/12E/2	DISPLAY DRIVERS	935263925005	N	S	2	30-mrt-04	30-jun-04	PCF8576CU/2/F2	Limited Availability. See Replacement
479	PCF8576T/S480/2	DISPLAY DRIVERS	935261731118	N	S	2	30-mrt-04	30-jun-04	PCF8576T	Limited Availability. See Replacement
480	PCF8576U	DISPLAY DRIVERS	933740720026	N	M	2	30-dec-03	30-mrt-04	None noted	Limited Availability. Consult Marketing
481	PCF8576U/10	DISPLAY DRIVERS	933841600005	N	M	2	30-dec-03	30-mrt-04	None noted	Limited Availability. Consult Marketing
482	PCF8576U/12	DISPLAY DRIVERS	935064190005	N	M	2	30-dec-03	30-mrt-04	None noted	Limited Availability. Consult Marketing
483	PCF8576U/2	DISPLAY DRIVERS	933774680026	N	M	2	30-dec-03	30-mrt-04	None noted	Limited Availability. Consult Marketing
484	PCF8577CT/S208/F2	CE1389 D DISPLAY DRIVERS	935074860118	N	S	2	30-mrt-04	30-jun-04	PCF8577CT/F3	Limited Availability. See Replacement
485	PCF8577CT/S420/3	DISPLAY DRIVERS	935254990118	N	S	2	30-mrt-04	30-jun-04	PCF8577CT/F3	Limited Availability. See Replacement
486	PCF8578T/S480/1	DISPLAY DRIVERS	935261722118	N	S	2	30-mrt-04	30-jun-04	PCF8578T	Limited Availability. See Replacement
487	PCF8579T/S480/1	DISPLAY DRIVERS	935261723118	N	S	2	30-mrt-04	30-jun-04	PCF8579T	Limited Availability. See Replacement
488	PCF8832U/2DA/1	ROW DRIVER	935268515026	T	S	1	30-jun-03	30-jun-03	None	Non-Manufacturable. Consult Marketing
489	PCK2509SPW	PCK2509SPW DH 3.3V HIGH SPEED PLL	935264404112	T	M	3	31-dec-03	30-jun-04	PCK2509SADH	Standard Discontinuation. See Replacement
490	PCK2509SPW	PCK2509SPW DH 3.3V HIGH SPEED PLL	935264404118	T	M	3	31-dec-03	30-jun-04	PCK2509SADH	Standard Discontinuation. See Replacement
491	PCK2510SPW	PCK2510SPW DH 3.3V HIGH SPEED PLL	935264405112	T	M	3	31-dec-03	30-jun-04	PCK2510SADH	Standard Discontinuation. See Replacement

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments
492	PCK2510SPW	PCK2510SPW DH 3.3V HIGH SPEED PLL	935264405118	T	M	3	31-dec-03	30-jun-04	PCK2510SADH	Standard Discontinuation. See Replacement
493	PHB12NQ15T	100V><300V N CHANNEL TRENCHFET	934055728118	T	M	3	31-dec-03	30-jun-04	PHM18NQ15T	Standard Discontinuation. See Replacement
494	PHB14NQ20T	100V><300V N CHANNEL TRENCHFET	934055772118	T	M	3	31-dec-03	30-jun-04	PHD14NQ20T	Standard Discontinuation. See Replacement
495	PHB18NQ10T	60V><100V N CHANNEL TRENCHFET	934055699118	T	M	3	31-dec-03	30-jun-04	PHD18NQ10T	Standard Discontinuation. See Replacement
496	PHB18NQ20T	100V><300V N CHANNEL TRENCHFET	934055765118	T	M	3	31-dec-03	30-jun-04	PHB20NQ20T	Standard Discontinuation. See Replacement
497	PHB23NQ10T	60V><100V N CHANNEL TRENCHFET	934055696118	T	M	3	31-dec-03	30-jun-04	PHB47NQ10T	Standard Discontinuation. See Replacement
498	PHB23NQ15T	100V><300V N CHANNEL TRENCHFET	934055725118	T	M	3	31-dec-03	30-jun-04	PHM18NQ15T	Standard Discontinuation. See Replacement
499	PHB27NQ10T	60V><100V N-CHANNEL TRENCHFET	934055809118	T	M	3	31-dec-03	30-jun-04	PHD34NQ10T	Standard Discontinuation. See Replacement
500	PHB30NQ15T	100V><300V N CHANNEL TRENCHFET	934055760118	T	M	3	31-dec-03	30-jun-04	PSMN063-150D	Standard Discontinuation. See Replacement
501	PHB34NQ10T	60V><100V N-CHANNEL TRENCHFET	934055806118	T	M	3	31-dec-03	30-jun-04	PHD34NQ10T	Standard Discontinuation. See Replacement
502	PHB55N04LT	30V N CHANNEL TRENCHFET	934056635118	T	M	3	31-dec-03	30-jun-04	PHB73N06T	Standard Discontinuation. See Replacement
503	PHB95N03LTA	<=30V N CHANNEL TRENCHFET	934057229118	T	M	3	31-dec-03	30-jun-04	PHB108NQ03LT	Standard Discontinuation. See Replacement
504	PHD11N03LT	60V><100V N-CHANNEL TRENCHFET	934055812127	T	M	1	30-jun-03	30-jun-04	PHD3055E	Wrong 12nc Ending. No last time buy available. See Replacement
505	PHD12NQ15T	100V><300V N CHANNEL TRENCHFET	934055726118	T	M	3	31-dec-03	30-jun-04	PHM18NQ15T	Standard Discontinuation. See Replacement. Consult Marketing
506	PHD23NQ10T	60V><100V N CHANNEL TRENCHFET	934055697118	T	M	3	31-dec-03	30-jun-04	PHD34NQ10T	Standard Discontinuation. See Replacement. Consult Marketing
507	PHD27NQ10T	60V><100V N-CHANNEL TRENCHFET	934055810118	T	M	3	31-dec-03	30-jun-04	PHD34NQ10T	Standard Discontinuation. See Replacement. Consult Marketing
508	PHD95N03LT	<=30V N CHANNEL TRENCHFET	934056736118	T	M	3	31-dec-03	30-jun-04	PHD108NQ03LT	Standard Discontinuation. See Replacement. Consult Marketing
509	PHE83N03LT	<=30V N CHANNEL TRENCHFET	934056593127	T	M	3	31-dec-03	30-jun-04	PHU71NQ03LT	Standard Discontinuation. See Replacement. Consult Marketing
510	PHE95N03LT	<=30V N CHANNEL TRENCHFET	934056594127	T	M	3	31-dec-03	30-jun-04	PHU82NQ03LT	Standard Discontinuation. See Replacement. Consult Marketing
511	PHF14NQ20T	100V><300V N CHANNEL TRENCHFET	934055774127	T	M	1	30-jun-03	30-jun-03	PHX14NQ20T	Package discontinuation, no last time buy possible. Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments
512	PHF9NQ20T	100V><300V N CHANNEL TRENCHFET	934055770127	T	M	1	30-jun-03	30-jun-03	PHX9NQ20T	Package discontinuation, no last time buy possible. Consult Marketing
513	PHK5NQ10T	60><100V N CHANNEL TRENCHFET	934055905118	T	M	3	31-dec-03	30-jun-04	PHM25NQ10T	Standard Discontinuation. See Replacement
514	PHN103S	N-channel enhancem. mode MOS trans.	934055965118	T	M	3	31-dec-03	30-jun-04	None	Standard Discontinuation. Old Technology
515	PHP12NQ15T	100V><300V N CHANNEL TRENCHFET	934055727127	T	M	3	31-dec-03	30-jun-04	PHP30NQ15T	Standard Discontinuation. See Replacement
516	PHP14NQ20T	100-300V N CHANNEL TRENCHFET	934055683127	T	M	3	31-dec-03	30-jun-04	PHP20NQ20T	Standard Discontinuation. See Replacement
517	PHP18NQ20T	100V><300V N CHANNEL TRENCHFET	934055764127	T	M	3	31-dec-03	30-jun-04	PHX18NQ20T	Standard Discontinuation. See Replacement
518	PHP23NQ10LT	100V><300V N CHANNEL TRENCHFET	934055682127	T	M	3	31-dec-03	30-jun-04	PHP23NQ10T	Standard Discontinuation. See Replacement
519	PHP23NQ15T	100V><300V N CHANNEL TRENCHFET	934055724127	T	M	3	31-dec-03	30-jun-04	PHP30NQ15T	Standard Discontinuation. See Replacement
520	PHP27NQ10T	60V><100V N-CHANNEL TRENCHFET	934055811127	T	M	3	31-dec-03	30-jun-04	PHP34NQ10T	Standard Discontinuation. See Replacement
521	PHP55N04LT	30V N CHANNEL TRENCHFET	934056641127	T	M	3	31-dec-03	30-jun-04	PHP73N06T	Standard Discontinuation. See Replacement. Old Product
522	PHX23NQ10LT	60V><100V N CHANNEL TRENCHFET	934055799127	T	M	3	31-dec-03	30-jun-04	PHP23NQ10T	Standard Discontinuation. See Replacement
523	PMBD6050/AT	High-speed diode	933884740215	T	C	3	31-mrt-04	30-jun-04	Philips: PMBD6050	Standard Discontinuation. See Replacement
524	PMBD6050/AT	High-speed diode	933884740235	T	C	3	31-mrt-04	30-jun-04	Philips: PMBD6050	Standard Discontinuation. See Replacement
525	PMBD6100/AT	High-speed double diode	933876270185	T	C	3	31-mrt-04	30-jun-04	Philips: PMBD6100	Standard Discontinuation. See Replacement
526	PMBD6100/AT	High-speed double diode	933876270215	T	C	3	31-mrt-04	30-jun-04	Philips: PMBD6100	Standard Discontinuation. See Replacement
527	PMBD914/FD	High-speed diode	933926870185	T	C	3	31-mrt-04	30-jun-04	Philips: PMBD914	Standard Discontinuation. See Replacement
528	PMBD914/FD	High-speed diode	933926870215	T	C	3	31-mrt-04	30-jun-04	Philips: PMBD914	Standard Discontinuation. See Replacement
529	PMBD914/FD	High-speed diode	933926870235	T	C	3	31-mrt-04	30-jun-04	Philips: PMBD914	Standard Discontinuation. See Replacement
530	PNX7850E	CENTAURUS	935272783557	T	S	1	30-jun-03	30-jun-03	PNX7850E/Z/M1D	Non-Manufacturable. See replacement part
531	PNX7850E/M1B	CENTAURUS	935272890557	T	S	1	30-jun-03	30-jun-03	PNX7850E/Z/M1D	Non-Manufacturable. See replacement part. Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments
532	PSMA26A	26 V transient-volt. suppr. diode	934052750135	T	M	3	31-dec-03	30-jun-04	None	Non-Manufacturable. See replacement part. Consult Marketing
533	PSW23112	PSW23112 MSC SOFTWARE	939100000112	T	M	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. See replacement part. Consult Marketing
534	PTD2000EB	PTD2000	935271639557	T	M	1	30-jun-03	30-jun-03	None	San Antonio plant closure, commercially impractical conditions apply. Consult Marketing. See Philips' CPCN dated 3/28/03
535	PTD2102EB	PTD2102	935271640557	T	M	1	30-jun-03	30-jun-03	None	San Antonio plant closure, commercially impractical conditions apply. Consult Marketing. See Philips' CPCN dated 3/28/03
536	PTD2200EB	PTD2200	935271641557	T	M	1	30-jun-03	30-jun-03	None	San Antonio plant closure, commercially impractical conditions apply. Consult Marketing. See Philips' CPCN dated 3/28/03
537	PTD2402EB	PTD2402EB	935271720557	T	M	1	30-jun-03	30-jun-03	None	San Antonio plant closure, commercially impractical conditions apply. Consult Marketing. See Philips' CPCN dated 3/28/03
538	PTD2408EB	PTD2408	935271643557	T	M	1	30-jun-03	30-jun-03	None	San Antonio plant closure, commercially impractical conditions apply. Consult Marketing. See Philips' CPCN dated 3/28/03
539	PTD2730SD	PTD2730SD	935271580112	T	M	1	30-jun-03	30-jun-03	None	San Antonio plant closure, commercially impractical conditions apply. Consult Marketing. See Philips' CPCN dated 3/28/03
540	PTD2740SD	PTD2740SD	935271581112	T	M	1	30-jun-03	30-jun-03	None	San Antonio plant closure, commercially impractical conditions apply. Consult Marketing. See Philips' CPCN dated 3/28/03
541	PTD2751SD	PTD2751SD	935271584112	T	M	1	30-jun-03	30-jun-03	None	San Antonio plant closure, commercially impractical conditions apply. Consult Marketing. See Philips' CPCN dated 3/28/03
542	PXAC37KBA/00	PXAC37KB A BLM - CAN PRODUCTS	935266515512	T	S	3	31-mrt-04	30-jun-04	PXAC37KFA/00	Recommended device provides wider operating temperature range. See 12nc 935266516512.
543	PXAC37KBBD/00	PXAC37KB BD BLM - CAN PRODUCTS	935266517551	T	S	3	31-mrt-04	30-jun-04	PXAC37KFBD/00	Recommended device provides wider operating temperature range. See 12nc 935266518557
544	PXAC37KBBD/00	PXAC37KB BD BLM - CAN PRODUCTS	935266517557	T	S	3	31-mrt-04	30-jun-04	PXAC37KFBD/00	Recommended device provides wider operating temperature range. See 12nc 935266518557
545	PXAC37KFBD/00	PXAC37KF BD BLM - CAN PRODUCTS	935266518551	N	S	3	31-mrt-04	30-jun-04	PXAC37KFBD/00	Packing option discontinuation. Device still available in 5 - tray qty. See 12nc 935266518557
546	PXAG49KBBD/00	PXAG49KB BD BLM - FLASH MCU	935267442551	N	S	3	31-mrt-04	30-jun-04	PXAG49KBBD/00	Standard Discontinuatin. See 12nc 935267442557 Packing option discontinuation. Device still available in 5 - tray qty
547	PXAG49KFBD/00	PXAG49KFBD/00 BLM - FLASH MCU	935267443551	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
548	PXAG49KFBD/00	PXAG49KFBD/00 BLM - FLASH MCU	935267443557	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
549	PXAS30KBA	PXAS30KBA	935262383529	N	S	3	31-mrt-04	30-jun-04	PXAS30KBA	Packing option discontinuation. Device still available in tubes. See Replacement 12nc 935262383512. Consult Marketing
550	PXAS30KFA	PXAS30KFA	935262382529	N	S	3	31-mrt-04	30-jun-04	PXAS30KFA	Packing option discontinuation. Device still available in tubes. See Replacement 12nc 935262383512. Consult Marketing
551	PXAS30KFBE	PXAS30KF BE PXAS30KFBE	935262384557	T	S	3	31-mrt-04	30-jun-04	None	Standard discontinuation. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
552	PXAS37KBA	PXAS37KBA	935262377529	N	S	3	31-mrt-04	30-jun-04	PXAS37KBA	Standard Discontinuation. See Replacement 12nc 935262377512. Packing option discontinuation. Device still available in Tubes	
553	PXAS37KFA	PXAS37KFA	935262378529	N	S	3	31-mrt-04	30-jun-04	PXAS37KFA	Packing option discontinuation. Device still available in Tubes. See Replacement 12nc 935262378512. Consult Marketing	
554	RS1A	MEDIUM POWER RECTIFIER	934056136115	T	M	3	31-dec-03	30-jun-04	None	Standard Discontinuation. No Replacement Available. Consult Marketing.	
555	RS1B	MEDIUM POWER RECTIFIER	934056135115	T	M	3	31-dec-03	30-jun-04	None	Standard Discontinuation. No Replacement Available. Consult Marketing.	
556	RS1D	MEDIUM POWER RECTIFIER	934056134115	T	M	3	31-dec-03	30-jun-04	BYD37D	Standard Discontinuation. See Replacement. Consult Marketing	
557	S1A	MEDIUM POWER RECTIFIER	934056129115	T	M	3	31-dec-03	30-jun-04	None	Standard Discontinuation. No Replacement Available. Consult Marketing.	
558	S1B	MEDIUM POWER RECTIFIER	934056128115	T	M	3	31-dec-03	30-jun-04	None	Standard Discontinuation. No Replacement Available. Consult Marketing.	
559	S1K	MEDIUM POWER RECTIFIER	934056131115	T	M	3	31-dec-03	30-jun-04	BYD17K	Standard Discontinuation. See Replacement. Consult Marketing	
560	S83C752-1N28/CV45	51 FAMILY CMOS ROM - 83C752	935137380112	T	S	2	31-mrt-04	30-jun-04	None	Limited Availability. Consult Marketing	
561	SAA1500T/N1	SAA1500T D	BATTERY MANAGEMENT	935043360112	T	C	2	30-jun-03	30-sep-03	None noted	Limited Availability. Process Terminated by Fab. Consult sales & marketing.
562	SAA1500T/N1	BATTERY MANAGEMENT	935043360118	T	C	2	30-jun-03	30-sep-03	None noted	Limited Availability. Process Terminated by Fab. Consult sales & marketing.	
563	SAA2502H	SAA2502H B	DIG. AUDIO COMPR/MISC.(SOTON)	935212880551	T	S	3	31-mrt-04	30-jun-04	None	Standard Discontinuation. Consult Marketing
564	SAA2502H	SAA2502H B	DIG. AUDIO COMPR/MISC.(SOTON)	935212880557	T	S	3	31-mrt-04	30-jun-04	None	Standard Discontinuation. Consult Marketing
565	SAA7201H/B/C2	SAA7201H/B BB	DVB-SOURCE DECODING (CAEN)	935260922551	T	S	3	31-mrt-04	30-jun-04	SAA7215HS/C6	Standard end of life. See replacement
566	SAA7201H/B/C2	SAA7201H/B BB	DVB-SOURCE DECODING (CAEN)	935260922557	T	S	3	31-mrt-04	30-jun-04	SAA7215HS/C6	Standard end of life. See replacement
567	SAA7201H/C3	SAA7201H BB	DVB-SOURCE DECODING (CAEN)	935262631551	T	S	3	31-mrt-04	30-jun-04	SAA7215HS/C6	Standard end of life. See replacement
568	SAA7212H/C1	SAA7212H BB	DVB-SOURCE DECODING (CAEN)	935260616557	T	S	2	1-sep-03	31-dec-03	SAA7215HS/C6	Limited Availability. Process terminated by Fab. See replacement
569	SAA7214H/C1	SAA7214H BF	BASIC-TYPENR NOT USED	935262416551	T	S	3	31-mrt-04	30-jun-04	SAA7240HS/C3	Standard end of life. See replacement
570	SAA7214H/C1	SAA7214H BF	BASIC-TYPENR NOT USED	935262416557	T	S	3	31-mrt-04	30-jun-04	SAA7240HS/C3	Standard end of life. See replacement
571	SAA7214HS/C2	TRANSPORT MPEG2	935268320551	T	S	3	31-mrt-04	30-jun-04	SAA7240HS/C3	Standard end of life. See replacement	

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments
572	SAA7214HS/C2	TRANSPORT MPEG2	935268320557	T	S	3	31-mrt-04	30-jun-04	SAA7240HS/C3	Standard end of life. See replacement
573	SAA7215HS/C3	DIVA3 C4	935266894551	T	S	1	30-jun-03	30-jun-03	SAA7215HS/C6	Non-Manufacturable. See successor part
574	SAA7215HS/C3	DIVA3 C4	935266894557	T	S	1	30-jun-03	30-jun-03	SAA7215HS/C6	Non-Manufacturable. See replacement part
575	SAA7216HS/C2	DIVA3 C4	935267048551	T	S	1	30-jun-03	30-jun-03	SAA7216HS/C5	Non-Manufacturable. See replacement part
576	SAA7216HS/C2	DIVA3 C4	935267048557	T	S	1	30-jun-03	30-jun-03	SAA7216HS/C5	Non-Manufacturable. See replacement part
577	SAA7240HS/C2	SAA7240HS BF DEMUX/DESCRAMBLR/MIP S WITH ICAM	935267416551	T	S	1	30-jun-03	30-jun-03	SAA7240HS/C3	Non-Manufacturable. See replacement part
578	SAA7240HS/C2	SAA7240HS BF DEMUX/DESCRAMBLR/MIP S WITH ICAM	935267416557	T	S	1	30-jun-03	30-jun-03	SAA7240HS/C3	Non-Manufacturable. See replacement part
579	SAA7356HL	SAA7356HL BE SPB2	935264570557	T	S	3	31-mrt-04	30-jun-04	None	Standard Discontinuation. Consult Marketing
580	SAA7356HL/M0B	SAA7356M0B BE SPB2	935269256557	T	S	3	31-mrt-04	30-jun-04	None	Standard Discontinuation. Consult Marketing
581	SAA7357EL/M0C	SCORCHER	935271833557	T	S	2	30-mrt-04	30-jun-04	None	Limited Supply. Consult Marketing
582	SAA7373GP/M1	SAA7373GP BG COMPACT DISC SYSTEMS (SOTON)	935221850557	N	S	3	31-mrt-04	30-jun-04	None	Standard Discontinuation. Consult Marketing
583	SAA7377GP/M1	SAA7377 BG COMPACT DISC SYSTEMS (SOTON)	935221840557	N	S	3	31-mrt-04	30-jun-04	SAA7377GP/M1	Standard Discontinuation. See Replacement 12nc 935221840518
584	SAA7392HL/M3	SAA7392HL BE COMPACT DISC SYSTEMS (SOTON)	935263368557	T	S	2	30-sep-03	31-dec-03	None	Limited Availability. Consult Marketing. Diffusion process discontinued in wafer fab
585	SAA7392HL/M3B	COMPACT DISC SYSTEMS (SOTON)	935267878557	T	S	2	30-sep-03	31-dec-03	None	Diffusion process discontinued by wafer fat
586	SAA7399HL/M2A	SAA7399HL BE COMPACT DISC SYSTEMS (SOTON)	935263660557	T	S	2	30-sep-03	31-dec-03	None	Diffusion process discontinued by wafer fat
587	SAA7785HT/4	SAA7785/4 B SAA7785H	935267640557	T	M	1	30-jun-03	30-jun-03	None	Non-Manufacturable. Consult Marketing
588	SAA7810HL/E/M3B	IGUANA	935271835557	T	S	1	30-jun-03	30-jun-03	None	Non-Manufacturable. Consult Marketing
589	SAA7849HL	IGUANA 2.9	935270441557	T	S	3	31-mrt-04	30-jun-04	None	Standard Discontinuation. Consult Marketing
590	SAA7849HL/M0A	IGUANA 2.9	935271860557	T	S	3	31-mrt-04	30-jun-04	None	Standard Discontinuation. Consult Marketing
591	SAA7850E	CENTAURUS	935271378557	T	S	1	30-jun-03	30-jun-03	PNX7850E/Z/M1D	Non-Manufacturable. See Replacement

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
592	SC80C451CGA68	SC80C451CG A68	51 FAMILY CMOS ROML. - 80C451	935019640512	T	S	2	30-mrt-04	30-jun-04	None	Limited Availability. Consult Marketing
593	SC83C51CGA44/CV	CV3250 A44	SC83C51	935136380518	T	S	1	30-jun-03	30-jun-03	None	Non-manufacturable. Consult Marketing
594	SI9925DY		<=30V N CHANNEL TRENCHFET	934056384118	T	M	1	30-jun-03	30-jun-03	SI9936DY	No last time buy possible. Consult Marketing
595	SI9956DY		<=30V N CHANNEL TRENCHFET	934056386118	T	M	1	30-jun-03	30-jun-03	SI9936DY	No last time buy possible. Consult Marketing
596	SL11CS3101U/N5D	SL11311UN5 CU	I-CODE	935267050025	N	M	1	30-jun-03	30-jun-03	None noted - See Comments	Will be replaced by Replacment 12hc 935267050006. Consult Marketing.
597	SZA1000H/K1		ASIC	935223360557	T	C	2	29-aug-03	31-dec-03	None	Limited Availability. Consult Marketing
598	TDA4821P/V1		BASIC-TYPENR NOT USED	935262779112	T	C	2	30-mrt-04	30-jun-04	None	Limited Availability. Consult Marketing
599	TDA4822PS/V1/M5		COSMIC	935267938112	T	C	2	30-mrt-04	30-jun-04	None	Limited Availability. Consult Marketing
600	TDA4841PS/V5		DEFLECTION CONTROLLER	935271526112	T	S	2	30-mrt-04	30-jun-04	None	Limited Supply. Consult Marketing
601	TDA4856/V3/S1		VISION SYNC. COMBI PS (HBURG)	935269535112	T	S	1	30-jun-03	30-jun-03	None	Non-Manufacturable. Consult Marketing
602	TDA4856/V5		VISION SYNC. COMBI PS (HBURG)	935272530112	T	S	1	30-jun-03	30-jun-03	None	Non-Manufacturable. See replacement part
603	TDA4858/V3		Economy autosync deflection contr.	935260576112	T	S	2	30-mrt-04	30-jun-04	None	Limited Availability. Consult Marketing
604	TDA4859PS/V3		DEFLECTION CONTROLLER	935267454112	T	C	1	30-jun-03	30-jun-03	None	Non-Manufacturable. Consult Marketing
605	TDA4859PS/V5		DEFLECTION CONTROLLER	935271517112	T	C	1	30-jun-03	30-jun-03	None	Non-Manufacturable. See Replacement
606	TDA4886/V1	TDA4886 N	VISION SYNC. COMBI PS (HBURG)	935261372112	T	C	1	30-jun-03	30-jun-03	None	Non-Manufacturable. Consult Marketing
607	TDA4886/V1/S1		VISION SYNC. COMBI PS (HBURG)	935270518112	T	S	2	30-mrt-04	30-jun-04	None	Limited Availability. Consult Marketing
608	TDA4886/V2	TDA4886 N	VISION SYNC. COMBI PS (HBURG)	935266857112	T	S	2	30-mrt-04	30-jun-04	None	Limited Availability. Consult Marketing
609	TDA4886/V2/S1		VISION SYNC. COMBI PS (HBURG)	935270541112	T	S	2	30-mrt-04	30-jun-04	None	Limited Availability. Consult Marketing
610	TDA4886A/V1	TDA4886A N	VISION SYNC. COMBI PS (HBURG)	935261628112	T	S	2	30-mrt-04	30-jun-04	None	Limited Availability. Consult Marketing
611	TDA5140AU/C1	XTDA5140AU CA	VCR MOTOR CONTROL (CAEN)	935225360005	T	S	3	31-mrt-04	30-jun-04	TDA5140AT	Standard Discontinuation. See Replacement. Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
612	TDA5145AU/C3	XTDA5145AU CA	HDD MOTOR CONTROL (CAEN)	935225460005	T	S	3	31-mrt-04	30-jun-04	TDA5145TS	Standard Discontinuation. See Replacement. Consult Marketing
613	TDA6403M/C3		TERRESTR. TUNER MOPLL (CAEN)	935262628118	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
614	TDA6404TS/C1		TERRESTR. TUNER MOPLL (CAEN)	935250380112	N	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
615	TDA6405TS/C1		TERRESTR. TUNER MOPLL (CAEN)	935251700118	N	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
616	TDA6660TT/C1		3 BAND MIXER-OSCILLATOR	935270785512	T	S	3	31-mrt-04	30-jun-04	None	Standard Discontinuation. Consult Marketing
617	TDA6660TT/C1		3 BAND MIXER-OSCILLATOR	935270785518	T	S	3	31-mrt-04	30-jun-04	None	Standard Discontinuation. Consult Marketing
618	TDA8006H/C117	TDA8006H17 B	CT READER ICS ENH.	935269305518	T	M	2	30-dec-03	30-mrt-04	TDA8006H/C325;	See replacement part 12nc 935272770557
619	TDA8031HL/C103		CT READERS ICS ENH	935271723518	T	M	1	30-jun-03	30-jun-03	TDA8031HL/C106	Non-Manufacturable. See replacement part 12nc 93527289251f
620	TDA8031HL/C103		CT READERS ICS ENH	935271723551	T	M	1	30-jun-03	30-jun-03	TDA8031HL/C106	Non-Manufacturable. See replacement part 12nc 93527289251f
621	TDA8031HL/C103		CT READERS ICS ENH	935271723557	T	M	1	30-jun-03	30-jun-03	TDA8031HL/C106	Non-Manufacturable. See replacement part. See 12nc 93527285251f
622	TDA8031HL/C104		CT READERS ICS ENH	935272422518	T	M	1	30-jun-03	30-jun-03	TDA8031HL/C106	Non-Manufacturable. See replacement part. See 12nc 93527289251f
623	TDA8031HL/C104		CT READERS ICS ENH	935272422551	T	M	1	30-jun-03	30-jun-03	TDA8031HL/C106	Non-Manufacturable. See replacement part. See 12nc 93527289251f
624	TDA8031HL/C104		CT READERS ICS ENH	935272422557	T	M	1	30-jun-03	30-jun-03	TDA8031HL/C106	Non-Manufacturable. See replacement part. See 12nc 93527289251f
625	TDA8050AT/C1	TDA8050AT D	5-65MHZ QPSK TRANSM CABLE APPL.	935263633118	T	S	2	30-sep-03	31-dec-03	None noted	Limited Availability. Consult Marketing
626	TDA8050T/C1	TDA8050T D	DVB-CHANNEL DECODING (CAEN)	935250360118	T	S	2	30-sep-03	31-dec-03	None noted	Limited Availability. Consult Marketing
627	TDA8083H/C1		QPSK DEMOD. DECODER SDD SYMBOLRANGE	935263382518	T	S	2	30-sep-03	31-dec-03	None noted	Limited Availability. Consult Marketing
628	TDA8083H/C1		QPSK DEMOD. DECODER SDD SYMBOLRANGE	935263382557	T	S	2	30-sep-03	31-dec-03	None noted	Limited Availability. Consult Marketing
629	TDA8376H/N2		MID-END TV PROCESSING	935089530518	T	S	1	30-jun-03	30-jun-03	None noted	Non-manufacturable, Consult Marketing
630	TDA8395T/N1		VISION MISCELLANEOUS (CONT.)	935089280118	T	S	1	30-jun-03	30-jun-03	TDA8395T/N3	Non-manufacturable, See Replacement
631	TDA8706AM/C3	TDA8706AM DB	CONVERTERS (CAEN)	935260792512	N	S	1	30-jun-03	30-jun-03	None noted	Non-manufacturable, Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
632	TDA8706AM/C3		CONVERTERS (CAEN)	935260792112	T	S	2	30-jun-03	30-jun-04	TDA8710	Limited Availability. See Replacement
633	TDA8706AM/C3		CONVERTERS (CAEN)	935260792118	T	S	2	30-jun-03	30-jun-04	TDA8710	Limited Availability. See Replacement
634	TDA8706AM/C3	TDA8706AM DB	CONVERTERS (CAEN)	935260792518	T	S	2	30-jun-03	30-jun-04	TDA8710	Limited Availability. See Replacement
635	TDA8745/N2	TDA8745 N	Satellite sound crt. with I2C-bus	935199060112	T	M	3	31-dec-03	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
636	TDA8763AM/3/C4	TDA8763AM3 DB	CONVERTERS (CAEN)	935261120112	T	S	2	30-jun-03	30-jun-04	TDA8764CM/3/C1	Limited Availability. See Replacement
637	TDA8763AM/3/C4	TDA8763AM3 DB	CONVERTERS (CAEN)	935261120118	T	S	2	30-jun-03	30-jun-04	TDA8764CM/3/C1	Limited Availability. See Replacement
638	TDA8763AM/4/C4	TDA8763AM4 DB	CONVERTERS (CAEN)	935261121112	T	S	2	30-jun-03	30-jun-04	TDA8764CM/4/C1	Limited Availability. See Replacement
639	TDA8763AM/4/C4	TDA8763AM4 DB	CONVERTERS (CAEN)	935261121118	T	S	2	30-jun-03	30-jun-04	TDA8764CM/4/C1	Limited Availability. See Replacement
640	TDA8763AM/5/C4	TDA8763AM5 DB	CONVERTERS (CAEN)	935261122112	T	S	2	30-jun-03	30-jun-04	TDA8764CM/5/C1	Limited Availability. See Replacement
641	TDA8763AM/5/C4	TDA8763AM5 DB	CONVERTERS (CAEN)	935261122118	T	S	2	30-jun-03	30-jun-04	TDA8764CM/5/C1	Limited Availability. See Replacement
642	TDA8764AHL/6/C3		10 BITS HIGH SPEED ADC	935272205118	T	S	2	30-jun-03	30-jun-04	TDA8764CHL/6/C1	Limited Availability. See replacement
643	TDA8764AHL/6/C3		10 BITS HIGH SPEED ADC	935272205151	T	S	2	30-jun-03	30-jun-04	TDA8764CHL/6/C1	Limited Availability. See replacement
644	TDA8764ATS/6/C3		10 BITS HIGH SPEED ADC	935272204112	T	S	2	30-jun-03	30-jun-04	TDA8764CTS/6/C1	Limited Availability. See replacement
645	TDA8764ATS/6/C3		10 BITS HIGH SPEED ADC	935272204118	T	S	2	30-jun-03	30-jun-04	TDA8764CTS/6/C1	Limited Availability. See replacement
646	TDA8768AH/4/C3		12BITS HIGH SPEED ADC	935271197518	T	S	2	30-jun-03	30-jun-04	TDA8768CH/4/C1	Limited Availability. See Replacement
647	TDA8768AH/4/C3		12BITS HIGH SPEED ADC	935271197551	T	S	2	30-jun-03	30-jun-04	TDA8768CH/4/C1	Limited Availability. See Replacement
648	TDA8768AH/5/C3		12BITS HIGH SPEED ADC	935271198518	T	S	2	30-jun-03	30-jun-04	TDA8768CH/5/C1	Limited Availability. See Replacement
649	TDA8768AH/5/C3		12BITS HIGH SPEED ADC	935271198551	T	S	2	30-jun-03	30-jun-04	TDA8768CH/5/C1	Limited Availability. See Replacement
650	TDA8768AH/7/C3		12BITS HIGH SPEED ADC	935271199518	T	S	2	30-jun-03	30-jun-04	TDA8768CH/7/C1	Limited Availability. See Replacement
651	TDA8768AH/7/C3		12BITS HIGH SPEED ADC	935271199551	T	S	2	30-jun-03	30-jun-04	TDA8768CH/7/C1	Limited Availability. See Replacement

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments
652	TDA8768BH/5/C3	ADC 12-BIT 80MSPS	935272779518	T	S	2	30-jun-03	30-jun-04	TDA8768CH/5/C1	Limited Availability. See replacement
653	TDA8768BH/5/C3	ADC 12-BIT 80MSPS	935272779551	T	S	2	30-jun-03	30-jun-04	TDA8768CH/5/C1	Limited Availability. See replacement
654	TDA8768BH/8/C3	ADC 12-BIT 80MSPS	935272780518	T	S	2	30-jun-03	30-jun-04	TDA8768CH/8/C1	Limited Availability. See replacement
655	TDA8768BH/8/C3	ADC 12-BIT 80MSPS	935272780551	T	S	2	30-jun-03	30-jun-04	TDA8768CH/8/C1	Limited Availability. See replacement
656	TDA8768BH/8/C3/S1	ADC 12-BIT 80MSPS	935272781518	T	S	2	30-jun-03	30-jun-04	TDA8768CH/8/C1	Limited Availability. See replacement
657	TDA8768BH/8/C3/S1	ADC 12-BIT 80MSPS	935272781551	T	S	2	30-jun-03	30-jun-04	TDA8768CH/8/C1	Limited Availability. See replacement
658	TDA8768H/4/C2	CONVERTERS (CAEN)	935271200518	T	S	2	30-jun-03	30-jun-04	TDA8768H/4/C3	Limited Availability. See Replacement
659	TDA8768H/4/C2	CONVERTERS (CAEN)	935271200551	T	S	2	30-jun-03	30-jun-04	TDA8768H/4/C3	Limited Availability. See Replacement
660	TDA8768H/5/C2	CONVERTERS (CAEN)	935271201518	T	S	2	30-jun-03	30-jun-04	TDA8768H/5/C3	Limited Availability. See Replacement
661	TDA8768H/5/C2	CONVERTERS (CAEN)	935271201551	T	S	2	30-jun-03	30-jun-04	TDA8768H/5/C3	Limited Availability. See Replacement
662	TDA8790M/C1	TDA8790M DK CONVERTERS (CAEN)	935201160112	T	S	2	30-jun-03	30-jun-04	None noted	Limited Availability. Consult Marketing
663	TDA8790M/C1	TDA8790M DK CONVERTERS (CAEN)	935201160118	T	S	2	30-jun-03	30-jun-04	None noted	Limited Availability. Consult Marketing
664	TDA8792M/C2	CONVERTERS (CAEN)	935199880118	T	S	2	30-sep-03	31-dec-03	None noted	Limited Availability. Consult Marketing
665	TDA8792M/C2/R1	CONVERTERS (CAEN)	935216710118	T	S	2	30-sep-03	31-dec-03	None noted	Limited Availability. Consult Marketing
666	TDA8792M/C2/R1	CONVERTERS (CAEN)	935216710512	T	S	2	30-sep-03	31-dec-03	None noted	Limited Availability. Consult Marketing
667	TDA8792M/C2/R1	CONVERTERS (CAEN)	935216710518	T	S	2	30-sep-03	31-dec-03	None noted	Limited Availability. Consult Marketing
668	TDA9800T/V3	TDA9800T D VISION SOUND (HAMBURG) CONT.	935057030112	N	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation
669	TDA9802T/V3	VISION SOUND (HAMBURG) CONT.	935057050112	T	S	2	30-sep-03	31-dec-03	None noted	Limited Availability. Consult Marketing
670	TDA9802T/V3	VISION SOUND (HAMBURG) CONT.	935057050118	T	S	2	30-sep-03	31-dec-03	None noted	Limited Availability. Consult Marketing
671	TDA9810T/V2	VISION SOUND (HAMBURG) CONT.	935261075112	N	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
672	TDA9814T/V4	TDA9814T D	VISION SOUND (HAMBURG) CONT.	935260610118	T	S	2	30-sep-03	31-dec-03	None noted	Limited Availability. Consult Marketing
673	TDA9885TS/V3		ALIGNMENT FRRE VIF/SIF CIRC NEG MOD	935270551112	N	S	3	31-mrt-04	30-jun-04	TDA9885TS/V3	Standard Discontinuation. See Replacement 12nc 935270551111
674	TDA9901TS/C2		CONVERTERS (CAEN)	935271205112	T	S	2	30-jun-03	30-jun-04	None noted	Limited Availability. Consult Marketing
675	TDA9901TS/C2		CONVERTERS (CAEN)	935271205118	T	S	2	30-jun-03	30-jun-04	None noted	Limited Availability. Consult Marketing
676	TDA9965AHL/C3		12BITS FRONT-END POUR DSC	935272939118	T	S	2	30-jun-03	30-jun-04	TDA9965BHL/40/C1	Limited Availability. See replacement
677	TDA9965AHL/C3		12BITS FRONT-END POUR DSC	935272939151	T	S	2	30-jun-03	30-jun-04	TDA9965BHL/40/C1	Limited Availability. See replacement
678	TDA9965AHL/C3		12BITS FRONT-END POUR DSC	935272939157	T	S	2	30-jun-03	30-jun-04	TDA9965BHL/40/C1	Limited Availability. See replacement
679	TDA9965HL/C3		12BIT IMAGING FRONT-END 30MSPS 5V	935272592118	T	S	2	30-jun-03	30-jun-04	TDA9965BHL/30/C1	Limited Availability. See replacement
680	TDA9965HL/C3		12BIT IMAGING FRONT-END 30MSPS 5V	935272592151	T	S	2	30-jun-03	30-jun-04	TDA9965BHL/30/C1	Limited Availability. See replacement
681	TDA9965HL/C3		12BIT IMAGING FRONT-END 30MSPS 5V	935272592157	T	S	2	30-jun-03	30-jun-04	TDA9965BHL/30/C1	Limited Availability. See replacement
682	TEA1091/N2		BATTERY MANAGEMENT	935190610112	T	S	3	31-mrt-04	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
683	TEA1202TS/N1	TEA1202TS DB	DC/DC CONVERTER	935262908112	N	S	1	30-jun-03	30-jun-03	TEA1202TS/N2	See replacement part
684	TEA1202TS/N1	TEA1202TS DB	DC/DC CONVERTER	935262908118	N	S	1	30-jun-03	30-jun-03	TEA1202TS/N2	See replacement part
685	TEA1207UK/N1		DC/DC CONVERTER	935267310027	T	S	2	30-mrt-04	30-jun-04	None noted	Process terminated by Fab. Limited supply. Consult Marketing
686	TEA1211TW/N1		UP-DOWN DC/DC CONVERTER	935270249118	N	S	3	31-mrt-04	30-jun-04	TEA1211HN/N1	Standard End of Live. See Replacement
687	TEA1404TS/N2		BATTERY MANAGEMENT	935263675112	N	S	2	30-sep-03	31-dec-03	TEA1404TS/N3	Limited Availability, See Replacement
688	TEA1404TS/N2		BATTERY MANAGEMENT	935263675118	N	S	2	30-sep-03	31-dec-03	TEA1404TS/N3	Limited Availability, See Replacement
689	TEA1520P/N1	TEA1520P N	POWERPLUG	935268215112	T	S	1	30-jun-03	30-jun-03	TEA1520P/N2	Change over from /N1 to /N2. Consult Marketing.
690	TEA1520T/N1	TEA1520T D	POWERPLUG	935268216112	T	S	1	30-jun-03	30-jun-03	TEA1520T/N2	Change over from /N1 to /N2. Consult Marketing.
691	TEA1520T/N1	TEA1520T D	POWERPLUG	935268216118	T	S	1	30-jun-03	30-jun-03	TEA1520T/N2	Change over from /N1 to /N2. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
692	TEA1521P/N1	TEA1521P N	POWERPLUG	935264421112	T	S	1	30-jun-03	30-jun-03	TEA1521P/N2	Change over from /N1 to /N2. Consult Marketing.
693	TEA1521T/N1	TEA1521T D	POWERPLUG	935263914112	T	S	1	30-jun-03	30-jun-03	TEA1521T/N2	Change over from /N1 to /N2. Consult Marketing.
694	TEA1521T/N1	TEA1521T D	POWERPLUG	935263914118	T	S	1	30-jun-03	30-jun-03	TEA1521T/N2	Change over from /N1 to /N2. Consult Marketing.
695	TEA1522P/N1	TEA1522P N	POWERPLUG	935263915112	T	S	1	30-jun-03	30-jun-03	TEA1522P/N2	Change over from /N1 to /N2. Consult Marketing.
696	TEA1522T/N1	TEA1522T D	POWERPLUG	935263916112	T	S	1	30-jun-03	30-jun-03	TEA1522T/N2	Change over from /N1 to /N2. Consult Marketing.
697	TEA1522T/N1	TEA1522T D	POWERPLUG	935263916118	T	S	1	30-jun-03	30-jun-03	TEA1522T/N2	Change over from /N1 to /N2. Consult Marketing.
698	TEA1523P/N1	TEA1523P N	POWERPLUG	935263917112	T	S	1	30-jun-03	30-jun-03	TEA1523P/N2	Change over from /N1 to /N2. Consult Marketing.
699	TEA1523T/N1	TEA1523T D	POWERPLUG	935263918112	T	S	1	30-jun-03	30-jun-03	TEA1523P/N2 or TEA1522T/N2	TEA1523 is not available anymore in SO package. Consult Marketing
700	TEA1523T/N1	TEA1523T D	POWERPLUG	935263918118	T	S	1	30-jun-03	30-jun-03	TEA1523P/N2 or TEA1522T/N2	TEA1523 is not available anymore in SO package. Consult Marketing
701	TEA1524P/N1	TEA1524P N	POWERPLUG	935268202112	T	S	1	30-jun-03	30-jun-03	TEA1524P/N2	Change over from /N1 to /N2. See Replacement. Consult Marketing.
702	TEA1601T/N2		POWER CONVERSION	935263127112	T	C	1	30-jun-03	30-jun-03	TEA1601T/N5	Non-manufacturable. See Replacement. Consult Marketing
703	TEA1601T/N2		POWER CONVERSION	935263127118	T	C	1	30-jun-03	30-jun-03	TEA1601T/N5	Non-manufacturable. See Replacement. Consult Marketing
704	TEA6320T/V1/S1		AUDIO POWER MISCELL. (HAMBURG)	935152800118	T	S	2	31-mrt-04	30-jun-04	None Noted	Limited Availability. Consult Marketing
705	TEA6322T/V1		AUDIO POWER MISCELL. (HAMBURG)	935188800112	T	M	2	30-dec-03	30-jun-04	None	Limited Availability. Consult Marketing
706	TEA6322T/V1		AUDIO POWER MISCELL. (HAMBURG)	935188800118	T	M	2	30-dec-03	30-jun-04	None	Limited Availability. Consult Marketing
707	TJA1050T/S900		HIGH SPEED CAN TRANSCEIVER	935273079118	N	C	1	30-jun-03	30-jun-03	TJA1050T	Non-Manufacturable. See replacement part. Consult Marketing
708	TZA1000T/N3		ASIC	935210150118	T	C	2	29-aug-03	31-dec-03	None	Limited Availability. Consult Marketing
709	TZA1027HL/V2		COMPACT DISC SYSTEMS (SOTON)	935262065518	T	S	3	31-mrt-04	30-jun-04	None	Standard Discontinuation. Consult Marketing
710	TZA1032UK		LADIC	935269546026	T	S	2	30-mrt-04	30-jun-04	TZA1032UK/M4	Limited Availability. See Replacement
711	TZA1032UK		LADIC	935269546028	T	S	2	30-mrt-04	30-jun-04	TZA1032UK/M4	Limited Availability. See Replacement

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
712	TZA1036HL/M1		DVDALAS2 AUTOMOTIVE	935268018118	T	S	2	30-mrt-04	30-jun-04	TZA1036HL/M1A	Limited Availability. See Replacement
713	TZA3001AHL/C4	TZA3001AHL BE	TRANSMISSION AND ASICS	935263839118	T	S	2	30-sep-03	31-dec-03	TZA3047	Limited Availability. See Replacement
714	TZA3001AHL/C4	TZA3001AHL BE	TRANSMISSION AND ASICS	935263839151	T	S	2	30-sep-03	31-dec-03	TZA3047	Limited Availability. See Replacement
715	TZA3031AHL/C4	TZA3031AHL BE	LDR STM1	935263835118	T	S	2	30-sep-03	31-dec-03	TZA3047	Limited Availability. See Replacement
716	TZA3031AHL/C4	TZA3031AHL BE	LDR STM1	935263835151	T	S	2	30-sep-03	31-dec-03	TZA3047	Limited Availability. See Replacement
717	TZA3041AHL/C4	TZA3041AHL BE	LDR GE/FC	935263837118	T	S	2	30-sep-03	31-dec-03	TZA3047	Limited Availability. See Replacement
718	TZA3041AHL/C4	TZA3041AHL BE	LDR GE/FC	935263837151	T	S	2	30-sep-03	31-dec-03	TZA3047	Limited Availability. See Replacement
719	UAA1570HL/V1	UAA1570HL BE	GPS (HAMBURG)	935261401518	T	S	1	30-jun-03	30-jun-03	None	Non-manufacturable. Consult Marketing
720	UAA1570HL/V1	UAA1570HL BE	GPS (HAMBURG)	935261401557	T	S	1	30-jun-03	30-jun-03	None	Non-manufacturable. Consult Marketing
721	UAA3535HL/C1		POLYPHASE EFM	935264155518	T	S	1	30-jun-03	30-jun-03	UAA3535HL/C1/M2	Non-manufacturable. See Replacement
722	UAA3535HL/C1	UAA3535HL BE	POLYPHASE EFM	935264155118	T	S	2	30-mrt-04	30-jun-04	UAA3535HL/C1/M2	Limited Availability. See Replacement
723	UAA3535HL/C1/M1		POLYPHASE EFM	935272252118	T	S	1	30-jun-03	30-jun-03	UAA3535HL/C1/M2	Non-Manufacturable. See Replacement
724	UAA3536HN/C1		A1+TRANSCEIVER CHIP	935268652118	T	S	1	30-jun-03	30-jun-03	UAA3536HN/C3	Non-Manufacturable. Consult Marketing
725	UAA3536HN/C1		A1+TRANSCEIVER CHIP	935268652518	T	S	1	30-jun-03	30-jun-03	UAA3536HN/C3	Non-Manufacturable. Consult Marketing
726	UBA2006T/N3	UBA2006T D	BATTERY MANAGEMENT	935267355112	T	C	3	31-mrt-04	30-jun-04	None	Standard Discontinuation
727	UBA2006T/N3	UBA2006T D	BATTERY MANAGEMENT	935267355118	T	C	3	31-mrt-04	30-jun-04	None	Standard Discontinuation
728	UBA2032T/N1	UBA2032T D	LIGHTING IC	935264054118	T	S	1	30-jun-03	30-jun-03	UBA2032T/N2	Change over from /N1 to /N2. Consult Marketing.
729	UBA2032TS/N1	UBA2032TS DB	LIGHTING IC	935264055118	T	S	1	30-jun-03	30-jun-03	UBA2032TS/N2	Change over from /N1 to /N2. Consult Marketing.
730	UBA2032TS/N1/S1		LIGHTING IC	935269686118	T	C	1	30-jun-03	30-jun-03	UBA2032TS/N2/S1	Change over from /N1 to /N2. Consult Marketing.
731	UBA2040ATT/N1	CE4853 DV	EL LUMINESCENT LAMP IC	935268889118	T	C	1	30-jun-03	30-jun-03	UBA2040ATT/N2	Change over from /N1 to /N2. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
732	UBA2040TT/N1	CE4852 DP	EL LUMINESCENT LAMP DRIVER IC	935268442118	T	C	1	30-jun-03	30-jun-03	UBA2040TT/N2	Change over from /N1 to /N2. Consult Marketing.
733	UBA8073HL/C4/S30		BASIC-TYPENR NOT USED	935272095118	N	S	3	31-mrt-04	30-jun-04	UBA8073HL/C4	Standard End of Life. See replacement
734	UCB1300BE	UCB1300 BE	ICS	935261133528	T	C	1	30-jun-03	30-jun-03	None	Non-Manufacturable. Consult Marketing
735	UCB1300BE	UCB1300 BE	ICS	935261133551	T	C	1	30-jun-03	30-jun-03	None	Non-Manufacturable. Consult Marketing
736	UCB1300BE	UCB1300 BE	ICS	935261133557	T	C	1	30-jun-03	30-jun-03	None	Non-Manufacturable. Consult Marketing
737	UDA1309H/N1	UDA1309H B	AUDIO DATA CONVERSION	935218510518	T	M	3	31-dec-03	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
738	UDA1309H/N1	UDA1309H B	AUDIO DATA CONVERSION	935218510551	T	M	3	31-dec-03	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
739	UDA1309H/N1	UDA1309H B	AUDIO DATA CONVERSION	935218510557	T	M	3	31-dec-03	30-jun-04	None noted	Standard Discontinuation. Consult Marketing
740	UDA1320ATS/N2	UDA1320ATS DK	AUDIO DATA CONVERSION	935261242112	T	M	3	31-dec-03	30-jun-04	UDA1330ATS/N2	Standard Discontinuation. See Replacement
741	UDA1320ATS/N2	UDA1320ATS DK	AUDIO DATA CONVERSION	935261242118	T	M	3	31-dec-03	30-jun-04	UDA1330ATS/N2	Standard Discontinuation. See Replacement
742	UDA1321PS/N101	UDA1321PS NB	AUDIO DATA CONVERSION	935261616112	T	M	3	31-dec-03	30-jun-04	UDA1321T/N101	Standard Discontinuation. See Replacement
743	UDA1328T/N1	UDA1328T D	AUDIO DATA CONVERSION	935261617112	T	M	2	30-sep-03	31-dec-03	None noted	Limited parts available. Consult Marketing
744	UDA1328T/N1	UDA1328T D	AUDIO DATA CONVERSION	935261617118	T	M	2	30-sep-03	31-dec-03	None noted	Limited parts available. Consult Marketing
745	UDA1335H/N1/S35		AUDIO DATA CONVERSION	935262445518	T	C	1	30-jun-03	30-jun-03	None	Non-manufacturable, Consult Marketing
746	UDA1335H/N1/S35		AUDIO DATA CONVERSION	935262445551	T	C	1	30-jun-03	30-jun-03	None	Non-manufacturable, Consult Marketing
747	UDA1335H/N1/S35		AUDIO DATA CONVERSION	935262445557	T	C	1	30-jun-03	30-jun-03	None	Non-manufacturable, Consult Marketing
748	UDA1350AH/N2	UDA1350AH B	VOLTAGE REGULATOR	935263335551	T	M	3	31-dec-03	30-jun-04	UDA1352TS	Standard Discontinuation. See replacement
749	UDA1350AH/N2	UDA1350AH B	VOLTAGE REGULATOR	935263335557	T	M	3	31-dec-03	30-jun-04	UDA1352TS	Standard Discontinuation. See replacement
750	UDA1350ATS/N2	UDA1350ATS D	SPDIF-DAC	935263334112	T	M	3	31-dec-03	30-jun-04	UDA1352TS	Standard Discontinuation. See replacement
751	UDA1350ATS/N2	UDA1350ATS D	SPDIF-DAC	935263334118	T	M	3	31-dec-03	30-jun-04	UDA1352TS	Standard Discontinuation. See replacement

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
752	US1B		MEDIUM POWER RECTIFIER	934056145115	T	M	3	31-dec-03	30-jun-04	None	Standard Discontinuation. No Replacement Available
753	US1D		MEDIUM POWER RECTIFIER	934056144115	T	M	3	31-dec-03	30-jun-04	None	Standard Discontinuation. No Replacement Available
754	V06040A2	V06040A2 B	V06040A2	935266452557	T	C	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. Consult Marketing
755	V22100DVB	V22100DVB SD	V22100DVB	935265940112	T	M	1	30-jun-03	30-jun-03	None noted	Non-manufacturable. Consult Marketing
756	VAS96011-2	VAS96011-2 B	VAS96011-2	935266074557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
757	VAS96011-3	VAS96011-3 B	VAS96011-3	935266076557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
758	VAS96011-4	VAS96011-4 B	VAS96011-4	935266078557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
759	VAS96011-5	VAS96011-5 B	VAS96011-5	935266080557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
760	VES1820-4	VES1820-4 B	VES1820-4	935264529557	T	S	2	30-sep-03	31-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
761	VES1848-2	VES1848-2 B	VES1848-2	935264535557	T	S	2	30-sep-03	31-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
762	VES1993A2	VES1993A2 B	VES1993A2	935264539557	T	S	2	30-sep-03	31-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
763	VM06252-A	VM06252-A B	VM06252-A	935265853557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
764	VM14119-A	VM14119-A P	VM14119-A	935265222157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
765	VM14160-2		ASIC	935272314157	T	S	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
766	VM14160-C		ASIC	935265240157	T	S	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
767	VM14221-B	VM14221-B P	VM14221-B	935265218157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
768	VM14221-C	VM14221-C P	VM14221-C	935266963157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
769	VM21105-A	VM21105-A B	VM21105-A	935265404557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
770	VM21376-A	VM21376-A Q	VM21376-A	935265487157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
771	VM21509-A	VM21509-A P	VM21509-A	935265866157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
772	VM21528-A	VM21528-A Q	VM21528-A	935265406157	T	C	2	30-mrt-04	30-jun-04	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
773	VM21668AA	VM21668AA B	VM21668AA	935265252557	T	C	2	30-jun-03	31-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
774	VM21672C5	VM21672C5 E	VM21672C5	935269084528	T	M	2	30-jun-03	30-jun-05	None	Limited Availability. Special Die Supply Program applies.
775	VM21672C6	VM21672C6 E	VM21672C6	935269196557	T	M	2	30-jun-03	30-jun-05	None	Limited Availability. Special Die Supply Program applies.
776	VMS110-E	VMS110-E A	VMS110-E	935265129112	T	M	2	30-jun-03	12-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
777	VMS110-E1	VMS110-E1 A	VMS110-E1	935270326518	T	M	2	30-jun-03	12-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
778	VMS113-A	VMS113-A A	VMS113-A	935265132112	T	M	2	30-jun-03	12-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
779	VMS113-B	VMS113-B A	VMS113-B	935265873518	T	M	2	30-jun-03	12-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
780	VMS115-2	VMS115-2 B	VMS115-2	935265134557	T	M	2	30-jun-03	12-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
781	VMS120-2	VMS120-2 B	VMS120-2	935265136557	T	M	2	30-jun-03	12-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
782	VNS14Q575-FC	V14Q575-FC B	VNS14Q575-FC	935265033557	T	M	2	30-jun-03	12-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
783	VNS67502-3	VNS67502-3 B	VNS67502-3	935265061557	T	M	2	30-jun-03	12-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
784	VNS67800A6	VNS67800A6 E	VNS67800A6	935269123557	T	M	2	30-jun-03	12-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
785	VP05797A2		ASIC	935265091518	T	S	1	30-jun-03	30-jun-03	None	Non Manufacturable. San Antonio plant closure, commercially impractical conditions apply. Consult Marketing
786	VP06106B2		ASIC	935265099518	T	S	1	30-jun-03	30-jun-03	None	Non Manufacturable. San Antonio plant closure, commercially impractical conditions apply. Consult Marketing
787	VP06360-2	VP06360-2 A	VP06360-2	935265103112	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
788	VP06388-2	VP06388-2 A	VP06388-2	935265491112	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
789	VP06473-2	VP06473-2 V	VP06473-2	935265340157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
790	VP06904B5	VP06904B5 B	VP06904B5	935265880557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
791	VP17139-2	VP17139-2 Q	VP17139-2	935265341157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
792	VP17171-3	VP17171-3 A	VP17171-3	935264923518	T	C	1	30-jun-03	30-jun-03	None noted	Non-manufacturable. Consult Marketing
793	VP21007-5	VP21007-5 B	VP21007-5	935265885557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
794	VP21015-2	VP21015-2 B	VP21015-2	935264773557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
795	VP21095-2	VP21095-2 B	VP21095-2	935266031557	T	C	1	30-jun-03	30-jun-03	None noted	Non-manufacturable. Consult Marketing
796	VP21176A2	VP21176A2 B	VP21176A2	935266039557	T	C	1	30-jun-03	30-jun-03	None noted	Non-manufacturable. Consult Marketing
797	VP21176A3	VP21176A3 B	VP21176A3	935266227528	T	C	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. Consult Marketing
798	VP21176A4	VP21176A4 B	VP21176A4	935266229528	T	C	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. Consult Marketing
799	VP21227A2	VP21227A2 B	VP21227A2	935264933557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
800	VP21453C2	VP21453C2 E	VP21453C2	935266218557	T	M	2	30-jun-03	12-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
801	VP21454-2	VP21454-2 B	VP21454-2	935265016557	T	M	2	30-jun-03	30-jun-05	None	Limited Availability. Consult Marketing.Special Die Supply Program applies. San Antonio ASIC last time buy
802	VP21505-4	VP21505-4 E	VP21511-2	935266691557	T	M	2	30-jun-03	12-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
803	VP21545-2		VP21545-2	935265164551	T	C	2	30-jun-03	31-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
804	VP21545-2	VP21545-2 B	VP21545-2	935265164557	T	C	2	30-jun-03	31-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
805	VP21680-2	VP21680-2 B	VP21680-2	935268052557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
806	VP21680A2	VP21680A2 B	VP21680A2	935265216557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
807	VP21742-2	VP21742-2 E	VP21742-2	935265890557	T	M	2	30-jun-03	12-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
808	VP21786-2	VP21786-2 E	VP21786-2	935265234557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
809	VP21786A2	VP21786A2 E	VP21786A2	935265711557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
810	VP21786B1	VP21786B1 E	VP21786B1	935266689157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
811	VP21786B2	VP21786B2 E	VP21786B2	935266685557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
812	VP21787A2	VP21787A2 E	VP21787A1	935265237557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
813	VP21787B2	VP21787B2 E	VP21787B2	935265712557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
814	VP21787C2	VP21787C2 E	VP21787C2	935266687557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
815	VP21855B2	VP21855B2 E	VP21855B1	935267523557	T	M	2	30-jun-03	12-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
816	VP21878B2	VP21878B2 B	VP21878B2	935266056557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
817	VP21884A2	VP21884A2 E	VP21884A2	935265255557	T	M	2	30-jun-03	30-jun-05	None	Limited Availability. Consult Marketing.Special Die Supply Program applies. San Antonio ASIC Last Time Buy
818	VP21911A2	VP21911A2 B	VP21911A2	935265262557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
819	VP21956-3	VP21956-3 E	VP21956-3	935267055528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
820	VP21999-2	VP21999-2 E	VP21999-2	935265843557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
821	VP22073-2	VP22073-2 E	VP22073-2	935266625557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
822	VP22086-2	VP22086-2 E	VP22086-2	935265788557	T	M	2	30-jun-03	12-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
823	VP22087-2	VP22087-2 E	VP22087-2	935265790557	T	M	2	30-jun-03	30-jun-05	None	Limited Availability. Consult Marketing. Special Die Supply Program applies. San Antonio Plant Closure
824	VP22089-3	VP22089-3 E	VP22089-3	935268685528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
825	VP22089-5		VP22089-5	935273412528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
826	VP22093-2	VP22093-2 B	VP22093-2	935267203557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
827	VP22110-1	VP22110-1 E	VP22110-1	935265716157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
828	VP22110-2	VP22110-2 E	VP22110-2	935265809557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
829	VP22110A1	VP22110A1 E	VP22110A1	935266694157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
830	VP22110A2	VP22110A2 E	VP22110A2	935266695557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
831	VP22110C1	VP22110C1 E	VP22110C1	935267348157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
832	VP22110C2	VP22110C2 E	VP22110C2	935267349557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
833	VP22110D1	VP22110D1 E	VP22110D1	935267880157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
834	VP22110D2	VP22110D2 E	VP22110D2	935267881557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
835	VP22110D3	VP22110D3 E	VP22110D3	935268930528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
836	VP22110D5		VP22110D5	935273418528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
837	VP22110E2	VP22110E2 E	VP22110E2	935269703528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
838	VP22110E3	VP22110E3 E	VP22110E3	935269884557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
839	VP22110E5		VP22110E5	935273416528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
840	VP22112-2	VP22112-2 E	VP22112-2	935265811557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
841	VP22112-3		VP22112-3	935273295528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
842	VP22127-2	VP22127-2 E	VP22127-2	935267823557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
843	VP22127A2	VP22127A2 E	VP22127A2	935268591557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
844	VP22127C2	VP22127C2 E	VP22127C2	935268929557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
845	VP22127D2	VP22127D2 E	VP22127D1	935269639557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
846	VP22148-2	VP22148-2 E	VP22148-2	935266670557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
847	VP22148A2	VP22148A2 E	VP22148A2	935266936557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
848	VP22148B2	VP22148B2 E	VP22148B2	935267200557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
849	VP22148B3	VP22148B3 E	VP22148B3	935267201528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
850	VP22173-2	VP22173-2 E	VP22173-2	935267205557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
851	VP22176-2	VP22176-2 E	VP22176-2	935267142557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
852	VP22176-3	VP22176-3 E	VP22176-3	935269251528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
853	VP22176-5		VP22176-5	935270069528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
854	VP22186-2	VP22186-2 E	VP22186-2	935267661557	T	C	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. San Antonio Plant Closure. Consult Marketing. See 3/28/03 CPCN Notice.
855	VP22186-5	VP22186-5 E	VP22186-5	935267664557	T	C	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. San Antonio Plant Closure. Consult Marketing. See 3/28/03 CPCN Notice.
856	VP22186-6	VP22186-6 E	VP22186-6	935267788557	T	C	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. San Antonio Plant Closure. Consult Marketing. See 3/28/03 CPCN Notice.
857	VP22221-2	VP22221-2 E	VP22221-2	935267643557	T	M	2	30-jun-03	12-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
860	VP22230-2	VP22230-2 B	VP22230-2	935268520557	T	C	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. Consult Marketing
861	VP22230A2	VP22230A2 B	VP22230A2	935269931557	T	C	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. Consult Marketing
862	VP22237-4	VP22237-4 E	VP22237-4	935268070557	T	M	2	30-jun-03	30-jun-05	None	Limited Availability. Special Die Supply Program applies. San Antonio Plant Closure. See Philips 3/28/03 CPCN Notice
863	VP22241-2	VP22241-2 E	VP22241-2	935267845557	T	C	1	30-jun-03	30-jun-03	VP22351-2	See Replacement. Consult Marketing. Project called Tarac_S (ROP1016173CP1A) from 24/01/2001.
864	VP22256-2	VP22256-2 E	VP22256-2	935268198557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
865	VP22256A2	VP22256A2 E	VP22256A2	935268315557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
866	VP22259A2	VP22259A2 B	VP22259A2	935269296557	T	M	2	30-jun-03	12-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
867	VP22260-2	VP22260-2 E	VP22260-2	935268145557	T	M	2	30-jun-03	12-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
868	VP22261B2		VP22261B2	935270997557	T	M	2	30-jun-03	12-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions Project called Patsy_C (ROP1011153/1R4A) from 13/12/2000. Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
869	VP22302-2	VP22302-2 E	VP22302-2	935268773557	T	C	2	30-jun-03	31-dec-03	VP22295-2	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
870	VP22329A2		VP22329A2	935270838557	T	M	2	30-jun-03	30-jun-05	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
871	VP22330A2		VP22330A2	935270840557	T	M	2	30-jun-03	30-jun-05	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions Non-Manufacturable. Consult Marketing. Project called Tarac_U (ROP1011128/1R1A) from 21/01/2002. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
872	VP22383-2		VP22383-1	935270197551	T	C	1	30-jun-03	30-jun-03	VP22480-2	Project called Tarac_U (ROP1011128/1R1A) from 21/01/2002. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
873	VP22383-2	VP22383-2 E	VP22383-1	935270197557	T	C	1	30-jun-03	30-jun-03	VP22480-2	San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
874	VP22384-2	VP22384-2 E	VP22384-2	935269893557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
875	VP22412A2		VP22412A2	935271388557	T	M	2	30-jun-03	30-jun-05	None	Special Die Supply Program applies. San Antonio Plant Closure. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
876	VP22412A3		VP22412A3	935273284557	T	M	2	30-jun-03	30-jun-05	None	Special Die Supply Program applies. San Antonio Plant Closure. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
877	VP27009-2	VP27009-2 B	VP27009-2	935266071557	T	C	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. Consult Marketing. Project called R1A (ROP101678/C) from 22/12/1994. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Project called R2C (ROP101636/3C) from 02/08/1994. Consult Marketing. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
878	VP27034-2	VP27034-2 B	VP27034-2	935266075557	T	C	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. Consult Marketing. Project called Brigitte_H R2E (ROP101636/3C) from 05/08/1994. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN
879	VP27061-2	VP27061-2 B	VP27061-2	935266077557	T	C	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. Consult Marketing. Project called Brigitte_H (ROP101636/3C) from 05/08/1994. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN
880	VP27061A2	VP27061A2 B	VP27061A2	935266079557	T	C	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. Consult Marketing. Project called Brigitte_H (ROP101636/3C) from 05/08/1994. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN
881	VP27064-2	VP27064-2 B	VP27064-2	935266081557	T	C	1	30-jun-03	30-jun-03	None noted	Non-manufacturable. Consult Marketing. Project called R1A Gustavv (ROP101641/7) from 21/06/1995. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Project called R1A_CARL_E (ROP101641/5). Consult Marketing. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
882	VP27067-2	VP27067-2 B	VP27067-2	935264683557	T	C	1	30-jun-03	30-jun-03	None noted	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
883	VP27091-2	VP27091-2 B	VP27091-2	935264696557	T	C	1	30-jun-03	30-jun-03	None noted	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
884	VP27106-2	VP27106-2 B	VP27106-2	935264732557	T	C	1	30-jun-03	30-jun-03	None noted	Project called R1A_CARL_F (ROP101641/6). Consult Marketing. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
885	VP27117-2	VP27117-2 A	VP27117-2	935265971112	T	C	1	30-jun-03	30-jun-03	None noted	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
886	VP27121-2	VP27121-2 B	VP27121-2	935264742557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
887	VP27122-2	VP27122-2 B	VP27122-2	935264749557	T	C	1	30-jun-03	30-jun-03	None noted	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
888	VP27123-2	VP27123-2 B	VP27123-2	935264755557	T	C	1	30-jun-03	30-jun-03	None noted	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
889	VP27140A2	VP27140A2 B	VP27140A2	935266088557	T	C	1	30-jun-03	30-jun-03	None noted	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
890	VP27142A2	VP27142A2 B	VP27142A2	935266091557	T	C	1	30-jun-03	30-jun-03	None noted	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
891	VP27151-2	VP27151-2 DH	VP27151-2	935266385112	T	C	1	30-jun-03	30-jun-03	None noted	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
892	VP27151-3	VP27151-3 DH	VP27151-3	935265496528	T	M	1	30-jun-03	30-jun-03	None noted	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
893	VP27151-4	VP27151-4 DH	VP27151-4	935266240528	T	C	1	30-jun-03	30-jun-03	None noted	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
894	VP27158-2	VP27158-2 B	VP27158-2	935264832557	T	C	1	30-jun-03	30-jun-03	None noted	Project called BATMAN 3.0 from 27/09/1995. Consult Marketing. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
895	VP27167-2	VP27167-2 B	VP27167-2	935266096557	T	C	1	30-jun-03	30-jun-03	None noted	Non-manufacturable. Consult Marketing. Project called R1A (ROP101678/2C) from 12/01/1995.
896	VP27168-2	VP27168-2 B	VP27168-2	935264835557	T	C	1	30-jun-03	30-jun-03	None noted	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
897	VP27183-2	VP27183-2 B	VP27183-2	935266106557	T	C	1	30-jun-03	30-jun-03	None noted	Project called R2B (ROP101678/2C) from 14/05/1996. Consult Marketing. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
898	VP27207-2	VP27207-2 B	VP27207-2	935266114557	T	C	1	30-jun-03	30-jun-03	None noted	Non-manufacturable. Consult Marketing. Project called R2C (ROP101678/2C) from 19/07/1996. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN
899	VP27210-3	VP27210-3 A	VP27210-3	935264891518	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
900	VP27234-2	VP27234-2 B	VP27234-2	935264899557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
901	VP27245-2	VP27245-2 E	VP27245-2	935264930557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
902	VP27246-2	VP27246-2 E	VP27246-2	935264934557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
903	VP27252A2	VP27252A2 B	VP27252A2	935268143557	T	C	1	30-jun-03	30-jun-03	None noted	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
904	VP27266-2	VP27266-2 B	VP27266-2	935264954557	T	C	1	30-jun-03	30-jun-03	None noted	Project called Irene R3A (ROP101078/C) from 14/07/1997. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
905	VP27272-2	VP27272-2 B	VP27272-2	935264966557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
906	VP27278-2	VP27278-2 B	VP27278-2	935266133557	T	C	1	30-jun-03	30-jun-03	None noted	Non-manufacturable. Consult Marketing. Project called R2A (ROP1011075/C) from 21/04/1997. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN
907	VP27280-2	VP27280-2 B	VP27280-2	935266135557	T	C	1	30-jun-03	30-jun-03	None noted	Non-manufacturable. Consult Marketing. Project called JOHANNA_B1 R1A (ROP1011105/C) from 28/07/1997. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN
908	VP27281A2	VP27281A2 B	VP27281A2	935266137557	T	C	1	30-jun-03	30-jun-03	None noted	Non-manufacturable. Consult Marketing. Project called ESSY_A2A (RYS105625/3C R4A) from 27/10/1997.
909	VP27282-2	VP27282-2 B	VP27282-2	935266139557	T	C	1	30-jun-03	30-jun-03	None noted	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
910	VP27297-2	VP27297-2 E	VP27297-2	935264972557	T	C	2	30-jun-03	30-jun-04	None noted	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
911	VP27298-4	VP27298-4 E	VP27298-4	935266073557	T	C	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. Consult Marketing. Project called R1A (ROP1011121/C) from 01/08/1998. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN
912	VP27305A2	VP27305A2 B	VP27305A2	935266157557	T	C	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. Consult Marketing. Project called EFFIE_A1B (RYS105638/C) from 16/03/1998. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN
913	VP27317-5	VP27317-5 B	VP27317-5	935265006528	T	C	2	30-jun-03	31-dec-03	None noted	Limited Availability. Consult Marketing. Project called Johanna R4A (ROP1011105/C) from 12/03/1998. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
914	VP27319-4	VP27319-4 E	VP27319-4	935266090557	T	C	1	30-jun-03	30-jun-03	None noted	Non-manufacturable. Consult Marketing. Project called JOHANNA_C1B (ROP 1011121/2C R2A) from 26/05/1998. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN
915	VP27334-2	VP27334-2 B	VP27334-2	935265011557	T	C	2	1-mei-03	30-dec-05	None noted	Limited Availability. Consult Marketing. San Antonio Plant Closure. See Philips' 03/28/03 CPCN Notice Conditions
916	VP27338A4	VP27338A4 B	VP27338A4	935265013557	T	C	1	30-jun-03	30-jun-03	None noted	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
917	VP27338C4	VP27338C4 B	VP27338C4	935265863557	T	C	1	30-jun-03	30-jun-03	None noted	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
918	VP27348-1	VP27348-1 E	VP27348-1	935265865157	T	M	1	30-jun-03	30-jun-03	None noted	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
919	VP27350-2	VP27350-2 E	VP27350-2	935265020557	T	C	1	30-jun-03	30-jun-03	None noted	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
920	VP27354-2	VP27354-2 B	VP27354-2	935265035557	T	C	2	30-jun-03	31-dec-03	None noted	Limited Availability. Limited Availability. San Antonio plant closure, commercially impractical conditions apply apply
921	VP27355-2	VP27355-2 B	VP27355-2	935265036557	T	C	1	30-jun-03	30-jun-03	None noted	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
922	VP27371-3	VP27371-3 E	VP27371-3	935269056557	T	C	1	30-jun-03	30-jun-03	VP22437	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
923	VP27371A2	VP27371A2 E	VP27371A2	935270689557	T	C	1	30-jun-03	30-jun-03	VP22437	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
924	VP27371B2		VP27371B1	935271090557	T	C	1	30-jun-03	30-jun-03	VP22437	Non-Manufacturable. See Replacement. Project called TARAC_B (ROP1016172CR1AU) from 09/05/2000.
925	VP27375-2	VP27375-2 B	VP27375-2	935266700557	T	C	2	1-mei-03	30-dec-05	None noted	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
926	VP27383-2	VP27383-2 E	VP27383-2	935267021557	T	C	1	30-jun-03	30-jun-03	VP22351-2	Non-Manufacturable. See Replacement. Project called TARAC_B (ROP1016172CR1AU) from 09/05/2000.
927	VP40514-2	VP40514-2 B	VP40514-2	935265069557	T	M	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
928	VP40520A2	VP40520A2 B	VP40520A2	935266196557	T	M	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
929	VP40523-2	VP40523-2 B	VP40523-2	935266200557	T	M	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
930	VP40531-2	VP40531-2 P	VP40531-2	935266143157	T	M	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
931	VP40540-2	VP40540-2 B	VP40540-2	935266209557	T	M	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
932	VP40542-2	VP40542-2 B	VP40542-2	935266210557	T	M	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
933	VP40547A2	VP40547A2 B	VP40547A2	935266212557	T	M	1	30-jun-03	30-jun-03	None noted	Non-Manufacturable. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
934	VP40550-4	VP40550-4 E	VP40550-4	935264862557	T	S	1	30-jun-03	30-jun-03	None	Non-Manufacturable. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
935	VP40551A2	VP40551A2 E	VP40551A2	935264873557	T	S	1	30-jun-03	30-jun-03	None	Non-Manufacturable. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
936	VP40555-2	VP40555-2 B	VP40555-2	935266153557	T	S	1	30-jun-03	30-jun-03	None	Non-Manufacturable. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
937	VP40557-2	VP40557-2 B	VP40557-2	935266701557	T	S	1	30-jun-03	30-jun-03	VP40581H	Non-Manufacturable. See Replacement. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions.
938	VP40557-5	VP40557-5 E	VP40557-5	935266271528	T	S	1	30-jun-03	30-jun-03	VP40581H	Non-Manufacturable. See Replacement. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions.
939	VP40557-6	VP40557-6 E	VP40557-6	935266785557	T	S	1	30-jun-03	30-jun-03	VP40581H	Non-Manufacturable. See Replacement. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions.
940	VP40559A3	VP40559A3 E	VP40559A3	935265719557	T	S	1	30-jun-03	30-jun-03	VP40575	Non-Manufacturable. See Replacement. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions.
941	VP40575-3	VP40575-3 E	VP40575-3	935266566557	T	S	1	30-jun-03	30-jun-03	None	Non-Manufacturable. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
942	VP40575-6	VP40575-6 E	VP40575-6	935268780528	T	S	1	30-jun-03	30-jun-03	None	Non-Manufacturable. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
943	VP40583A2		VP40583A2	935271758557	T	S	1	30-jun-03	30-jun-03	VP40584B	Non-Manufacturable. See Replacement. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions.
944	VP40583A3		VP40583A3	935271759557	T	S	1	30-jun-03	30-jun-03	VP40584B	Non-Manufacturable. See Replacement. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions.
945	VP40583A4		VP40583A4	935271760528	T	S	1	30-jun-03	30-jun-03	VP40584B	Non-Manufacturable. See Replacement. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions.
946	VP40583A5		VP40583A5	935271761557	T	S	1	30-jun-03	30-jun-03	VP40584B	Non-Manufacturable. See Replacement. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions.
947	VP40583A6		VP40583A6	935271762528	T	S	1	30-jun-03	30-jun-03	VP40584B	Non-Manufacturable. See Replacement. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions.
948	VP40584A2		VP40584A2	935271423557	T	S	1	30-jun-03	30-jun-03	VP40584B	Non-Manufacturable. See Replacement. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions.
949	VP40584A3		VP40584A3	935271424528	T	S	1	30-jun-03	30-jun-03	VP40584B	Non-Manufacturable. See Replacement. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions.
950	VP40584A4		VP40584A4	935271425557	T	S	1	30-jun-03	30-jun-03	VP40584B	Non-Manufacturable. See Replacement. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions.
951	VP40584A5		VP40584A5	935271426528	T	S	1	30-jun-03	30-jun-03	VP40584B	Non-Manufacturable. See Replacement. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions.
952	VP40586-2		VP40586-2	935272927557	T	S	1	30-jun-03	30-jun-03	VP40586A	Non-Manufacturable. See Replacement. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions.
953	VP40586-3		VP40586-3	935272928528	T	S	1	30-jun-03	30-jun-03	VP40586A	Non-Manufacturable. See Replacement. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
954	VP40586-4		VP40586-4	935272929557	T	S	1	30-jun-03	30-jun-03	VP40586A	Non-Manufacturable. See Replacement. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions.
955	VP40586-5		VP40586-5	935272930528	T	S	1	30-jun-03	30-jun-03	VP40586A	Non-Manufacturable. See Replacement. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions.
956	VT21898A5	VT21898A5 B	VT21898A5	935269357557	T	M	2	30-jun-03	12-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
957	VT21898A6	VT21898A6 B	VT21898A6	935269358557	T	M	2	30-jun-03	12-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
958	VT21954A2	VT21954A2 E	VT21954A2	935265992557	T	C	1	30-jun-03	30-jun-03	None	Non-Manufacturable. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
959	VT22130-6	VT22130-6 E	VT22130-6	935267145557	T	C	1	30-jun-03	30-jun-03	None	Non-Manufacturable. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
960	VT22161-1		VT22161-1	935269317151	T	M	1	30-jun-03	30-jun-03	None	Non-Manufacturable. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
961	VT22161-2	VT22161-2 E	VT22161-2	935269318557	T	M	1	30-jun-03	30-jun-03	None	Non-Manufacturable. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
962	VT22417-2		VT22417-2	935271991557	T	M	1	30-jun-03	30-jun-03	None	Packing option discontinuation. Device still available in large pack qty. Consult Marketing.
963	VTSQ3D3A1	VTSQ3D3A1 B	VTSQ3D3A1	935265815557	T	M	1	30-jun-03	30-jun-03	None	Non-Manufacturable. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
964	VY05743-2	VY05743-2 B	VY05743-2	935264553557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
965	VY05988-2	VY05988-2 A	VY05988-2	935265304112	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
966	VY05988-3	VY05988-3 A	VY05988-3	935265305518	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
967	VY06482-2	VY06482-2 A	VY06482-2	935264653112	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
968	VY06658-2	VY06658-2 E	VY06658-2	935264669557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
969	VY06670-2	VY06670-2 B	VY06670-2	935265889557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
970	VY06672-2	VY06672-2 B	VY06672-2	935264672557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
971	VY06719-2		ASIC	935265984112	T	S	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
972	VY06719-3		ASIC	935264675518	T	S	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
973	VY06759-2	VY06759-2 B	VY06759-2	935266108557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
974	VY06775-2	VY06775-2 B	VY06775-2	935264688557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
975	VY06780-2	VY06780-2 B	VY06780-2	935264728557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
976	VY06786-3	VY06786-3 Q	VY06786-3	935264730157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
977	VY06798E2	VY06798E2 E	VY06798E2	935265514557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
978	VY06813-2	VY06813-2 B	VY06813-2	935264752557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
979	VY06888D2	VY06888D2 E	VY06888D2	935265516557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
980	VY06925-2	VY06925-2 B	VY06925-2	935266113557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
981	VY06937-2	VY06937-2 B	VY06937-2	935264777557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
982	VY06951-2	VY06951-2 B	VY06951-2	935264782557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
983	VY06993A2	VY06993A2 B	VY06993A2	935266115557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
984	VY06998C2	VY06998C2 B	VY06998C2	935264787557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
985	VY12203-2		ASIC	935265445157	T	S	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
986	VY12324-2	VY12324-2 Q	VY12324-2	935265357157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
987	VY12338-3	VY12338-3 Q	VY12338-3	935265359157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
988	VY12437-2	VY12437-2 Q	VY12437-2	935265361157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
989	VY12439-2	VY12439-2 Q	VY12439-2	935265362157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
990	VY12442-2	VY12442-2 Q	VY12442-2	935265363157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
991	VY12447-2	VY12447-2 B	VY12447-2	935264850557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
992	VY13040-1	VY13040-1 A	VY13040-1	935265985112	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
993	VY13040-2	VY13040-2 A	VY13040-2	935264868112	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
994	VY13040-3	VY13040-3 A	VY13040-3	935264871518	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
995	VY14084-2	VY14084-2 B	VY14084-2	935264852557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
996	VY14090-2		ASIC	935264573557	T	S	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
997	VY14190-2		ASIC	935264583557	T	S	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
998	VY14703-2	VY14703-2 A	VY14703-2	935264698112	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
999	VY15008-2	VY15008-2 B	VY15008-2	935266123557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1000	VY15009-2	VY15009-2 B	VY15009-2	935266128557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1001	VY15018-2	VY15018-2 B	VY15018-2	935264588557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1002	VY15019-2	VY15019-2 B	VY15019-2	935264590557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1003	VY16606-2	VY16606-2 B	VY16606-2	935264603557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1004	VY16611-2	VY16611-2 B	VY16611-2	935264604557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1005	VY16625-2	VY16625-2 B	VY16625-2	935264607557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1006	VY16670-2	VY16670-2 B	VY16670-2	935266132557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1007	VY16672-2	VY16672-2 B	VY16672-2	935266134557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1008	VY16676-2	VY16676-2 B	VY16676-2	935266138557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1009	VY16684-2	VY16684-2 B	VY16684-2	935266140557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1010	VY16825-2	VY16825-2 B	VY16825-2	935264615557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1011	VY16831B2	VY16831B2 B	VY16831B2	935264616557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1012	VY21084-2	VY21084-2 B	VY21084-2	935266145557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1013	VY21110-4		ASIC	935265986157	T	S	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
1014	VY21110-5		ASIC	935264634157	T	S	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1015	VY21164-2	VY21164-2 Q	VY21164-2	935264638157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1016	VY21246-2	VY21246-2 E	VY21246-2	935264645557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1017	VY21250A2	VY21250A2 E	VY21250A2	935264646557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1018	VY21253A2	VY21253A2 B	VY21253A2	935266163557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1019	VY21303A2	VY21303A2 E	VY21303A2	935266287157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1020	VY21339A3	VY21339A3 E	VY21339A3	935266319528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1021	VY21339B2	VY21339B2 E	VY21339B2	935265083557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1022	VY21339B3	VY21339B3 E	VY21339B3	935266328528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1023	VY21398-2	VY21398-2 E	VY21398-2	935266294157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1024	VY21398-4	VY21398-4 E	VY21398-4	935265112528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1025	VY21410-2	VY21410-2 A	VY21410-2	935265116518	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1026	VY21471-2	VY21471-2 E	VY21471-2	935266305157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1027	VY21471-3	VY21471-3 E	VY21471-3	935266352528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1028	VY21493-2	VY21493-2 B	VY21493-2	935265177557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1029	VY21542-2	VY21542-2 E	VY21542-2	935265178557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1030	VY21599-2		VY21599-2	935265199557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1031	VY21696-2	VY21696-2 E	VY21696-2	935264924557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1032	VY21696-3	VY21696-3 E	VY21696-3	935266357528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1033	VY21703-2	VY21703-2 E	VY21703-2	935264935557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
1034	VY21703-3	VY21703-3 E	VY21703-3	935266973528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1035	VY21737-2	VY21737-2 B	VY21737-2	935264970557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1036	VY21827-2	VY21827-2 E	VY21827-2	935265004557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1037	VY21827-3	VY21827-3 E	VY21827-3	935265007528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1038	VY21872A2	VY21872A2 B	VY21872A2	935264661557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1039	VY21872B2	VY21872B2 B	VY21872B2	935265751557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1040	VY21872D2	VY21872D2 B	VY21872D2	935266864557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1041	VY21874-2	VY21874-2 B	VY21874-2	935264662557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1042	VY21939-2	VY21939-2 E	VY21939-2	935266325557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1043	VY21939-3	VY21939-3 E	VY21939-3	935264670528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1044	VY21940-2	VY21940-2 E	VY21940-2	935266326557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1045	VY21940-3	VY21940-3 E	VY21940-3	935265535528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1046	VY21973-1	VY21973-1 E	VY21973-1	935267270157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1047	VY21973-2	VY21973-2 E	VY21973-2	935267271557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1048	VY21977-2	VY21977-2 E	VY21977-2	935267269557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1049	VY21983A2	VY21983A2 E	VY21983A2	935268265557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1050	VY21983A3	VY21983A3 CA	VY21983A3	935269068024	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1051	VY21983A4	VY21983A4 E	VY21983A4	935270625557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1052	VY22011A2	VY22011A2 E	VY22011A2	935264700557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1053	VY22011B2	VY22011B2 E	VY22011B2	935264701557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
1054	VY22011C2A	VY22011C2A E	VY22011C2A	935265724557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1055	VY22011C2B	VY22011C2B E	VY22011C2B	935265726557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1056	VY22011C2C	VY22011C2C E	VY22011C2C	935265727557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1057	VY22011C3A	VY22011C3A E	VY22011C3A	935265991557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1058	VY22011C3B	VY22011C3B E	VY22011C3B	935265819557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1059	VY22011C3C	VY22011C3C E	VY22011C3C	935265739557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1060	VY22012-2	VY22012-2 E	VY22012-2	935266765557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1061	VY22012-3	VY22012-3 E	VY22012-3	935266796528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1062	VY22015-2	VY22015-2 E	VY22015-2	935264703557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1063	VY22015-3	VY22015-3 E	VY22015-3	935265905528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1064	VY22015A2	VY22015A2 E	VY22015A2	935267783557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1065	VY22015A3	VY22015A3 E	VY22015A3	935267784528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1066	VY22038-2	VY22038-2 E	VY22038-2	935269047557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1067	VY22054-2	VY22054-2 E	VY22054-2	935267984557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1068	VY22054-3	VY22054-3 E	VY22054-3	935267985528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1069	VY22055-2	VY22055-2 E	VY22055-2	935267090557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1070	VY22055-3	VY22055-3 E	VY22055-3	935267094528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1071	VY22055A2	VY22055A2 E	VY22055A2	935267525557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1072	VY22055A3	VY22055A3 E	VY22055A3	935267526528	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1073	VY22060-4	VY22060-4 E	VY22060-4	935266843557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
1074	VY22061-2	VY22061-2 E	VY22061-2	935266584557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1075	VY22061A2	VY22061A2 E	VY22061A2	935267750557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1076	VY22071-2	VY22071-2 E	VY22071-2	935268551557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1077	VY22071A2	VY22071A2 E	VY22071A2	935269198557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1078	VY22099A2	VY22099A2 E	VE22099A2	935266627557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1079	VY22099H2	VY22099H2 E	VY22099H2	935267617557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1080	VY22099H3	VY22099H3 E	VY22099H3	935267618557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1081	VY22187B3	VY22187B3 B	VY22187B3	935270206557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1082	VY22248-2	VY22248-2 E	VY22248-2	935268003557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1083	VY22266-2	VY22266-2 E	VY22266-2	935270314557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1084	VY22271-2		VY22271-2	935270316551	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1085	VY22285-2	VY22285-2 B	VY22285-2	935269664557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1086	VY22285A2	VY22285A2 B	VY22285A2	935269851557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1087	VY22289-2	VY22289-2 E	VY22289-2	935268522557	T	M	2	30-jun-03	12-dec-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1088	VY22402A2		VY22402A2	935271218557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1089	VY22402B2		VY22402B2	935271875557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1090	VY22435-2		VY22435-2	935271292528	T	M	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1091	VY22436-2		VY22436-2	935270912557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1092	VY22436A2		VY22436A2	935272431557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions
1093	VY22471-2		VY22471-2	935271390557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions

Philips Semiconductors, Inc.
Product Discontinuation Notice DN49
Exhibit A
June 30, 2003

Type Number	NA Part #	Description	Twelve NC Code	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Ship Date	Replacement Type	Comments	
1094	VY22497-2	VY22497-2	935272328557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions	
1095	VY27059-2	VY27059-2 B	935264706557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions	
1096	VY27146-2	VY27146-2 A	935264819112	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions	
1097	VY27260-2	VY27260-2 E	935264831557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions	
1098	VY27310-2	VY27310-2 Q	935265339157	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions	
1099	VY27340B2	VY27340B2 B	935269625557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions	
1100	VY27357A2	VY27357A2 E	935270310557	T	C	1	30-jun-03	30-jun-03	None	Limited Availability. San Antonio plant closure, commercially impractical conditions apply. See Philips' 03/28/03 CPCN Notice Conditions	
1101	X3A-BFQ32	PNP BROADBAND TRANSISTORS	933828360002	T	M	3	31-dec-03	31-mrt-04	None	Standard Discontinuation. Consult Marketing	
1102	XAU2903CK	XAU2903 CK	LINEAR INDUSTRIAL	935230500026	N	M	2	30-dec-03	30-mrt-04	XAU2903CU	Limited Availability, See Replacement
1103	XN5230CK	XN5230 CK	LINEAR INDUSTRIAL	935045540602	N	M	2	30-dec-03	30-mrt-04	XNE5230CU	Limited Availability, See Replacement
1104	XNE5534CK	XNE5534 CK	LINEAR INDUSTRIAL	935146170026	N	M	2	30-dec-03	30-mrt-04	XNE5234CU	Limited Availability, See Replacement
1105	XNE5539CK	XNE5539 CK	LINEAR INDUSTRIAL	935146190026	N	M	2	30-dec-03	30-mrt-04	XNE5539CU	Limited Availability, See Replacement