

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
2N1505 (Cont'd) TN2218A 3 NSC TN2219A 3 NSC TP2218A 3 SPR TP2219A 3 SPR	2N1531 DE121 1 DGE	2N1559 DE179 1 DGE	2N1591 (Cont'd) THC2221 3 SPR TMPT2221 3 SPR TP2221 3 SPR	2N1615 (Cont'd) THC1711 3 SPR THC3500 3 SPR	2N1679 (Cont'd) 2N5337 3 MOTA BUY47 3 SGSI
2N1506 2N2218 1 PHIN 2N4237 1 MOTA D40D3 1 GESY 2N697 3 RCA 2N5786 3 RCA D40D2 3 MOTA D40D4 3 GESY DE128 3 DGE GES2218 3 GESY THC2218 3 SPR TN2218 3 NSC TP2218 3 SPR	2N1532 DE121 1 DGE 2N1532A DE121 1 DGE 2N1533 DE121 1 DGE 2N1534 DE121 1 DGE 2N1534A DE121 1 DGE 2N1535 DE121 1 DGE DE121 1 DGE BDX96 3 PHIN 2N1535A DE121 1 DGE	2N1564 2N1711 1 PHIN DE128 1 DGE D40D5 3 GESY PN2222A 3 NSC THC2211 3 SPR 2N1565 2N1613 1 PHIN DE128 1 DGE RCA1A01 1 RCA D40D7 3 GESY DE123 3 DGE PN2221A 3 NSC THC1613 3 SPR 2N1565A RCA1A01 1 RCA	2N1592 2N2222 1 MOTA DE123 1 DGE BSS81C 3 SIEG GES2222 3 GESY PN2222 3 NSC THC2222 3 SPR TMPT2222 3 SPR TP2222 3 SPR 2N1593 2N2222 1 MOTA DE123 1 DGE BSS81C 3 SIEG GES2222 3 GESY PN2222 3 NSC THC2222 3 SPR TMPT2222 3 SPR TP2222 3 SPR 2N1594 2N2222 1 MOTA DE123 1 DGE BSS81C 3 SIEG GES2222 3 GESY PN2222 3 NSC THC2222 3 SPR TMPT2222 3 SPR TP2222 3 SPR	2N1616 BD949 1 PHIN DE73 1 DGE BD241A 3 RCA SGSI 2N1617 BD951 1 PHIN BDY91 1 PHIN DE73 1 DGE 2N5038 3 RCA BD241B 3 RCA SGSI 2N1618 BD953 1 PHIN BDY90 1 PHIN DE73 1 DGE BD241C 3 RCA SGSI 2N1620 BD953 1 PHIN BD241C 3 RCA SGSI 2N1623 2N2906 1 MOTA DE159 3 DGE GES2906 3 GESY PN2906 3 NSC THC2906 3 SPR TMPT2906 3 SPR TP2906 3 SPR 2N1631 2N1632 1 LTE DE126A 3 DGE 2N1632 DE126A 1 DGE 2N1633 2N1634 1 LTE DE126A 1 DGE 2N1634 DE126A 1 DGE 2N1635 2N1636 1 LTE DE126A 1 DGE 2N1636 DE126A 1 DGE 2N1637 DE126A 1 DGE 2N1638 DE126A 1 DGE 2N1639 DE126A 1 DGE 2N1644 2N2218 1 PHIN 2N697 3 RCA DE128 3 DGE GES2218 3 GESY THC2218 3 SPR TN2218 3 NSC TP2218 3 SPR 2N1647 BD937 1 PHIN BD239B 3 RCA SGSI 2N1648 BD941 1 PHIN 2N6474 3 RCA 2N1649 BD937 1 PHIN BD239B 3 RCA SGSI 2N1650 BD941 1 PHIN 2N6474 3 RCA 2N1651 DE179 1 DGE 2N1652 DE179 1 DGE 2N1653 DE179 1 DGE 2N1654 MM3006 1 MOTA 2N1655 MM3007 1 MOTA 2N1666 BDX94 1 PHIN 2N4905 3 RCA 2N4906 3 RCA BDW22B 3 SGSI 2N1667 BDX92 1 PHIN 2N4905 3 RCA BDW22A 3 SGSI 2N1668 BDX92 1 PHIN 2N4905 3 RCA BDW22A 3 SGSI 2N1669 BDX96 1 PHIN BDW22C 3 SGSI 2N1679 2N5335 1 GSE	2N1680 2N5334 1 GSE 2N5337 3 MOTA BUY68 3 SGSI D42C7 3 GESY 2N1691 D44T1 1 GESY 2N1700 BFY50 1 PHIN D40D4 1 GESY 2N697 3 RCA D40D4C 3 SPR 2N1701 2N4910 1 GSE D44C4 1 GESY 2N3054 3 MOTA 2N3632 3 PHIN 2N6260 3 RCA 2N6290 3 RCA 2N6374 3 RCA BD135 3 PHIN BD239 3 RCA BU407 3 APX D44C5 3 GESY DE175 3 DGE ST44C4 3 STI 2N1702 2N5877 1 MOTA DE283 1 DGE D44VH7 3 GESY DE130 3 DGE 2N1703 DE130 1 DGE 2N1704 2N2218 1 PHIN 2N697 3 RCA DE128 3 DGE GES2218 3 GESY THC2218 3 SPR TN2218 3 NSC TP2218 3 SPR 2N1708 2N3508 1 MOTA 2N3903 1 GESY 2N2222 3 SGSI BC548A 3 PHIN DE123A 3 DGE DE123AP 3 DGE THC3903 3 SPR TMPT3903 3 SPR 2N1709 D42C7 1 GESY 2N6292 3 RCA MDS27 3 MOTA 2N1710 D42C4 1 GESY 2N6290 3 RCA MDS27 3 MOTA 2N1711 D40D5 1 GESY DE128 1 DGE PN2222A 1 NSC THC1711 1 SPR 2B1711 3 PHIN 2N697 3 RCA 2N1613 3 RCA SGSI 2N2218 3 PHIN 2N2219 3 MOTA 2N219A 3 PHIN 2N3019 3 MOTA 2N3020 3 MOTA PHIN SGSI 2N3500 3 MOTA 2N4400 3 NSC 40409 3 RCA BFY50 3 PHIN BFY52 3 SGSI BS2218 3 SGSI D40D1 3 GESY D40D5C 3 SPR D40D7 3 GESY D44E7 3 GESY DE123 3 DGE DE123A 3 DGE DE126 3 DGE GES3566 3 GESY PN100 3 NSC PN3566-5 3 NSC THC697 3 SPR THC956 3 SPR THC1566 3 SPR THC2195 3 SPR THC3566 3 SPR TP3566 3 SPR 2N1711A D40D7 1 GESY 2N1711B D40D7 1 GESY