

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
<b>THBC213</b> BC213 BC178 BC213L BC557	<b>THBC309B</b> BC309B	<b>THBC485A</b> BC485A	<b>THC718</b> 2N2221A 2N4400 DE123A	<b>THC2219</b> DE128 GES2219 TN2219 TP2219	<b>THC2908 (Cont'd)</b> TP2906 <b>THC2906A</b> PN2906A TMPT2906A TP2906A TPQ2906A
<b>THBC213A</b> BC213A BC213LA	<b>THBC309C</b> BC309C	<b>THBC485B</b> BC485B	<b>THC760</b> 2N2483 2N3700 BC547B DE108	<b>THC2219A</b> GES2219A TN2219A TP2219A	<b>THC2907</b> BSS80C DE159 GES2907 PN2907 TMPT2907 TP2907
<b>THBC213B</b> BC213B BC213LB	<b>THBC317A</b> BC317A	<b>THBC546</b> BC546	<b>THC760A</b> 2N2483 2N3700 2N4409 BFY73	<b>THC2221</b> BSS81B DE123A GES222A PN2221 TMPT2221	<b>THC2907A</b> BSS82C PN2907A TMPT2907A TP2907A
<b>THBC213C</b> BC213C BC213LC	<b>THBC317B</b> BC317B	<b>THBC546A</b> BC546A	<b>THC915</b> 2N2221A DE123A MP56565	<b>THC2221A</b> BSS79B GES2221A TMPT2221A TP2221A	<b>THC2923</b> DE199
<b>THBC214</b> BC214 2N5087 BC179 BC214L BC559	<b>THBC318A</b> BC318A	<b>THBC547</b> BC547	<b>THC916</b> BCY56 DE123A	<b>THC2222</b> BSS81C GES2222 PN2222 TMPT2222 TP2222	<b>THC2924</b> DE199
<b>THBC214A</b> BC214A BC214LA	<b>THBC318B</b> BC318B	<b>THBC547A</b> BC547A	<b>THC917</b> 2N918	<b>THC2222A</b> BSS79C DE102A DE123A GES2222A PN2222A TMPT2222A TPQ2222A	<b>THC2925</b> DE199
<b>THBC214B</b> BC214B BC214LB	<b>THBC318C</b> BC318C	<b>THBC547B</b> BC547B	<b>THC930</b> DE123A GES930 PN930 TP930	<b>THC2223</b> BSS79C DE102A DE123A GES2223A PN2223A TMPT2223A TPQ2223A	<b>THC2926</b> BC548B DE199
<b>THBC214C</b> BC214C BC214LC	<b>THBC319</b> BC319	<b>THBC547C</b> BC547C	<b>THC930A</b> DE123A	<b>THC2224</b> BSS79C DE102A DE123A GES2224A PN2224A TMPT2224A TPQ2224A	<b>THC2945</b> DE159 TP2945
<b>THBC237</b> BC237 BC107 BC547 SC237	<b>THBC319B</b> BC319B	<b>THBC548</b> BC548	<b>THC930A</b> DE123A	<b>THC2224A</b> BSS79C DE102A DE123A GES2224A PN2224A TMPT2224A TPQ2224A	<b>THC2946</b> DE159 TP2946
<b>THBC237A</b> BC237A	<b>THBC319C</b> BC319C	<b>THBC548A</b> BC548A	<b>THC9329</b> 2N930 2N4409 BFY76 GES929	<b>THC2243</b> 2N1893 2N3020 BSW67 DE128	<b>THC3009</b> 2N3013 DE123A PN3646
<b>THBC237B</b> BC237B	<b>THBC327-16</b> BC327-16	<b>THBC548B</b> BC548B	<b>THC9330</b> DE123A	<b>THC2270</b> D40D4 DE128	<b>THC3013</b> PN3646
<b>THBC238</b> BC238 BC108 SC238	<b>THBC327-25</b> BC327-25	<b>THBC548C</b> BC548C	<b>THC9356</b> 2N1711 PN2222A	<b>THC2484</b> 2N3903 2N5210 BCX41 BSS64 DE123A TMPT2484 TP2484	<b>THC3019</b> 2N4305 BCX56-16 D38H5 DE128 TN3019
<b>THBC238A</b> BC238A	<b>THBC328-16</b> BC328-16	<b>THBC555A</b> BC555A	<b>THC981</b> 2N720A 2N2219	<b>THC2509</b> 2N720A DE154	<b>THC3053</b> BCX55-10 BSS79C GES3053
<b>THBC238B</b> BC238B	<b>THBC328-25</b> BC328-25	<b>THBC555B</b> BC555B	<b>THC981</b> 2N720A 2N2219	<b>THC2510</b> DE128 2N930 DE123A	<b>THC3072</b> 2N3763 D40D1 GESY
<b>THBC238C</b> BC238C	<b>THBC337</b> BC337	<b>THBC555C</b> BC555C	<b>THC1420</b> 2N2219	<b>THC2511</b> 2N930A BFY76 DE123A	<b>THC3073</b> 2N3006A DE159 MP5A05
<b>THBC239</b> BC239 2N5089 BC109 SC239	<b>THBC337-16</b> BC337-16	<b>THBC557</b> BC557	<b>THC1566</b> 2N1711 DE128	<b>THC2566</b> 2N930A 2N2484	<b>THC3107</b> 2N3019 D40DB DE128
<b>THBC239B</b> BC239B	<b>THBC337-25</b> BC337-25	<b>THBC557A</b> BC557A	<b>THC1613</b> D40D7 DE123 PN2221A	<b>THC2604</b> 2N5086 BCY70 DE159	<b>THC3108</b> 2N2102 2N3020 D40D7 DE128
<b>THBC239C</b> BC239C	<b>THBC338</b> BC338	<b>THBC557B</b> BC557B	<b>THC1711</b> D40D5 DE128 PN2222A	<b>THC2605</b> 2N5086 BCY71 DE159	<b>THC3109</b> 2N3499 D40DB DE128
<b>THBC257</b> BC257 BC177 BC557	<b>THBC338-16</b> BC338-16	<b>THBC557C</b> BC557C	<b>THC2017</b> 2N2989 D40D7 DE128	<b>THC2712</b> BC548A BCY58 DE199	<b>THC3114</b> 2N3440 D44T1 DE154
<b>THBC257A</b> BC257A	<b>THBC338-25</b> BC338-25	<b>THBC558</b> BC558	<b>THC2102</b> 2N2297 2N4239 BCX56-6	<b>THC2714</b> BC548A BCY59	<b>THC3115</b> 2N2221 DE123A MPS2221
<b>THBC257B</b> BC257B	<b>THBC338-16</b> BC338-16	<b>THBC558A</b> BC558A	<b>THC2192A</b> 2N2297 2N4239 BCX56-10 BFY55 D40D10 DE128	<b>THC2904</b> DE129 TN2904 TP2904	<b>THC3116</b> 2N2222 DE123A MPS2222
<b>THBC258</b> BC258 BC178	<b>THBC338-25</b> BC338-25	<b>THBC558B</b> BC558B	<b>THC2192B</b> 2N2297 2N4239 BCX56-10 BFY55 D40D10 DE128	<b>THC2905A</b> TN2905A TP2905A	<b>THC3117</b> 2N930A 2N5210 BFR17 DE123A
<b>THBC258A</b> BC258A	<b>THBC339</b> BC339	<b>THBC558C</b> BC558C	<b>THC2195</b> 2N697 2N1711 2N2219 BS2218 DE128	<b>THC2906</b> DE159 GES2906 PN2906 TMPT2906	
<b>THBC258B</b> BC258B	<b>THBC413</b> BC413	<b>THBC559</b> BC559	<b>THC2195A</b> 2N697 2N2219		
<b>THBC258C</b> BC258C	<b>THBC413B</b> BC413B	<b>THBC560</b> BC560	<b>THC2218A</b> GES2218A TN2218A TP2218A		
<b>THBC259</b> BC259 BC179	<b>THBC413C</b> BC413C	<b>THBC560A</b> BC560A			
<b>THBC259B</b> BC259B	<b>THBC414</b> BC414	<b>THBC560B</b> BC560B			
<b>THBC259C</b> BC259C	<b>THBC414B</b> BC414B	<b>THBC560C</b> BC560C			
<b>THBC307</b> BC307 BC177 SC307	<b>THBC414C</b> BC414C	<b>THBC560D</b> BC560D			
<b>THBC307A</b> BC307A	<b>THBC415</b> BC415	<b>THBC560E</b> BC560E			
<b>THBC307B</b> BC307B	<b>THBC415A</b> BC415A	<b>THBC560F</b> BC560F			
<b>THBC308</b> BC308 BC178 SC308	<b>THBC415B</b> BC415B	<b>THBC560G</b> BC560G			
<b>THBC308A</b> BC308A	<b>THBC415C</b> BC415C	<b>THBC560H</b> BC560H			
<b>THBC308B</b> BC308B	<b>THBC416</b> BC416	<b>THBC560I</b> BC560I			
<b>THBC308C</b> BC308C	<b>THBC416A</b> BC416A	<b>THBC560J</b> BC560J			
<b>THBC309</b> BC309 BC179 SC309	<b>THBC416B</b> BC416B	<b>THBC560K</b> BC560K			
	<b>THBC416C</b> BC416C	<b>THBC560L</b> BC560L			
	<b>THBC485</b> BC485	<b>THBC560M</b> BC560M			