

Part No.	Part No.	Part No.	Part No.	Part No.	Part No.
Replacement No.	Mfr.	Replacement No.	Mfr.	Replacement No.	Mfr.
MD7002 IT122 MP310	1 INL 3 MPS	MEF3458 (Cont'd) THJ4341 TMPF4341 TP4341	3 SPR 3 SPR 3 SPR	MEF4392 ITE4392 MPF4392 PN4392-18	1 INL 3 MOTA 3 NSC
MD7002A IT122 MP310	1 INL 3 MPS	MEF3459 2N4339 BFW13	1 INL 3 PHIN	MEF4393 ITE4393 MPF4393	SIX 1 IFC 3 IFC
MD7002B IT122 MP310	1 INL 3 MPS	DE312 THJ4339	3 DGE 3 SPR	THJ5486 MPF5486	2N5486 1 INL 3 NC
MD7003 IT132 MP351	1 INL 3 MPS	TMPF4339 TP4339	3 SPR 3 SPR	PN4393-18	3 NC SIX 1 IFC
MD7003A IT132 MP351	1 INL 3 MPS	MEF3460 2N4338 2N3460	1 INL 3 IFC	MEF4416 ITE4416 2N4416	1 INL 3 MOTA
MD7003B IT132 MP351	1 INL 3 MPS	BFW13 DE312	3 PHIN 3 DGE	THJ4338 2N5245	3 SPR 3 IFC
MD7004 IT129 MP311	1 INL 3 MPS	TMPF4338 TP4338	3 SPR 3 SPR	PN4416 PN4416-18	3 SIX 3 NC
MD7004A IT129 MP311	1 INL 3 MPS	MEF3684 2N3684 2N3822	1 INL 3 IFC	MEF4856 2N4856 DE466	1 INL 3 DGE
MD7007 IT129 MP311	1 INL 3 MPS	2N4339 BFW11	3 SIX 3 PHIN	THJ4856 MPF4856	3 SPR 3 SPR
MD7007A IT129 MP311	1 INL 3 MPS	MEF3685 2N3685 BFW12	1 INL 3 PHIN	MEF4857 2N4857 DE466	1 INL 3 DGE
MD7007B IT129 MP311	1 INL 3 MPS	2N4339 BFW12	3 SIX 3 MOTA	THJ4857 MPF4857 TP4857	3 SPR 3 SPR 3 SPR
MD7091 MD8003	1 MOTA 1 INL	MEF3688 2N3686 2N3821	1 INL 3 IFC	MEF4858 2N4858 DE466	1 INL 3 DGE
MD8001 IT120 MP312	1 INL 3 MPS	2N3686 BFW13	3 IFC 3 MOTA	THJ4858 MPF4858 TP4858	3 SPR 3 SPR 3 SPR
MD8002 IT120 MP312	1 INL 3 MPS	MEF3687 2N3687 2N3821	1 INL 3 IFC	MEF4859 2N4859 DE466	1 INL 3 DGE
MD8003 IT122 MP310	1 INL 3 MPS	2N4341 BFW12	3 SIX 3 PHIN	THJ4858 MPF4858 TP4858	3 SPR 3 SPR 3 SPR
MDS26 2N6288	3 RCA	MEF3821 2N3821 BFW13	1 INL 3 PHIN	MEF4860 2N4860 DE466	1 INL 3 DGE
MDS27 2N6290 2N6292 2N6551 D42C7	3 RCA 3 RCA 3 MOTA 3 GESY	MEF3822 2N3822 BFW11 DE456	1 INL 3 DGE	MEF4861 2N4861 DE466	1 INL 3 DGE
MDS73 MDS77	1 MOTA	MEF3823 2N3823 BFW11	1 PHIN	MEF4862 2N4860 DE466	1 INL 3 DGE
MDS74 MJE172 D43C11	1 MOTA 3 GESY	MEF3824 2N3822 BFW11 DE459	1 DGE	MEF4863 2N4861 DE465	1 INL 3 DGE
MDS75 MJE253 ST253	1 MOTA 3 STI	MEF3825 2N3823 BFW11	1 INL	MEF4864 2N4861 DE466	1 INL 3 DGE
MDS76 2N6111	3 RCA	MEF3826 2N3822 BFW11 THJ3822	1 DGE	MEF4865 2N4860 DE465	1 INL 3 DGE
MDS77 2N6107 2N6109 2N6554	3 RCA 3 RCA 3 MOTA	MEF3827 2N3823 BFW11 THJ3822	1 SPR	MEF4866 2N4861 DE466	1 INL 3 DGE
MDS1678 D42C7	1 GESY	MEF3954 2N3954 BFW11	1 MOTA	MEF4867 2N4860 DE466	1 INL 3 DGE
MDS27 2N6292	1 MOTA	MEF3955 2N3955 BFW11	1 MOTA	MEF4868 2N4861 DE466	1 INL 3 DGE
MED160 BPW17 BPX81-3	1 ALGG 3 SIEK	MEF3956 2N5546 BFW11	1 IFC	MEF4869 2N4860 DE466	1 INL 3 DGE
MEF103 2N5457 2N5953	1 INL 3 IFC	MEF3957 2N5547 BFW11	1 IFC	MEF4870 2N4861 DE466	1 INL 3 DGE
MEF104 2N5459 2N5951	1 INL 3 IFC	MEF3958 2N5547 BFW11	1 PHIN	MEF4871 2N4861 DE466	1 INL 3 DGE
MEF105 2N5457 2N5951	1 INL 3 IFC	MEF3959 2N5547 BFW11	1 SPR	MEF4872 2N4861 DE466	1 INL 3 DGE
MEF106 2N5457 2N5951	1 INL 3 IFC	MEF3960 2N5547 BFW11	1 PHIN	MEF4873 2N4861 DE466	1 INL 3 DGE
MEF107 2N5457 2N5951	1 INL 3 IFC	MEF3961 2N5547 BFW11	1 DGE	MEF4874 2N4861 DE466	1 INL 3 DGE
MEF108 2N5457 2N5951	1 INL 3 IFC	MEF3962 2N5547 BFW11	1 DGE	MEF4875 2N4861 DE466	1 INL 3 DGE
MEF109 2N5457 2N5951	1 INL 3 IFC	MEF3963 2N5547 BFW11	1 DGE	MEF4876 2N4861 DE466	1 INL 3 DGE
MEF110 2N5457 2N5951	1 INL 3 IFC	MEF3964 2N5547 BFW11	1 DGE	MEF4877 2N4861 DE466	1 INL 3 DGE
MEF111 2N5457 2N5951	1 INL 3 IFC	MEF3965 2N5547 BFW11	1 DGE	MEF4878 2N4861 DE466	1 INL 3 DGE
MEF112 2N5457 2N5951	1 INL 3 IFC	MEF3966 2N5547 BFW11	1 DGE	MEF4879 2N4861 DE466	1 INL 3 DGE
MEF113 2N5457 2N5951	1 INL 3 IFC	MEF3967 2N5547 BFW11	1 DGE	MEF4880 2N4861 DE466	1 INL 3 DGE
MEF114 2N5457 2N5951	1 INL 3 IFC	MEF3968 2N5547 BFW11	1 DGE	MEF4881 2N4861 DE466	1 INL 3 DGE
MEF115 2N5457 2N5951	1 INL 3 IFC	MEF3969 2N5547 BFW11	1 DGE	MEF4882 2N4861 DE466	1 INL 3 DGE
MEF116 2N5457 2N5951	1 INL 3 IFC	MEF3970 2N5547 BFW11	1 DGE	MEF4883 2N4861 DE466	1 INL 3 DGE
MEF117 2N5457 2N5951	1 INL 3 IFC	MEF3971 2N5547 BFW11	1 DGE	MEF4884 2N4861 DE466	1 INL 3 DGE
MEF118 2N5457 2N5951	1 INL 3 IFC	MEF3972 2N5547 BFW11	1 DGE	MEF4885 2N4861 DE466	1 INL 3 DGE
MEF119 2N5457 2N5951	1 INL 3 IFC	MEF3973 2N5547 BFW11	1 DGE	MEF4886 2N4861 DE466	1 INL 3 DGE
MEF120 2N5457 2N5951	1 INL 3 IFC	MEF3974 2N5547 BFW11	1 DGE	MEF4887 2N4861 DE466	1 INL 3 DGE
MEF121 2N5457 2N5951	1 INL 3 IFC	MEF3975 2N5547 BFW11	1 DGE	MEF4888 2N4861 DE466	1 INL 3 DGE
MEF122 2N5457 2N5951	1 INL 3 IFC	MEF3976 2N5547 BFW11	1 DGE	MEF4889 2N4861 DE466	1 INL 3 DGE
MEF123 2N5457 2N5951	1 INL 3 IFC	MEF3977 2N5547 BFW11	1 DGE	MEF4890 2N4861 DE466	1 INL 3 DGE
MEF124 2N5457 2N5951	1 INL 3 IFC	MEF3978 2N5547 BFW11	1 DGE	MEF4891 2N4861 DE466	1 INL 3 DGE
MEF125 2N5457 2N5951	1 INL 3 IFC	MEF3979 2N5547 BFW11	1 DGE	MEF4892 2N4861 DE466	1 INL 3 DGE
MEF126 2N5457 2N5951	1 INL 3 IFC	MEF3980 2N5547 BFW11	1 DGE	MEF4893 2N4861 DE466	1 INL 3 DGE
MEF127 2N5457 2N5951	1 INL 3 IFC	MEF3981 2N5547 BFW11	1 DGE	MEF4894 2N4861 DE466	1 INL 3 DGE
MEF128 2N5457 2N5951	1 INL 3 IFC	MEF3982 2N5547 BFW11	1 DGE	MEF4895 2N4861 DE466	1 INL 3 DGE
MEF129 2N5457 2N5951	1 INL 3 IFC	MEF3983 2N5547 BFW11	1 DGE	MEF4896 2N4861 DE466	1 INL 3 DGE
MEF130 2N5457 2N5951	1 INL 3 IFC	MEF3984 2N5547 BFW11	1 DGE	MEF4897 2N4861 DE466	1 INL 3 DGE
MEF131 2N5457 2N5951	1 INL 3 IFC	MEF3985 2N5547 BFW11	1 DGE	MEF4898 2N4861 DE466	1 INL 3 DGE
MEF132 2N5457 2N5951	1 INL 3 IFC	MEF3986 2N5547 BFW11	1 DGE	MEF4899 2N4861 DE466	1 INL 3 DGE
MEF133 2N5457 2N5951	1 INL 3 IFC	MEF3987 2N5547 BFW11	1 DGE	MEF4900 2N4861 DE466	1 INL 3 DGE
MEF134 2N5457 2N5951	1 INL 3 IFC	MEF3988 2N5547 BFW11	1 DGE	MEF4901 2N4861 DE466	1 INL 3 DGE
MEF135 2N5457 2N5951	1 INL 3 IFC	MEF3989 2N5547 BFW11	1 DGE	MEF4902 2N4861 DE466	1 INL 3 DGE
MEF136 2N5457 2N5951	1 INL 3 IFC	MEF3990 2N5547 BFW11	1 DGE	MEF4903 2N4861 DE466	1 INL 3 DGE
MEF137 2N5457 2N5951	1 INL 3 IFC	MEF3991 2N5547 BFW11	1 DGE	MEF4904 2N4861 DE466	1 INL 3 DGE
MEF138 2N5457 2N5951	1 INL 3 IFC	MEF3992 2N5547 BFW11	1 DGE	MEF4905 2N4861 DE466	1 INL 3 DGE
MEF139 2N5457 2N5951	1 INL 3 IFC	MEF3993 2N5547 BFW11	1 DGE	MEF4906 2N4861 DE466	1 INL 3 DGE
MEF140 2N5457 2N5951	1 INL 3 IFC	MEF3994 2N5547 BFW11	1 DGE	MEF4907 2N4861 DE466	1 INL 3 DGE
MEF141 2N5457 2N5951	1 INL 3 IFC	MEF3995 2N5547 BFW11	1 DGE	MEF4908 2N4861 DE466	1 INL 3 DGE
MEF142 2N5457 2N5951	1 INL 3 IFC	MEF3996 2N5547 BFW11	1 DGE	MEF4909 2N4861 DE466	1 INL 3 DGE
MEF143 2N5457 2N5951	1 INL 3 IFC	MEF3997 2N5547 BFW11	1 DGE	MEF4910 2N4861 DE466	1 INL 3 DGE
MEF144 2N5457 2N5951	1 INL 3 IFC	MEF3998 2N5547 BFW11	1 DGE	MEF4911 2N4861 DE466	1 INL 3 DGE
MEF145 2N5457 2N5951	1 INL 3 IFC	MEF3999 2N5547 BFW11	1 DGE	MEF4912 2N4861 DE466	1 INL 3 DGE
MEF146 2N5457 2N5951	1 INL 3 IFC	MEF4000 2N5547 BFW11	1 DGE	MEF4913 2N4861 DE466	1 INL 3 DGE
MEF147 2N5457 2N5951	1 INL 3 IFC	MEF4001 2N5547 BFW11	1 DGE	MEF4914 2N4861 DE466	1 INL 3 DGE
MEF148 2N5457 2N5951	1 INL 3 IFC	MEF4002 2N5547 BFW11	1 DGE	MEF4915 2N4861 DE466	1 INL 3 DGE
MEF149 2N5457 2N5951	1 INL 3 IFC	MEF4003 2N5547 BFW11	1 DGE	MEF4916 2N4861 DE466	1 INL 3 DGE
MEF150 2N5457 2N5951	1 INL 3 IFC	MEF4004 2N5547 BFW11	1 DGE	MEF4917 2N4861 DE466	1 INL 3 DGE
MEF151 2N5457 2N5951	1 INL 3 IFC	MEF4005 2N5547 BFW11	1 DGE	MEF4918 2N4861 DE466	1 INL 3 DGE
MEF152 2N5457 2N5951	1 INL 3 IFC	MEF4006 2N5547 BFW11	1 DGE	MEF4919 2N4861 DE466	1 INL 3 DGE
MEF153 2N5457 2N5951	1 INL 3 IFC	MEF4007 2N5547 BFW11	1 DGE	MEF4920 2N4861 DE466	1 INL 3 DGE
MEF154 2N5457 2N5951	1 INL 3 IFC	MEF4008 2N5547 BFW11	1 DGE	MEF4921 2N4861 DE466	1 INL 3 DGE
MEF155 2N5457 2N5951	1 INL 3 IFC	MEF4009 2N5547 BFW11	1 DGE	MEF4922 2N4861 DE466	1 INL 3 DGE
MEF156 2N5457 2N5951	1 INL 3 IFC	MEF4010 2N5547 BFW11	1 DGE	MEF4923 2N4861 DE466	1 INL 3 DGE
MEF157 2N5457 2N5951	1 INL 3 IFC	MEF4011 2N5547 BFW11	1 DGE	MEF4924 2N4861 DE466	1 INL 3 DGE
MEF158 2N5457 2N5951	1 INL 3 IFC	MEF4012 2N5547 BFW11	1 DGE	MEF4925 2N4861 DE466	1 INL 3 DGE
MEF159 2N5457 2N5951	1 INL 3 IFC	MEF4013 2N5547 BFW11	1 DGE	MEF4926 2N4861 DE466	1 INL 3 DGE
MEF160 2N5457 2N5951	1 INL 3 IFC	MEF4014 2N5547 BFW11	1 DGE	MEF4927 2N4861 DE466	1 INL 3 DGE
MEF161 2N5457 2N5951	1 INL 3 IFC	MEF4015 2N5547 BFW11	1 DGE	MEF4928 2N4861 DE466	1 INL 3 DGE
MEF162 2N5457 2N5951	1 INL 3 IFC	MEF4016 2N5547 BFW11	1 DGE	MEF4929 2N4861 DE466	1 INL 3 DGE
MEF163 2N5457 2N5951	1 INL 3 IFC				