

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
2N3087 (Cont'd)	2N3108	2N3118 (Cont'd)	2N3138 (Cont'd)	2N3183 (Cont'd)	2N3196 (Cont'd)
THJ4339 3 SPR	2N2102 1 RCA	DE128 1 DGE	ST44C7 3 STI	BDV92 3 PHIN	SDT3762 3 SOD
THJ4340 3 SPR	2N3020 1 MOTA	BUY68 3 SGSI	2N3140	BDW52A 3 SGSI	SDT3763 3 SOD
THJ4341 3 SPR	D40D7 1 GESY	D40D4 3 GESY	2N5477 1 GSE	D44H7 3 GESY	SDT3766 3 SOD
TMF3459 3 SPR	DE128 1 DGE	GES2219 3 GESY	D44C7 1 GESY	DE219 3 DGE	SDT3825 3 SOD
TMF3821 3 SPR	THC3108 1 SPR	THC2219 3 SPR	2N5347 3 MOTA	SDT3750 3 SOD	SDT3827 3 SOD
TMF4339 3 SPR	2N1893 3 RCA	TN2219 3 NSC	2N6292 3 RCA	SDT3751 3 SOD	2N3197
TMF4340 3 SPR	2N2297 3 PHIN	TP2219 3 SPR	BD239A 3 RCA	SDT3752 3 SOD	2N3790 1 MOTA
TMF4341 3 SPR	2N4239 3 GSE	2N3119	BU407 3 APX	SDT3753 3 SOD	2N6247 1 RCA
TP3459 3 SPR	2N4305 3 TRWS	D40E7 1 GESY	ST44C7 3 STI	SDT3756 3 SOD	2N3792 3 RCA
TP3821 3 SPR	BCX56-6 3 SIEG	DE128 1 DGE	2N3142	SDT3757 3 SOD	2N5880 3 MOTA
TP4339 3 SPR	BCX56-10 3 SIEG	2N3120	2N5477 1 GSE	SDT3758 3 SOD	BDV94 3 PHIN
TP4340 3 SPR	BFY55 3 PHIN	2N3764 1 MOTA	D44C7 1 GESY	SDT3761 3 SOD	BDW52B 3 SGSI
TP4341 3 SPR	D38H4 3 GESY	D41D4 1 GESY	2N5347 3 MOTA	SDT3762 3 SOD	D44H10 3 GESY
2N3088	D40D10 3 GESY	DE128 1 DGE	2N6292 3 RCA	SDT3763 3 SOD	DE219 3 DGE
2N3460 1 IFC	THC2102 3 SPR	THC3120 1 SPR	BD239A 3 RCA	SDT3766 3 SOD	SDT3754 3 SOD
2N4339 1 INL	THC3020 3 SPR	D41D4C 3 SPR	BU407 3 APX	SDT3825 3 SOD	SDT3759 3 SOD
MOTA	TN3020 3 NSC	D43C6 3 GESY	ST44C7 3 STI	SDT3827 3 SOD	SDT3764 3 SOD
SIX	2N3109	2N3121	2N3144	2N3184	SDT3826 3 SOD
2N4339-5 1 NSC	2N3499 1 MOTA	2N2906A 1 SGSI	2N5477 1 GSE	2N3789 1 MOTA	2N3198
SIX 1 DGE	D40D8 1 GESY	2N3468 1 MOTA	D44C7 1 GESY	2N6246 1 RCA	2N6226 1 MOTA
DE312 1 DGE	DE128 1 DGE	D41E5 1 GESY	2N5347 3 MOTA	2N3791 3 RCA	2N6248 1 RCA
2N4338 3 INL	THC3109 1 SPR	DE159 1 DGE	2N6292 3 RCA	2N5879 3 MOTA	BDW52C 3 SGSI
2N4340 3 SIX	2N697 3 RCA	THC3121 1 SPR	BD239A 3 RCA	BDV92 3 PHIN	BDX96 3 PHIN
BFW12 3 PHIN	BFY51 3 PHIN	2N4032 3 PHIN	BU407 3 APX	BDW52A 3 SGSI	DE180 3 DGE
BFW13 3 PHIN	GES3499 3 GESY	D41D7 3 GESY	ST44C7 3 STI	D44H7 3 GESY	DE285 3 DGE
THJ3460 3 SPR	THC3499 3 SPR	PN2906A 3 NSC	2N3147	DE219 3 DGE	MJ15016 3 MOTA
THJ4339 3 SPR	2N3110	THC2906A 3 SPR	DE127 1 DGE	SDT3750 3 SOD	SDT3755 3 SOD
TMF3460 3 SPR	2N3020 1 MOTA	TMP2906A 3 SPR	2N3149	SDT3751 3 SOD	SDT3760 3 SOD
TMF4339 3 SPR	2N3053 1 RCA	TP2906A 3 SPR	D60T255010 1 WESY	SDT3752 3 SOD	SDT3765 3 SOD
TP3460 3 SPR	BSX20 1 PHIN	TPQ2906A 3 SPR	2N3150	SDT3753 3 SOD	TIP544 3 TII
TP4339 3 SPR	D40D4 1 GESY	2N3122	D60T255010 1 WESY	SDT3756 3 SOD	2N3199
2N3088A	DE128 1 DGE	2N5321 1 RCA	2N3151	SDT3757 3 SOD	D45C5 1 GESY
2N3460 1 IFC	THC3110 1 SPR	D40D1 1 GESY	D60T255010 1 WESY	SDT3758 3 SOD	2N6109 3 RCA
2N3821 1 MOTA	2N1893 3 RCA	DE128 1 DGE	2N3171	SDT3761 3 SOD	BD240 3 RCA
2N4339 1 INL	2N4305 3 TRWS	D42C7 3 GESY	2N3789 1 MOTA	SDT3762 3 SOD	ST45C5 3 STI
SIX	BCX55-10 3 SIEG	2N3123	2N6254 1 RCA	SDT3763 3 SOD	2N3200
2N4339-5 1 NSC	BSS79C 3 SIEG	2N2219 1 PHIN	2N3791 3 RCA	SDT3766 3 SOD	D45C8 1 GESY
SIX	D38H4 3 GESY	DE128 3 DGE	2N5878 3 MOTA	SDT3825 3 SOD	2N6107 3 RCA
2N4338 3 INL	D40D4C 3 GESY	GES2219 3 GESY	BDV92 3 PHIN	SDT3827 3 SOD	BD240A 3 RCA
2N4340 3 SIX	GES3053 3 GESY	THC2219 3 SPR	D44H7 3 GESY	2N3185	ST45C8 3 STI
BFW12 3 PHIN	THC3020 3 SPR	TN2219 3 NSC	DE130 3 DGE	2N3790 1 MOTA	2N3202
BFW13 3 PHIN	THC3053 3 SPR	TP2219 3 SPR	DE219 3 DGE	2N6247 1 RCA	2N3719 1 MOTA
DE312 3 DGE	TN3020 3 NSC	2N3124	SDT7731 3 SOD	2N3792 3 RCA	2N5783 1 RCA
DE456 3 DGE	2N3113	DE179 1 DGE	SDT7732 3 SOD	2N5880 3 MOTA	DE323 1 DGE
THJ3460 3 SPR	2N2607 1 INL	2N3125	SDT7733 3 SOD	BDV94 3 PHIN	2N5323 3 RCA
THJ3821 3 SPR	2N3329 1 SIX	DE179 1 DGE	SDT9202 3 SOD	BDW52B 3 SGSI	BSS44 3 SGSI
THJ4339 3 SPR	2N2608 3 SIX	2N3127	SDT9207 3 SOD	D44H10 3 GESY	D42C7 3 GESY
TMF3460 3 SPR	2N3330 3 MOTA	DE160 1 DGE	SDT9704 3 SOD	DE219 3 DGE	D43C6 3 GESY
TMF3821 3 SPR	2N5020 3 NSC	2N3131	SDT9801 3 SOD	SDT3754 3 SOD	DE129 3 DGE
TMF4339 3 SPR	2N5267 3 INL	BSX19 1 PHIN	SDT9802 3 SOD	SDT3759 3 SOD	SDT3852 3 SOD
TP3460 3 SPR	THJ3329 3 SPR	2N3132	SDT9803 3 SOD	SDT3764 3 SOD	THC3719 3 SPR
TP3821 3 SPR	TMF3329 3 SPR	DE179 1 DGE	2N3172	SDT3826 3 SOD	2N3203
TP4339 3 SPR	TP3329 3 SPR	2N3133	2N3789 1 MOTA	2N3186	2N3720 1 MOTA
2N3089	2N3114	2N2905 1 PHIN	2N6246 1 RCA	2N6226 1 MOTA	2N5781 1 RCA
2N3460 1 IFC	2N3440 1 RCA	DE129 1 DGE	2N3791 3 RCA	2N6248 1 RCA	DE323 1 DGE
2N4339 1 INL	D44T1 1 GESY	MPS3703 1 NSC	2N5879 3 MOTA	BDW52C 3 SGSI	2N5322 3 RCA
MOTA	DE154 1 DGE	RCA1A05 1 RCA	BDV92 3 PHIN	BDX96 3 PHIN	BSS44 3 SGSI
NSC	THC3114 1 SPR	THC3133 1 SPR	BDW52A 3 SGSI	DE180 3 DGE	D43C8 3 GESY
SIX	2N2987 3 GSE	MPS3703C 3 SPR	D44H7 3 GESY	DE285 3 DGE	DE129 3 DGE
DE312 1 DGE	BD115 3 PHIN	THC2905 3 SPR	DE219 3 DGE	MJ15016 3 MOTA	SDT3550 3 SOD
2N4338 3 INL	BFN18 3 SIEG	TN2905 3 NSC	SDT3750 3 SOD	SDT3755 3 SOD	SDT3553 3 SOD
2N4340 3 SIX	BFN26 3 SIEG	TP2905 3 SPR	SDT3751 3 SOD	SDT3760 3 SOD	THC3720 3 SPR
BFW12 3 PHIN	D44T2 3 GESY	2N3134	SDT3752 3 SOD	SDT3765 3 SOD	2N3204
BFW13 3 PHIN	DE396 3 DGE	2N2905 1 MOTA	SDT3753 3 SOD	TIP544 3 TII	2N6303 1 MOTA
THJ3460 3 SPR	TN3440 3 NSC	PHIN	SDT3756 3 SOD	2N3195	DE323 3 DGE
THJ4339 3 SPR	2N3115	2N4037 1 RCA	SDT3757 3 SOD	2N3789 1 MOTA	THC6303 3 SPR
TMF3460 3 SPR	2N2221 1 MOTA	DE129 1 DGE	SDT3758 3 SOD	2N6246 1 RCA	2N3205
TMF4339 3 SPR	DE123A 1 DGE	PN3645 1 NSC	SDT3761 3 SOD	2N3791 3 RCA	D45C4 1 GESY
TP3460 3 SPR	MPS2221 1 GESY	THC3134 1 SPR	SDT3762 3 SOD	2N5879 3 MOTA	2N6109 3 RCA
TP4339 3 SPR	THC3115 1 SPR	BCX52-10 3 SIEG	SDT3763 3 SOD	BDV92 3 PHIN	BD240 3 RCA
2N3089A	BSS81B 3 SIEG	BD138 3 PHIN	SDT3766 3 SOD	BDW52A 3 SGSI	ST45C4 3 STI
2N3460 1 IFC	GES222A 3 GESY	D41D4 3 GESY	SDT3825 3 SOD	D44H7 3 GESY	2N3206
2N3821 1 MOTA	PN2221 3 NSC	THC2905 3 SPR	SDT3827 3 SOD	DE219 3 DGE	D45C7 1 GESY
2N4339 1 INL	THC2221 3 SPR	THC4037 3 SPR	2N3173	SDT3750 3 SOD	2N6107 3 RCA
NSC	TMP2221 3 SPR	TN2905 3 NSC	2N3790 1 MOTA	SDT3751 3 SOD	BD240A 3 RCA
SIX	TP2221 3 SPR	TN4037 3 NSC	2N6247 1 RCA	SDT3752 3 SOD	ST45C7 3 STI
2N4338 3 INL	2N3116	TP2905 3 SPR	2N3792 3 RCA	SDT3753 3 SOD	2N3208
2N4340 3 SIX	2N2222 1 MOTA	2N3135	2N5880 3 MOTA	SDT3756 3 SOD	2N5783 1 RCA
BFW12 3 PHIN	DE123A 1 DGE	MPS3703 1 NSC	BDV94 3 PHIN	SDT3757 3 SOD	DE323 1 DGE
BFW13 3 PHIN	MPS2222 1 GESY	THC3135 1 SPR	BDW52B 3 SGSI	SDT3758 3 SOD	BSS44 3 SGSI
DE312 3 DGE	THC3116 1 SPR	MPS3703C 3 SPR	D44H10 3 GESY	SDT3761 3 SOD	D42C7 3 GESY
DE456 3 DGE	BSS81C 3 SIEG	2N3136	DE219 3 DGE	SDT3762 3 SOD	SDT3552 3 SOD
THJ3460 3 SPR	GES2222 3 GESY	2N2907 1 MOTA	SDT3754 3 SOD	SDT3763 3 SOD	2N3209
THJ3821 3 SPR	PN2222 3 NSC	PN3645 1 NSC	SDT3759 3 SOD	SDT3766 3 SOD	2N869A 1 MOTA
THJ4339 3 SPR	THC2222 3 SPR	THC3136 1 SPR	SDT3764 3 SOD	SDT3825 3 SOD	DE106 1 DGE
TMF3460 3 SPR	TMP2222 3 SPR	BSS80C 3 SIEG	SDT3826 3 SOD	SDT3827 3 SOD	PN3640 3 NSC
TMF3821 3 SPR	TP2222 3 SPR	DE159 3 DGE	2N3174	2N3196	2N3210
TMF4339 3 SPR	2N3117	GES2907 3 GESY	2N6226 1 MOTA	2N3789 1 MOTA	2N708 1 MOTA
TP3460 3 SPR	2N930A 1 MOTA	PN2907 3 NSC	2N6248 1 RCA	2N6246 1 RCA	2N3903 1 GESY
TP3821 3 SPR	2N5210 1 NSC	THC2907 3 SPR	BDW52C 3 SGSI	2N3791 3 RCA	BSX19 1 PHIN
TP4339 3 SPR	BFR17 1 SGSI	TMP2907 3 SPR	BDX96 3 PHIN	2N5879 3 MOTA	DE123A 1 DGE
2N3107	DE123A 1 DGE	TP2907 3 SPR	DE180 3 DGE	BDV92 3 PHIN	2N2222 3 SGSI
2N3019 1 MOTA	THC3117 1 SPR	2N3137	DE285 3 DGE	BDW52A 3 SGSI	BC548A 3 PHIN
D40D8 1 GESY	BC107 3 SGSI	BFW16A 1 PHIN	MJ15016 3 MOTA	D44H7 3 GESY	DE123AP 3 DGE
DE128 1 DGE	BC547B 3 PHIN	DE311 1 DGE	SDT3755 3 SOD	DE219 3 DGE	PN3646 3 NSC
THC3107 1 SPR	DE123AP 3 DGE	MRF517 3 MOTA	SDT3760 3 SOD	SDT3750 3 SOD	THC3903 3 SPR
2N4305 3 TRWS	PN100 3 NSC	2N3138	SDT3765 3 SOD	SDT3751 3 SOD	TMP23903 3 SPR
BCX56-16 3 SIEG	THC930A 3 SPR	2N5477 1 GSE	TIP544 3 TII	SDT3752 3 SOD	2N3211
BSV64 3 PHIN	THC5210 3 SPR	D44C7 1 GESY	2N3183	SDT3753 3 SOD	2N3013 1 MOTA
D38H5 3 GESY	2N3118	2N5347 3 MOTA	2N3789 1 MOTA	SDT3756 3 SOD	2N3903 1 GESY
THC3019 3 SPR	2N2219 1 PHIN	2N6292 3 RCA	2N6246 1 RCA	SDT3757 3 SOD	DE123A 1 DGE
TN3019 3 NSC	2N3553 1 MOTA	BD239A 3 RCA	2N3791 3 RCA	SDT3758 3 SOD	2N2222 3 SGSI
	D40D7 1 GESY	BU407 3 APX	2N5879 3 MOTA	SDT3761 3 SOD	BC548A 3 PHIN