

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	
<b>2N3010</b> (Cont'd) TMP74125 3 SPR	<b>2N3020</b> (Cont'd) THC3108 3 SPR THC3110 3 SPR	<b>2N3043</b> IT121 1 INL MP311 3 MPS	<b>2N3055</b> (Cont'd) 2N3715 3 MOTA 2N3716 3 MOTA	<b>2N3069</b> (Cont'd) 2N4416 3 INL BFW10 3 PHIN BFW11 3 PHIN DE312 3 DGE DE459 3 DGE THJ3458 3 SPR THJ3822 3 SPR THJ4341 3 SPR TMPF3458 3 SPR TMPF3822 3 SPR TMPF4341 3 SPR TP3458 3 SPR TP3822 3 SPR TP4341 3 SPR	<b>2N3080</b> (Cont'd) DE283 3 DGE PTC402 3 PTC <b>2N3081</b> DE129 1 DGE <b>2N3084</b> 2N3459 1 IFC 2N3821 1 MOTA 2N4339 1 INL 2N4340-5 1 NSC 2N4341 1 SIX 2N3458 3 IFC BFW11 3 PHIN BFW12 3 PHIN DE312 3 DGE DE456 3 DGE THJ3459 3 SPR THJ3821 3 SPR THJ4339 3 SPR THJ4341 3 SPR TMPF3459 3 SPR TMPF3821 3 SPR TMPF4339 3 SPR TMPF4341 3 SPR TP3459 3 SPR TP3821 3 SPR TP4339 3 SPR TP4341 3 SPR	
<b>2N3011</b> BSX28 1 SGSI DE123A 1 DGE FN2369 1 NSC BSX20 3 PHIN	<b>2N3021</b> 2N3789 1 MOTA D45C5 1 GESY 2N3791 3 RCA 2N6109 3 RCA BD240 3 RCA BDV92 3 PHIN D44H7 3 GESY DE219 3 DGE ST45C5 3 STI	<b>2N3044</b> IT122 1 INL MP310 3 MPS <b>2N3045</b> IT122 1 INL MP310 3 MPS <b>2N3046</b> IT121 1 INL MP311 3 MPS <b>2N3047</b> IT122 1 INL MP310 3 MPS <b>2N3048</b> IT122 1 INL MP310 3 MPS <b>2N3049</b> IT122 1 INL MP310 3 MPS <b>2N3050</b> IT122 1 INL MP310 3 MPS <b>2N3051</b> IT122 1 INL MP310 3 MPS <b>2N3052</b> IT122 1 INL MP310 3 MPS <b>2N3053</b> IT122 1 INL MP310 3 MPS	2N5760 3 MOTA 2N5877 3 MOTA 2N5882 3 MOTA 2N6262 3 RCA 2N6471 3 RCA 2N6569 3 MOTA BDV93 3 PHIN D44C8 3 GESY D44H4 3 GESY D44H8 3 GESY D44VH7 3 GESY DE280 3 DGE DE390 3 DGE MRF464 3 MOTA SDT9210 3 SOD <b>2N3055H</b> 2N3055A 1 MOTA <b>2N3055JAN</b> 2N5302JAN 1 MOTA <b>2N3055SD</b> 2N3055A 1 MOTA <b>2N3055UB</b> 2N3055A 1 MOTA <b>2N3056</b> DE128 1 DGE <b>2N3058</b> BC179 1 PHIN BC559 1 PHIN BC479 3 SGSI BC589A 3 PHIN BCF29 3 PHIN THBC179 3 SPR <b>2N3059</b> IT139 1 INL MP351 3 MPS <b>2N3066</b> 2N3459 1 IFC 2N4339 1 MOTA 2N4340 1 INL 2N4339 3 INL 2N4341 3 SIX BFW12 3 PHIN BFW13 3 PHIN DE459 3 DGE THJ3459 3 SPR THJ4339 3 SPR THJ4340 3 SPR TMPF3459 3 SPR TMPF4339 3 SPR TMPF4340 3 SPR TP3459 3 SPR TP4339 3 SPR TP4340 3 SPR <b>2N3067</b> 2N3460 1 IFC 2N4338 1 INL NSC SIX 2N4339 1 MOTA 2N4340 3 SIX BFW12 3 PHIN THC3072 3 SPR D43C8 3 GESY <b>2N3073</b> 2N2906A 1 SGSI DE159 1 DGE MPSA05 1 GESY THC3073 3 SPR BC846B 3 SIEG BCX41 3 SIEG MPSA05C 3 SPR PN2906A 3 NSC THC2906A 3 SPR TMPT2906A 3 SPR TMPTA05 3 SPR TP2906A 3 SPR TPQ2906A 3 SPR <b>2N3076</b> 2N6249 1 MOTA 2N6674 3 PTC BUX41 3 SGSI D64V53 3 GESY DE286 3 DGE SDT7605 3 SOD SDT7610 3 SOD SDT7611 3 SOD SDT7612 3 SOD SVT7563 3 TRWS <b>2N3079</b> 2N5838 1 MOTA BUX21 3 APX BUX82 3 PHIN SVT7523 3 TRWS <b>2N3080</b> 2N6542 1 MOTA BUS21A 3 APX BUX82 3 PHIN D64VE3 3 GESY	2N3789 1 MOTA D45C2 1 GESY 2N3791 3 RCA 2N6111 3 RCA BD240 3 RCA BDV92 3 PHIN D44H7 3 GESY DE219 3 DGE ST45C2 3 STI <b>2N3023</b> 2N3789 1 MOTA D45C6 1 GESY 2N3791 3 RCA 2N6109 3 RCA BD240 3 RCA BDV92 3 PHIN D44H7 3 GESY DE219 3 DGE ST45C6 3 STI <b>2N3024</b> 2N3791 1 MOTA 2N4904 1 RCA D45C8 1 GESY 2N6107 3 RCA 2N6226 3 MOTA BD240A 3 RCA BDV94 3 PHIN BDX92 3 PHIN D44H8 3 GESY D45H4 3 GESY DE219 3 DGE ST45C8 3 STI <b>2N3025</b> 2N3791 1 MOTA 2N4905 1 RCA D45C6 1 GESY 2N6109 3 RCA 2N6226 3 MOTA BD240 3 RCA BDV94 3 PHIN BDX92 3 PHIN D44H8 3 GESY D45H7 3 GESY DE219 3 DGE ST45C6 3 STI <b>2N3026</b> 2N3791 1 MOTA 2N4905 1 RCA D45C8 1 GESY 2N6107 3 RCA 2N6226 3 MOTA BD240A 3 RCA BDV94 3 PHIN BDX92 3 PHIN D44H8 3 GESY D45H7 3 GESY DE219 3 DGE ST45C8 3 STI <b>2N3035</b> BCY56 1 PHIN DE123A 1 DGE <b>2N3036</b> 2N1893 1 SGSI 2N3053 1 MOTA 2N5320 1 RCA BD139 1 PHIN DE128 1 DGE 2N4923 3 MOTA BCX55-10 3 SIEG BSS79C 3 SIEG D42T1 3 GESY GES3053 3 GESY MJE182 3 NSC SD339 3 MIKG THC3053 3 SPR <b>2N3037</b> BD139 1 PHIN 2N4923 3 MOTA MJE182 3 NSC SD339 3 MIKG <b>2N3038</b> BD139 1 PHIN 2N4923 3 MOTA MJE182 3 NSC SD339 3 MIKG <b>2N3039</b> DE129 1 DGE <b>2N3040</b> DE129 1 DGE	2N3055A 1 MOTA 2N3055JAN 1 MOTA 2N3055SD 1 MOTA 2N3055UB 1 MOTA 2N3056 1 DGE 2N3058 1 PHIN BC559 1 PHIN BC479 3 SGSI BC589A 3 PHIN BCF29 3 PHIN THBC179 3 SPR IT139 1 INL MP351 3 MPS 2N3459 1 IFC 2N4339 1 MOTA 2N4340 1 INL NSC SIX 2N4339 3 INL 2N4341 3 SIX BFW12 3 PHIN BFW13 3 PHIN DE459 3 DGE THJ3459 3 SPR THJ4339 3 SPR THJ4340 3 SPR TMPF3459 3 SPR TMPF4339 3 SPR TMPF4340 3 SPR TP3459 3 SPR TP4339 3 SPR TP4340 3 SPR 2N3460 1 IFC 2N4338 1 INL NSC SIX 2N4339 1 MOTA 2N4340 3 SIX BFW12 3 PHIN THC3072 3 SPR D43C8 3 GESY 2N2906A 1 SGSI DE159 1 DGE MPSA05 1 GESY THC3073 3 SPR BC846B 3 SIEG BCX41 3 SIEG MPSA05C 3 SPR PN2906A 3 NSC THC2906A 3 SPR TMPT2906A 3 SPR TMPTA05 3 SPR TP2906A 3 SPR TPQ2906A 3 SPR 2N6249 1 MOTA 2N6674 3 PTC BUX41 3 SGSI D64V53 3 GESY DE286 3 DGE SDT7605 3 SOD SDT7610 3 SOD SDT7611 3 SOD SDT7612 3 SOD SVT7563 3 TRWS 2N5838 1 MOTA BUX21 3 APX BUX82 3 PHIN SVT7523 3 TRWS 2N6542 1 MOTA BUS21A 3 APX BUX82 3 PHIN D64VE3 3 GESY	2N3459 1 IFC 2N3821 1 MOTA 2N4339 1 INL 2N4340 1 NSC 2N4341 1 SIX DE312 1 DGE 2N3458 3 IFC BFW11 3 PHIN BFW12 3 PHIN BFW13 3 PHIN DE456 3 DGE DE459 3 DGE THJ3459 3 SPR THJ3821 3 SPR THJ4339 3 SPR THJ4340 3 SPR THJ4341 3 SPR TMPF3459 3 SPR TMPF3821 3 SPR TMPF4339 3 SPR TMPF4340 3 SPR TMPF4341 3 SPR TP3459 3 SPR TP3821 3 SPR TP4339 3 SPR TP4340 3 SPR TP4341 3 SPR 2N3459 1 IFC 2N3821 1 MOTA 2N4339 1 INL 2N4340 1 NSC SIX 2N4341 1 SIX DE312 1 DGE 2N3458 3 IFC BFW11 3 PHIN BFW12 3 PHIN BFW13 3 PHIN DE456 3 DGE DE459 3 DGE THJ3459 3 SPR THJ3821 3 SPR THJ4339 3 SPR THJ4340 3 SPR THJ4341 3 SPR TMPF3459 3 SPR TMPF3821 3 SPR TMPF4339 3 SPR TMPF4340 3 SPR TMPF4341 3 SPR TP3459 3 SPR TP3821 3 SPR TP4339 3 SPR TP4340 3 SPR TP4341 3 SPR 2N3459 1 IFC 2N3821 1 MOTA 2N4339 1 INL 2N4340 1 NSC SIX 2N4341 1 SIX DE312 1 DGE 2N3458 3 IFC BFW11 3 PHIN BFW12 3 PHIN BFW13 3 PHIN DE456 3 DGE DE459 3 DGE THJ3459 3 SPR THJ3821 3 SPR THJ4339 3 SPR THJ4340 3 SPR THJ4341 3 SPR TMPF3459 3 SPR TMPF3821 3 SPR TMPF4339 3 SPR TMPF4340 3 SPR TMPF4341 3 SPR TP3459 3 SPR TP3821 3 SPR TP4339 3 SPR TP4340 3 SPR TP4341 3 SPR 2N3459 1 IFC 2N3821 1 MOTA 2N4339 1 INL 2N4340 1 NSC SIX 2N4341 1 SIX DE312 1 DGE 2N3458 3 IFC BFW11 3 PHIN BFW12 3 PHIN BFW13 3 PHIN DE456 3 DGE DE459 3 DGE THJ3459 3 SPR THJ3821 3 SPR THJ4339 3 SPR THJ4340 3 SPR THJ4341 3 SPR TMPF3459 3 SPR TMPF3821 3 SPR TMPF4339 3 SPR TMPF4340 3 SPR TMPF4341 3 SPR TP3459 3 SPR TP3821 3 SPR TP4339 3 SPR TP4340 3 SPR TP4341 3 SPR